

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX3263D

LAU KWOK YEW GABRIEL
BLK 121B RIVERVALE DRIVE
#15-432
SINGAPORE 542121
TEL : FAX :
PH : 96662265
ATTN :

ESTIMATE BILL

Number : EB00004960
Date : 06/10/2018
Case No : AD00010008
Vehicle No : SKN6005T
Chassis : KMHSU81BSEU28209
Year of Mfr : 2014
Policy No : 5092221527-01
Model : HYUNDAI DM
SANTA FE 2.4L GDI

Term:

Sn	DESCRIPTION	QTY	U PRICE	ABS D/AB SR 4WD DISC SDR	AMOUNT
1	TAIL GATE - REPAIR	1.0			
2	REAR BUMPER TOP - REPAIR	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					0.00
3	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	500.00	0 200	500.00
4	SPRAY PAINT ON THE AFFECTED AREAS	1.0	600.00	0 300	600.00
5	ANTI-RUST COATING	1.0	80.00	0 40 X	80.00
Labour 1 Sub Total					1,180.00
SINGAPORE DOLLARS : ONE THOUSAND TWO HUNDRED SIXTY-TWO AND CENTS SIXTY ONLY					
Less Excess					0.00
SUBTOTAL					1,180.00
GST 7.00%					82.60
TOTAL					1,262.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date of accident : 06/10/2018 09:16 AM. Place : JUNCTION OF YCK AND AMK AVE 6 AND LENTOR AVE

08/09/2018 10:15 AM

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE