

REPAIR ESTIMATE*Anura
ju

VEHICLE NO : SH 9811A

DATE 5/10/2018 16:07

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper Rubber Mat X			\$ 50.00	Nett
	Rear Bumper Advertisement Logo /			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) /		\$ 100.00	\$ 200.00	Nett
				\$ 300.00	
	Labour Charge				
	Panel Beating-Repair Rear Bumper			\$ 220.00 100	
	Spray Painting Charge			\$ 220.00 200	
	TOTAL LABOUR			\$ 440.00	
	ESTIMATE TOTAL			\$ 740.00	
<p> <i>Ka /uh 1/1/14</i> <i>8/10/18 1010 hrs</i> <i>2 hrs.</i> <i>U/s</i> <i>After Repair, hls</i> </p> <div data-bbox="873 1243 1334 1646" data-label="Text"> <p>LKK Auto Consultants hereby notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged parts during resurvey • Parts prices are subject to change • Third party survey is on a "no fault" basis • No illegal modification is allowed • Supplementary works must be reviewed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					