

ASS. REC. BY:

REF:

CS/FCU8018202/K1rbn2

Special Instruction:

Surveyor

Kalvin.

ASSIGNMENT (Office)

05/10/2018

From (Person):

CWS May Chua

of

FCL

Date/Time:

05/10/2018 4:52pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 6254J

Insured:

SHD 3430G

at Workshop m/s:

Premier

Tel:

6544 6671

of

23 Chungi South Ave 2 #03-03

Policy No:

Claim No:

018007294m7SH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

03/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

05/10/2018 10:57am

Person Contacted:

Gary

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 6254J - NS/LNC 17003740/H1rbn2

DOA: 20/02/2018

SHD 3430G - X

12/10/18

Revert 1A thru email.

Surveyor: Kelvin

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SHC6254 J Yr Regn: 5 Nov 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1.6-85

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 52330 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KNAH M 414 MF554385

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / QHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 3/10/8

Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
16/10/8 Chuan PIP \$580 / 20yr
Red: 81955.90, 771

FCI

RECEIVED 17 OCT 2018

Date/Time, File Pass to?

: Prel. Report

1) typist

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

110

50

50

21

231

Report Format: TP

Lump Sum / I.B.I. (\$ 580.00)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007294MFSH

Date: 12 October 2018

Our Ref: CS/FCI18018202/K1rb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6254J

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/10/2018 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,535.90</u>
Revised Estimate Amount	: S\$ <u>580.00</u>
"Check" Items Amount	: S\$ <u> </u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the o/s front portion.



Yours faithfully

KALVIN
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-10-2018	Our Ref No. D18007294MFSH
Accident Date	03-10-2018	Claim Type. Third Party
Insured Vehicle	SHD3430G	Third Party Vehicle. SHC6254J
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GOH WEE DEK	
Contact No.	65446676/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	05 Nov 2014 / 08:47:09	Receipt No.:	AACCK001-AX239-141105-000001
Asset Type:	Vehicle	Transaction Amount:	\$63,855.00
Asset ID:	SHC6254J	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20141105084709801807		

Vehicle No.:	SHC6254J
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	05 Nov 2014
Original Registration Date:	05 Nov 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5543815
Engine No.:	D4FDDH307962
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2014
Open Market Value:	\$19,878.00
Minimum PARF Benefit:	\$7,426.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	05 Nov 2014 08:47:09
COE No.:	2014110501001222Z
COE Expiry Date:	04 Nov 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$51,337.00
Lifespan Expiry Date:	04 Nov 2022
Owner ID Type:	Company

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

4-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6254 J

1 pc	Front bumper emblem X ^{an}	\$	44.00
1 pc	Front bumper X ^{right}	\$	531.00
1 pc	Front bumper o/s side retainer X ^{an}	\$	16.00
1 pc	Front o/s fender X ^{right}	\$	384.00
1 pc	Front o/s fender inner shield X ^{sub}	\$	120.00
1 pc	Front o/s wheel cover X ^{an}	\$	116.00
		\$	1,211.00
	Less 10%	\$	121.10
		\$	1,089.90

S/NETT

1 set	Front o/s fender inner shield clips X ^{an}	\$	28.00
1 set	Front bumper clips X ^{an}	\$	48.00
1 pc	Front o/s fender sticker X ^{an}	\$	30.00
	Sundry nec	\$	50.00 ²⁰
	To check wheel alignment	\$	80.00 X ^{an}
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X ^{an}
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$	550.00 ²⁰⁰
	To putty and spray painting on front bumper, front o/s fender	\$	400.00 ³⁶⁰
	To apply rustproofing on the repaired and replaced panels.	\$	80.00 X ^{an}
		\$	2,535.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Calculated by
8/10/18 1220 L.
2 days
4/5
Alpha Repair photo



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18018202/K1rbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3430G	Veh. Inspected	SHC 6254J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007294MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	05/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414MF5543815	Colour	SILVER	
Odometer	523303	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	7 mm	
L/H Front Tyre	205/65 R16	ACHILLES	7 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/10/2018	Inspection Date	08/10/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6254J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER EMBLEM	NOT NECESSARY	44.00	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	531.00	-
1	FRONT BUMPER O/S SIDE RETAINER	SERVICEABLE	16.00	-
1	FRONT O/S FENDER	TO REPAIR SEE LABOUR	384.00	-
1	FRONT O/S FENDER INNER SHIELD	SERVICEABLE	120.00	-
1	FRONT O/S WHEEL COVER	SERVICEABLE	116.00	-
	LESS 10% DISCOUNT		-121.10	-
			1,089.90	-
SPECIAL NETT ITEMS				
1	SET FRONT O/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	FRONT O/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			156.00	20.00
LABOUR				
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME, ETC. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT O/S FENDER.		550.00	200.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT O/S FENDER.		400.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	80.00	-
			1,290.00	560.00
GRAND TOTAL			2,535.90	580.00



RECOMMENDED COST OF REPAIRS			580.00
-----------------------------	--	--	--------

Report Ref No. CS/FCI18018202/K1rbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.