



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 08.10.2018

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2607X TOYOTA AXIO HYBRID 1.5 (2016)

To Supply

1) 1pc	Rear bumper	\$	Ry 700.00
2) 1pc	Rear bumper clip	\$	x 20.00
3) 1pc	Left tail lamp	\$	ang 450.00

Sub total Parts	\$	1,170.00
Less: 25% discount	\$	(292.50)
	\$	877.50

L/charges

1)	To remove rear bumper & left tail lamp. Replace rear bumper & left tail lamp. Align & adjust rear bumper.	\$	200 300.00
2)	To putty, respray painting rear bumper. To polish.	\$	200 300.00

Sub total L/charges	\$	600.00
Estimated Grand Total	\$	1,477.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495744
'wp'
8/10/18 1630
02 days
Resurvey after repair
sur @ lkkauto.com