

23/03/2002

ASS. REC. BY:

REF: 09/EGL18018204/K13602 Special Instruction:

Survivor:

Kalin

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGL

Date/Time: 08102018 11.05am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY/CS

To Inspect Vehicle No:

SHC 6883T

Insured:

YK1599D

at Workshop m/s

Premier Automotiv

Tel:

of

23 Chungi South Ave 2 #01-02

Policy No:

Claim No:

YK1599D/SA/pl

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04-102018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

08102018 11:06am

Person Contacted:

Gang

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 6883T - C14 / AXA15020330 / H11V352

DOA: 23/12/05

YK1599D - X

9/10/18

Email preli revised to Pei Li



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: YK1599D/SA/pl

Our ref: CS/EGII8018204/K1sb

Date : 9/10/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SHC 6883T


We thank you for your instruction on 8/10/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 8/10/2018 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,548.70
Revised Estimate Amount	: S\$1,268.90
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

KALVIN ANG

Automotive Assessor / Investigator

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 9 October 2018 1:49 PM
To: SUR; 'Survey Report (ERGO Insurance Pte. Ltd.)'
Subject: RE: YK1599D / TP : SHC6883T/LKK / DOA : 04/10/2018
Attachments: SHC 6883T PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SHC 6883T
Date of survey: 8/10/2018
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 9 October 2018 12:51 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: FW: YK1599D / TP : SHC6883T/LKK / DOA : 04/10/2018

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Monday, 8 October 2018 11:05 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: SUR (sur@lkkauto.com) <sur@lkkauto.com>
Subject: OI : YK1599D / TP : SHC6883T/LKK / DOA : 04/10/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **PREMIER AUTOMOTIVE SERVICES PTE LTD.**

ADDRESS : 23 CHANGI SOUTH AVE 2
#01-02
SINGAPORE 486443

PERSON TO CONTACT : GOH WEE DEK @ 6544 6682 / 6214 8880 EXT 68

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimates and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 8 October, 2018 11:05 AM
To: 'admin-d@lkkauto.com'
Cc: SUR (sur@lkkauto.com)
Subject: OI : YK1599D / TP : SHC6883T/LKK / DOA : 04/10/2018
Attachments: SHC6883T - SAS n ESTIMATE.pdf; SHC6883T - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **PREMIER AUTOMOTIVE SERVICES PTE LTD.**

ADDRESS : 23 CHANGI SOUTH AVE 2
#01-02
SINGAPORE 486443

PERSON TO CONTACT : GOH WEE DEK @ 6544 6682 / 6214 8880 EXT 68

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimates and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
Tel: +65 6829 9199
Fax: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 08.10.2018
Our Reference: YK 1599D/SA/pl
Your Reference: SHC 6883T

Sent via Fax

or

Email

weedek.goh@premiertaxi.com /
gary.shi@premiertaxi.com /
vincent.chua@premiertaxi.com

To: **PREMIER AUTOMOTIVE SERVICES PTE LTD**

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SHC 6883T
Insured's Vehicle: YK 1599D
Date Of Accident: 04.10.2018


We acknowledge receipt of your request for PRS on: 05.10.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* **LKK**

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input checked="" type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: OFFICER-IN-CHARGE - SIT1

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	13 Aug 2015 / 08:00:16	Receipt No.:	AACCK001-AX239-150813-000005
Asset Type:	Vehicle	Transaction Amount:	\$72,145.00
Asset ID:	SHC6883T	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150813080016357432		
Vehicle No.:	SHC6883T		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	13 Aug 2015		
Original Registration Date:	13 Aug 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5603253		
Engine No.:	D4FDEH313524		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2015		
Open Market Value:	\$21,263.00		
Minimum PARF Benefit:	\$13,061.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	13 Aug 2015 08:00:16		
COE No.:	2015081301002981C		
COE Expiry Date:	12 Aug 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$50,236.00		
Lifespan Expiry Date:	12 Aug 2023		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

5-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6883 T

1 pc	Rear o/s fender <i>X 1400</i>	\$ 1,208.00
1 pc	Rear o/s fender inner shield <i>X 50</i>	\$ 120.00
1 pc	Rear o/s wheel cover <i>X 50</i>	\$ 116.00
1 pc	o/s tail lamp <i>hatch</i>	\$ 421.00
1 pc	Rear bumper <i>X 1400</i>	\$ 696.00
1 pc	Rear bumper o/s reflector <i>X 50</i>	\$ 46.00
1 pc	Rear bumper o/s side retainer <i>X 50</i>	\$ 29.00
1 pc	Rear windscreen moulding <i>X 40</i>	\$ 87.00
		<hr/>
		\$ 2,723.00
	Less 10%	\$ 272.30
		<hr/>
		\$ 2,450.70

S/NETT

1 pc	Rear o/s fender sticker <i>— 20</i>	\$ 60.00
1 set	Rear o/s fender inner shield clips <i>X 20</i>	\$ 28.00
1 set	Sealant <i>X 20</i>	\$ 50.00
	Sundry <i>new</i>	\$ 50.00 <i>20</i>
	To check rear o/s wheel alignment	\$ 80.00 <i>X 20</i>
	To dismantle / refit old rear windscreen glass onto new moulding	\$ 120.00 <i>X 10</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 <i>50</i>
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld cut-off the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the same	\$ 950.00 <i>400</i>
	To putty and spray painting on rear bumper, rear o/s fender	\$ 500.00 <i>360</i>
	To apply rustproofing on the repaired and replaced panels.	\$ 80.00 <i>X 20</i>
		<hr/>
		\$ 4,548.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to market rate
- Third party survey is on a "no win, no fee" basis
- No illegal modification is allowed
- Supplementary items (e.g. paint, primer, etc) must be provided and approved from insurance company

Acknowledged by Repairer

Kalvin LKK
8/10/18 1330 L.
3 P2
45
After Repair photo




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18018204/K1sbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 25-10-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YK 1599D	Veh. Inspected	SHC 6883T	
Policy No.		Coverage (\$)	0.00	
Claim No.	YK1599D/SA/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	08/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5603253	Colour	SILVER	
Odometer	433202	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/10/2018	Inspection Date	08/10/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6883T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR O/S FENDER	TO REPAIR SEE LABOUR	1,208.00	-
1	REAR O/S FENDER INNER SHIELD	SERVICEABLE	120.00	-
1	REAR O/S WHEEL COVER	SERVICEABLE	116.00	-
1	O/S TAIL LAMP	GRAZED	421.00	421.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	REAR BUMPER O/S REFLECTOR	SERVICEABLE	46.00	-
1	REAR BUMPER O/S SIDE RETAINER	SERVICEABLE	29.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	87.00	-
	LESS 10% DISCOUNT		-272.30	-42.10
			2,450.70	378.90
SPECIAL NETT ITEMS				
1	REAR O/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SET REAR O/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SET SEALANT (SN)	NOT NECESSARY	50.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			188.00	80.00
LABOUR				
	TO CHECK REAR O/S WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE/REFIT OLD REAR WINDSCREEN GLASS ONTO NEW MOULDING.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD CUT-OFF THE REAR O/S FENDER INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME. INCLUSIVE OF THE REPAIR OF REAR O/S FENDER AND REAR BUMPER.		950.00	400.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, REAR O/S FENDER.		500.00	360.00

Report Ref No. CS/EGI18018204/K1sbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	80.00	-
			1,910.00	810.00
GRAND TOTAL			4,548.70	1,268.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CS/EGI18018204/K1sbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.