23/03/2002 ASS. REC. BY:	REF: (93 / AV) 18	018206 / Act	EZ Special	Instruction	*	
Surveyor Adrun	ASSIGNME					
From (Person): Chin Let Yin	u of	ALLI	Dat	te/Time:	8102018	1053cm
Estimated Cost:		Bill to:				
To Inspect Vehicle No:		S	Insured:	3	LM 87.72L	
at Workshop m/s			Tel:	9230 :	2438.	
of		# 01-21				
Policy No: 099999 4800).	Claim No:	241831	בבחבו	186	
Carron Income 1						
Make of Veh: (Client's Record)			D.C).A	01-10201	8
CA / REV / REP. / REV 24 Date/Time: 08-10/2018 -10	HRS ישףי Hum_Person Contacted:	Banjumin	ا Vehi	l.O.D. Endo	orsement:	
3KD 3015A						
SIM 3721L.						
Dismantle:	910/2018					
		14				

200

TOTAL

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC... Page 1 of 1

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM8722L AND SKD5075A ON 01/10/2018

From:

Chin, Lee-Ying

To:

assignments@lkkauto.com, admin-a@lkkauto.com

Cc:

Fong, Andy-SY

Sent:

Monday, 8 October, 2018 10:53:46 AM

Attachments:

05102018114348.pdf

HI LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Singapore 079120 Tel +(65) 6419 1947 | Fax +(65) 6835 7416 Lee-Ying.Chin@aig.com |www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



COMMISSIONER FOR OATHS

ACRA NUMBER 200911678H

GST REGISTRATION NUMBER | 200911678H

05/10/2018

Our Ref: SKD 5075A (V) MAX FACTOR

Your Ref: SLM 8722L

TO: AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way Tower 2 #07-16 Singapore 079120

Attn: Motor Claims Department

RIAZ QAYYUM ILLE HONSI NUS

DIRECTOR

ABDUL HALIM BIN ROSALAN ILLE HONELUTAS

ASSOCIATE:

MUHD RIDHWAN ABDUL RAHIM ILLB HONSI LEEDS

ASSOCIATE

BY FAX: 6415-3727

NOTICE OF ACCIDENT

Dear Sir

We are instructed by our client to *notify* you of a road traffic accident on <u>01 October 2018</u> at about <u>2220</u> hours along <u>PIE</u> involving our client's vehicle registration number <u>SKD 5075A</u> and vehicle registration number <u>SLM 8722L</u> driven by you or your authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop :

MAX FACTOR GARAGE PTE LTD

Address

23 Kaki Bukit Road 4

#01-21 Synergy @ KB Singapore 417801

Telephone no.

9230 2438 Benjamin

Fax no.: 6384 4749

Please let us hear from you by the stipulated time.

Yours faithfully

encs

cc. Client

FOR SURVEYOR

Please initial here after completion of prerepair inspection. Thank you.

Appointed surveyor (Name & signature)

Date & time of inspection



Stamford Tyres International Pte Ltd

23 Kaki Bukit Road 4 #01-12/13 Synergy@KB Singapore 417801

Phone Number:

6702 3355

Fax Number:

6341 6993

Customer:

10/9/2018 11:45 AM

Company:

VIN

License NO:

SKD5075A

VIII

Date:

e NO: SKD5

Technician:

Odometer:

Order NO:

VEHICLE ALIGNMENT REPORT

VOLKSWAGEN, SCIROCCO (G03,7,8), 08-11 (Customized)

Primary	Angles		Initial	Specific	Final	
-				Min.	Max.	
	Caster	Left		7°17'	8°17'	
		Right		7°17'	8°17'	
	Camber	Left	-1°18'	-1°11'	-0°11'	-1°18′
ront	1533-550-55-5	Right	-1°12'	-1°11'	-0°11'	-1°12'
	Toe	Left	0°12'	0°00'	0°10'	0°12'
		Right	-0°15'	0°00'	0°10'	-0°15'
		Total	-0°03'	0°00'	0°20'	-0°03'
	Camber	Left	-1°30'	-1°50′	-0°50'	-1°30'
	10 - C.	Right	-1°54'	-1°50'	-0°50'	-1°54'
	Toe	Left	0°12'	0°00'	0°10'	0°12'
Rear	100	Right	0°36'	0°00'	0°10'	0°36'
		Total	0°48'	0°00'	0°20'	0°48'
	Max Thrust Angle		0°12'		20'	0°12'
			Initial	Specific	cations	Final
Secondary Angles			milia	Min.	Max.	
SAI		Left				
		Right				****
Included Angle		Left				
		Right				****
Toe Out On Turns		Left		1°20'	2°01'	
Toe Out Of	ii Tullis	Right		1°20'	2°01'	
Max Turn I	nside	Left			STATE	****
max rami		Right			****	****
Toe Curve	Change	Left				****
ioc ouive	Onlingo	Right				****
Setback		Front	4mm			4mm
Jeiback		Rear	-31mm		****	-31mm
Track Width Diff.			-14mm			-14mm
Wheel Base Diff.			35mm			35mm
Front Ride	Height	Left		379mm	399mm	
T TOTAL TRIGO	, rioigin	Right		379mm	399mm	
Rear Ride	Height	Left		379mm	399mm	
	M	Right		379mm	399mm	
Frame Ang		0.00		1		

www.stamfordtyres.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC	
Owner ID: /ehicle Details	5654F	
Vehicle No.:	SKD5075A	
Vehicle to be Exported:	No	
Intended Deregistration Date:	09 Oct 2018	
Vehicle Make:	VOLKSWAGEN	
Vehicle Model:	SCIROCCO 1.4 TSI A	
Primary Colour:	Black	
Manufacturing Year:	2011	
Engine No.:	CAV323830	
Chassis No.:	WVWZZZ13ZCV003510	
Maximum Power Output:	118.0 kW (158 bhp)	
Open Market Value:	\$25,368.00	
Original Registration Date:	09 Dec 2011	
First Registration Date:	09 Dec 2011	
Transfer Count:	2	
Actual ARF Paid: Intended PARF Rebate Details	\$25,368.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	08 Dec 2021	
PARF Rebate Amount: Intended COE Rebate Details	\$16,489.00	
COE Expiry Date:	08 Dec 2021	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
QP Paid:	\$49,301.00	
COE Rebate Amount:	\$15,594.00	
Total Rebate Amount:	\$32,083.00	

The information contained herein is correct as at 09 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

	ACCIDENT STATEMENT
Date Of Report	02/10/2018 15:54
Date Of Accident	01/10/2018 22:20
Exact Location Of Accident	
Country/State of Loss	TWDS CHANGI NEAR PAYA LEBAR (ALONG FLYOVER) SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKD5075A
Insured/Policyholder	ON DOUTON
Name Of Registered Owner	TAY YANG QUAN
NRIC No	S8635654F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82826995
Alternative Phone No	OFFICE-82826995
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	SCIROCCO 1.4 TSI A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098026928
Cover Note Number	

Driver

 Name of Driver
 TAY YANG QUAN

 NRIC No
 \$8635654F

 Date Of Birth
 05/12/1986

 Occupation
 INDOOR

 Date Of Driving Pass
 11/02/2011

Driving Experience 7 YEARS AND 7 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-82826995

Fax Number

Contact Number OFFICE-82826995

EMail Address NOEMAIL

Address

BLK 441 FAJAR RD #12-458

Postcode

670441

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

OWNER

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: LEONG SIU FONG

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

BUKIT PANJANG NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 42 FAJAR ROAD , POSTCODE: 679005 , COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-8929999 - FAX NO: 67673650

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

TOO LARGE

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

SLM8722L

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

LIM YONG JIAN

NRIC/Passport Number

S9505814J

Contact Number

83991141

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAY YANG QUAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SKD5075A

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
 the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information personal information personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

e Addis Dependant on the

Date & Time: 02/10

1:55 cm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:

Sketch Plan #2 Pg. 1

SKETCH PLAN		
	41.1	
	(-)	1
		Vehicle A=SKD 5075A B=SLM 8722L
		B:SLM8+224
		Y
	LA LA	
DESCRIBE CIRCUMSTANCES	DE THE ACCIDENT	
	to the second of	
REICH 10 F	OLICE REPORT.	
-		
-		
21111		
ECLARATION		<u></u>
We declare the foregoing particula	ars are true in every respect.	$\langle \lambda \rangle$
De		472
ligyholder's Signature	Driver's Signature	
itela Time: 02/10/2018	(If driver is not the policyholder)	Reporting Centre Personnel's Signature Name:

POLICE REPORT Pg. 1





Police Station Of Origin: Bukit Panjang N.P.C 1 Segar Road #01-05 SINGAPORE 677738 Tel No: 1800-8929999

1 of 3 Report No. T/20181002/2007

REPORT	OF A TRAFFI	C ACCIDENT			
	ne Report M 018 02:32	/lade:	Vide Report No.:	Station Diary No.: 17	
Informa	nt's Partic	ulars			
	f Informant: NG QUAN		Address: APT BLK 441 FAJAR ROAD	#12-458 SINGAPORE 670441	
ID Type / ID No.: NRIC NO / S8635654F			Contact No.: Home/Office: Mobile: 82826995		
National SINGAP	lity: PORE CITIZ	EN	Email:		
Sex: Male	Age: 31	Date of Birth: 05/12/1986	Type of Informant: Driver		
Race: Chinese			Language:	Institution / School Name:	
Occupation: MANAGER			Driving Licence Information: Class: 3 Date of Expiry:		

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 01/10/2018 22:20	Type of Location Straight Road
	EXPRESSWAY gi near paya lebar (a	along flyover) Road Surface:		Road Speed Limit:
Clear	Traffic Flow: Traffic Con			
		Traffic Control: Not Controlled		Traffic Volume: Moderate

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKD5075A	Car	VOLKSWAGO N	SCIROCCO 1.4 TSI A	Black	Seriously Damaged	1
SLM8722L	Car				Totally Damaged	1

Details of Vo	ehicle Insurance			
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKD5075A	NTUC Income Insurance Co-Operative Limited	5098026928	13/02/2018	12/02/2019





Police Station Of Origin: Bukit Panjang N.P.C 2 of 3 Report No. T/20181002/2007

1 Segar Road #01-05 SINGAPORE 677738

Tel No: 1800-8929999

CONTINUATION OF REPORT

No. of Pedestrian	ns Injured: NIL		Use of Per	destriar	Cross	sina: NA
Driver						
Name	TAY YANG QUAN			ID No		S8635654F
Related Vehicle	SKD5075A (Car)			Conta	ct No.	82826995
Hospital/Clinic	TAN TOCK SENG HOSPITAL			Class of Driving Licence & Expiry Date		Class: 3 Date of Expiry: NIL
Date Treatment	01/10/2018	150.4	Date Disc			/2018
No. of Days gran	ted Medical Leave	05	Degree of			
Driver						
Name	Lim Yong Jian			ID No		S9505814J
Related Vehicle	NIL			Conta	ct No.	83991141
Hospital/Clinic	NIL			Class Driving Licent Expiry	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disch		NIL	
No. of Days grant	ted Medical Leave	NIL	Degree of	Injury	NIL	

Brief Details.

On the 1st of October 2018, while driving my vehicle SKD5075A along PIE towards Changi, near Paya Lebar on lane 3. A vehicle in front of me suddenly jam brake, I managed to came to a stop. However, a vehicle bearing SLM8722L did not manage to stop on time thus causing a collision with my vehicle. I went to make a check and discovered the right rear side of my bumper was seriously damaged. I was issued with 5 day medical certificate from Tan Tock Seng Hospital from 1/10/2018 - 05/10/2018. I suffered from a neck strained injury due to the accident.

I wish to state that there is an in built front camera install in my vehicle.

POLICE REPORT Pg. 1





Police Station Of Origin: Bukit Panjang N.P.C

3 of 3 Report No. T/20181002/2007

1 Segar Road #01-05 SINGAPORE 677738 Tel No: 1800-8929999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:	Signature Of Informant:
Sgt 2 CHERYL YEO	
Signature Of Interpreter:	Date/fime:
Not applicable	02/10/2018 02:32
Officer In Charge Of Case:	Classification Of Case:
	117
Contact No.: 65476219	T. T
Authentication Stamp	

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.























MOTORCAR (Rear)

(1)Replace (√) (2)Repair() (3)Check €) (4)Not Consistent NC)

Rear F		(14)Onecationed (15)Not Working	
	*INC		CON ACON
1137	993626	Rear Number Plate	COT
1138	993627	Rear Number Plate Base	

	~ INC	Item	CON	AC	Q
1137		Rear Number Plate	CUT	./	
1138		Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish	aut	V	
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	BR	V	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	BR	/	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement	B7	1/	
1150	992970	Rear Bumper Beam	1		
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			_
1153	993040	Rear Bumper Protector			_
1154	993036	Rear Bumper Pad			_
1155	993026	Rear Bumper Moulding		-	_
1156	993044	Rear Bumper Reflector	+-+	-	_
	993023	Rear Bumper Lower Spoiler	+	-	-
1158	994023	Reverse Sensor	1.1	1	_
	993327	Rear End Panel	125	·/	-
1160	993339	Rear End Panel Top Garnish	100	V	_
1161	993333	Rear End Panel Inner Trim	+	-	_
	990333	Boot Compartment Inner Trim	-	-	_
1163	993851	Rear LH Taillamp	+-+	\dashv	_
	993853	Rear LH Taillamp Garnish	+	-	_
1165	993859	Rear LH Taillamp Panel	+	\dashv	_
	995116	Rear RH Taillamp	00	-	_
1167	993853	Rear RH Taillamp Garnish	BR	V	_
	993859	Rear RH Taillamp Panel	1-1	-	_
1169	993554	Rear Apron Panel	+	-	_
1170	992895	Roatlid	+	\dashv	_
1171		Bootlid Emblem	+	\dashv	_
		Bootlid Handle	+	-	_
1173		Bootlid Moulding	+	-	_
	990376	Bootlid Reflector	+	\dashv	_
1175	995222	Bootlid Lamp LH	+	-	_
1176	002800	Bootlid Lamp RH	-	-	_
1177	005243	Bootlid Lock	-		_
		Bootlid Rubber		-	_
			-	_	_
1179	002977	Bootlid Hinge		7	_
		Bootlid Spoiler	1	,	_
	994543		1	1	
1182		Tailgate Emblem	NEC	1	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
		Tailgate Garnish	BT	V	
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
188	994646	Tailgate Protector			
189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
191	994679	Tailgate Wiper Nozzle		+	_
192	994555	Tailgate Wiper Motor			-
	994602	Tailgate Glass	1	+	-
	994606	Tailgate Glass Rubber	1	-	_
	994604	Tailgate Glass Moulding	10.00		_
196	994607	Tailgata Class Moulding	NEC	10	
	0046007	Tailgate Glass Sealant	NEC	V	
197		Tailgate Lock			
198	994651	Tailgate Rubber	1 cut	1	
199	994611	Tailgate Hinge	-		
200	004504	Tailgate Damper	1	-	
200	224224	rangate Damper			

		Vehicle No: SKD5	47.5		
NAC	INC	Venticie 140: OKDS	15	A.	
NAC		Item	CON	AC	Qty
1202	993784	Spare Tyre Board	_	-	
1203	994328	Spare Tyre Panel	-		
		Spare Tyre	-		
1205	994326	Spare Tyre Lock Screw	_		
		Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
		CD Changer Assy			
		Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
		Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
		Rear Exhaust Heat Shield			
		Rear LH Chassis Member			
		Rear RH Chassis Member			
		Rear LH Fender			
		Rear LH Fender Protector			
		Rear LH Fender Inner Panel			
		Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
		Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
		Rear LH Rim Cover			
		Rear LH Tyre			
1228	993456	Rear RH Fender	DD	V	
		Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel	DD	1	\neg
1231	993431	Rear RH Fender Inner Trim	1		\neg
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield	TN	V	
1234	993622	Rear RH Mudflap	MIS		
1235	993934	Rear RH Wheel Rim	122		
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239		Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241		Rear Fender 1/4 Glass			
		Rear Fender 1/4 Glass Rubber	NEC	1	
1243	993453	Rear Fender 1/4 Glass Sealant	NEC	1	
		Rear Windscreen Glass			
1245		Rear Windscreen Rubber			
1246		Rear Windscreen Moulding	NEC	V	
1247		Rear Windscreen Sealant	NEC	V	
1248		Third Brake Light			
1249		Rear Fender Air Grille	M15	V	
1250		Fuel Lid	=		
		Fuel Neck			
1252		Fuel Tank			
1253		Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
±1136	990247				
		Roar Exhaust my If lev	DD	V	
		set			
		Rear wiring harness!	U IT	1/	
		lights & reverse souson	-		
11		0			\neg
		Atra			
		· / Moren for			
			- 6		\dashv
		116/10/2	JAA	-	
		101.1	100		-

No of Items: 25

Assessor:

Totim lim 15/10/18



(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched (07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary #12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTOR CAR (UC)

ACTIONIACI (4)Not Consistent (NC)

(1)Replace (√) (2)Repair (X) (3)Check (?)

Vehicle No: SKD 5075A

NAC	INC	Item	CON	AC	Qt
1372		Frt LH Shock Absorber			
		Frt LH Shock Absorber Mounting			
		Frt LH Coil Spring			
		Frt LH Knuckle Arm			
		Frt LH Knuckle Arm Bearing			
and the second name of	-	Frt LH Lower Arm			
-		Frt LH Upper Arm			
		Frt LH Tie Rod			-
1380	The second second	Frt LH Drive Shaft	1		
1381		Frt LH Control Arm			
1382		Frt LH Trailing Arm	_		
Control of the last		Frt LH Leaf Spring	_		\vdash
1384		Frt LH Brake Disc Rotor	1		\vdash
		Frt LH Brake Caliper	+		
		Frt LH Brake Pipe	-	-	\vdash
		Frt LH Brake Hose	+-	\vdash	-
		Frt LH Brake Sensor Wire	+	-	-
		Frt Stay Bar Bracket	-	-	1
		Steering Rack & Pinion		-	+
		Steering Cross Member	-	-	-
		Frt Sub Frame	+-	-	+
		Frt Sub Frame Mounting	-	-	+
			+-	+	+
1394		Frt Anti Roll Bar	+-	+-	+
1395		Frt Anti Roll Bar Linkage	+	+	+
1396		Engine Block	+	+	+
1397		Engine block Gasket	-	+	+
		Engine Oil Sump	_	+	+
		Engine Oil	-	+	+
		Gear Box Assy	-	+	+
1401		Gear Box Gasket	-	+	+
		Gear Box Oil Sump	-	+	+
		Gear Oil		+	+-
		Centre Exhaust Pipe Assy	-	+	+
		Centre Exhaust Mounting		+	+
		Floor Panel	+-	+	-
		Rear LH Shock Absorber		+	+
		Rear LH Shock Absorber Mounting		+	+
		Rear LH Coil Spring		+	+
		Rear LH Knuckle Arm	7	7	+
		Rear LH Knuckle Arm Bearing	-	+	-
	-	Rear LH Lower Arm		+	-
		Rear LH Upper Arm		+	-
-	_	Rear LH Drive Shaft		_	_
1413		Rear LH Control Arm		-	1
	_	Rear LH Trailing Arm		1	1
1415		Rear LH Leaf Spring		1	
		Rear LH Brake Disc Rotor			
1417		Rear LH Brake Caliper Assy			
1418		Rear LH Brake Pipe			
		Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
		Rear Sub Frame Mounting			
		Rear Anti Roll Bar	37	V	/
		Rear Anti Roll Bar Linkage	NI		1
1424		Axle Beam		1	
1425		Rear Axle Panhard Rod			
1420		Differential Assy			
1.44	1 223000				

INC	NAME OF THE PARTY	COST		
	Item	CON	AC	Qty
	Frt RH.Shock Absorber			
	Frt RH Shock Absorber Mounting			
	Frt RH Coil Spring			
	Frt RH Knuckle Arm			
991851	Frt RH Lower Arm			
991692	Frt RH Drive Shaft			
990661	Frt RH Control Arm			
992062	Frt RH Trailing Arm			
			\vdash	
		CIT	1./	
				111
		121	1	+
		-	+	+
		DC	+	+
				-
		NE	1	-
		10 1	/	1
		-	+	+-
		-	+	+
			1	-
		DD	V	_
			-	1.,
		A DD	K	X
992938	Rear RH Brake Caliper Assy	-		
990434	Rear RH Brake Pipe			
992947	Rear RH Brake Hose			
			_	
			+	
			+	
	,			
	- Amarko			
	March			
	mark			
	mark			
	mar Jo			
	(Cho Seal)			
	(chopen)			
	(cho ben)			
	(cho ben)			
	(6) pers			
	16 pers			
	(6 poper)			
	(6 poper)			
	16 poper			
	(6) per			
	16 Johnson			
	1 (6 to best			
	991845 991851 992064 992060 991692 990661 992062 991848 991293 991281 991295 993720 993723 993750 993551 993601 993885 993322 993178 995110 992942 992938 990434	991845 Frt RH Knuckle Arm Bearing 991851 Frt RH Lower Arm 992064 Frt RH Upper Arm 992040 Frt RH Tie Rod 991692 Frt RH Drive Shaft 990661 Frt RH Control Arm 992062 Frt RH Trailing Arm 991848 Frt RH Leaf Spring 991293 Frt RH Brake Disc Rotor 991281 Frt RH Brake Caliper 991292 Frt RH Brake Hose 991295 Frt RH Brake Hose 991295 Frt RH Brake Sensor Wire 993720 Rear RH Shock Absorber 993721 Rear RH Coil Spring 993173 Rear RH Coil Spring 993550 Rear RH Knuckle Arm 993551 Rear RH Knuckle Arm 993551 Rear RH Lower Arm 993885 Rear RH Upper Arm 993885 Rear RH Drive Shaft 993178 Rear RH Control Arm 995117 Rear RH Trailing Arm 995110 Rear RH Leaf Spring 992942 Rear RH Brake Disc Rotor	991845 Frt RH Knuckle Arm Bearing 991851 Frt RH Lower Arm 992064 Frt RH Upper Arm 992040 Frt RH Tie Rod 991692 Frt RH Drive Shaft 990661 Frt RH Control Arm 992062 Frt RH Trailing Arm 991848 Frt RH Leaf Spring 991293 Frt RH Brake Disc Rotor 991281 Frt RH Brake Pipe 991295 Frt RH Brake Hose 991295 Frt RH Brake Hose 991296 Frt RH Brake Sensor Wire 993720 Rear RH Shock Absorber 993721 Rear RH Shock Absorber 993723 Rear RH Knuckle Arm 993173 Rear RH Knuckle Arm 993551 Rear RH Knuckle Arm Bearing 993601 Rear RH Lower Arm 993885 Rear RH Upper Arm 993178 Rear RH Control Arm 995117 Rear RH Trailing Arm 995117 Rear RH Trailing Arm 995110 Rear RH Brake Disc Rotor	991845 Frt RH Knuckle Arm Bearing 991851 Frt RH Lower Arm 992064 Frt RH Upper Arm 992040 Frt RH Tie Rod 991692 Frt RH Drive Shaft 990661 Frt RH Control Arm 992062 Frt RH Trailing Arm 991848 Frt RH Leaf Spring 991293 Frt RH Brake Disc Rotor 991291 Frt RH Brake Caliper 991292 Frt RH Brake Hose 991295 Frt RH Brake Hose 991296 Frt RH Brake Hose 991297 Frt RH Brake Sensor Wire 993720 Rear RH Shock Absorber 993721 Rear RH Coil Spring 993173 Rear RH Coil Spring 993551 Rear RH Knuckle Arm 993551 Rear RH Knuckle Arm 993601 Rear RH Lower Arm 993885 Rear RH Upper Arm 993178 Rear RH Control Arm 995117 Rear RH Trailing Arm 995110 Rear RH Leaf Spring 992942 Rear RH Brake Disc Rotor

No of Items:___ Assessor: Tarim hum 16/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

AIM SUBFU	LDER TRA	CKING							
Case N	otified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed	Status	
Main 0:	2 Oct 2018 Edit Reg		08 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	5\$0.00 View F			Pending for Report Cancel Ca	
Ма	ain	R	eference	Claim De	etails	\Box	Documents		Show All
CLAIM SUBI	FOLDER DE	TAILS			[[Created	by adjuster]		
insured:	LCRF PTE	LTD, Co. Reg. N	No.: 201624597K						
Main Claimant:	ē.								
Vehicle Reg. No.:	SKD507	5A		Date o			8 00:00 - :59 s and 22 Days Fro	m LTA Reg Dat	e (Man Yr)]
Claim Type:	TP / 241	8315022SG		Policy/ Note N		99999480	0 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLM8722	Ľ		Policy (Claim					
				Excess	:				
Repairer:	Max Fact	or Garage Pte Lt	d (HQ) 23 KAKI BT	ROAD 4 \$01-21 SY	NERGY @	KB, 4178	01 Kaki Bukit - Te	l:	
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Expre	ss) - Tel: 65-6419-	3000 [H	Handled b	y Olea, Maricel]	Maricel.Olea@a	ig.com
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Handle	ed by ADR	IAN LIN	G] [Final Rp	t due 18/10/	2018]
Claimant's Solicitor:	RIAZ LLC	- Tel: 65340110							
ASSOCIATE	D MAIL RE	CEIVED					Viev	v All Comp	ose Case Mail
AIG_SG (1	10/10/2018)	Request to upl	oad TP GIA Report	:					
ALL ASSOC	IATED TAS	ks⊟			Viev	w All S	Search Tasks Co	reate New Task	Complete
Due Date	Priority	Type Task	Group Subject	t Handler	Assigned	Ву	Completed On	Created (On Done

Claim Documents

*SKD5075A (2418315022SG) [SLM8722L] TP

Oct 1 2018 12:00AM [LCRF PTE LTD] Max Factor Garage Pte Ltd

Pho	otos/Images		3 per page	~
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/10/18 14:36	General View	Load JPG	✓
2	12/10/18 14:36	General View	1 Load JPG	~
3	12/10/18 14:36	General View	Load JPG	V
4	12/10/18 14:36	General View	Load JPG	V
5	12/10/18 14:36	General View	Load JPG	V
6	12/10/18 14:36	General View	Load JPG	V
7	12/10/18 14:36	General View	■ Load JPG	~
8	12/10/18 14:36	General View	1 Load JPG	V
9	12/10/18 14:36	General View	1 Load JPG	~
10	12/10/18 14:36	General View	Load JPG	V
11	12/10/18 14:36	General View	1 Load JPG	~
12	12/10/18 14:36	General View	Load JPG	~
13	12/10/18 14:36	General View	1 Load JPG	V
14	12/10/18 14:36	General View	1 Load JPG	~
15	12/10/18 14:36	General View	Load JPG	V
16	12/10/18 14:36	General View	Load JPG	V
17	12/10/18 14:36	General View	■ Load JPG	~
18	12/10/18 14:36	General View	Load JPG	V
19	12/10/18 14:36	General View	Load JPG	~
20	12/10/18 14:36	General View	Load JPG	V
21	12/10/18 14:36	General View	1 Load JPG	V
22	12/10/18 14:36	General View	Load JPG	~
23	12/10/18 14:36	General View	Load JPG	V
24	12/10/18 14:36	General View	■ Load JPG	~
25	12/10/18 14:36	General View	Load JPG	V
26	12/10/18 14:36	General View	1 Load JPG	~
27	12/10/18 14:36	General View	1 Load JPG	V
28	12/10/18 14:36	General View	1 Load JPG	V
29	12/10/18 14:36	General View	1 Load JPG	V
30	12/10/18 14:36	General View	1 Load JPG	V
31	12/10/18 14:36	General View	■ Load JPG	~
32	12/10/18 14:36	General View	1 Load JPG	V
33	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	V
34	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	V
35	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	V
36	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	~
37	12/10/18 14:37	Photographs of Damaged Parts	■ Load JPG	V

Pho	tos/Images			√ ∀
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna Lord IPG	
38	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	14
39	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	
10	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	_
1	12/10/18 14:37	Photographs of Damaged Parts	■ Load JPC	3 2
12	12/10/18 14:37	Photographs of Damaged Parts	⑥ Load JPC	5 2
13	12/10/18 14:37	Photographs of Damaged Parts	■ Load JPC	3 2
14	12/10/18 14:37	Photographs of Damaged Parts	■ Load JPC	3 •
15	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	3 2
6	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	3 L
17	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	3 👿
18	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	3 🖳
19	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	3 L
50	12/10/18 14:37	Photographs of Damaged Parts	Load JPG	3 5
51	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	
52	12/10/18 14:37	Photographs of Damaged Parts	Load JPC	3 V
53	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	-
54	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	
		Photographs of Damaged Parts	1 Load JPC	
55	12/10/18 14:37			-
56	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	
57	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	
8	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	
59	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	-
50	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	-
51	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	_
52	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	-
63	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	3 Y
54	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	3 🖳
55	12/10/18 14:37	Photographs of Damaged Parts	■ Load JPC	3
56	12/10/18 14:37	Photographs of Damaged Parts	■ Load JPC	3 5
57	12/10/18 14:37	Photographs of Damaged Parts	■ Load JPG	3 5
58	12/10/18 14:37	Photographs of Damaged Parts	■ Load JPC	3 5
59	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	G 🖳
70	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	3 5
71	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	3 5
72	12/10/18 14:37	Photographs of Damaged Parts	■ Load JPC	3 🗸
73	12/10/18 14:37	Photographs of Damaged Parts	Load JPC	3 👿
74	12/10/18 14:37	Photographs of Damaged Parts	Load JPC	3 5
75	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	-
76	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	
77	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	-
		Photographs of Damaged Parts	1 Load JPC	-
78	12/10/18 14:37		1 Load JPC	-
79	12/10/18 14:37	Photographs of Damaged Parts		
30	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	_
31	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	
32	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	
33	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	-
84	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	
85	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPC	
36	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	(2)
87	12/10/18 14:37	Photographs of Damaged Parts	1 Load JPG	G G

Merimen e-Claims Page 3 of 3

Pho	tos/Images		3 per i	oage 🔻	4
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	İ	Thumbnail	Print
88	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	∀
89	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	Y
90	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	V
91	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	✓
92	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	₹
93	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	~
94	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	V
95	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	V
96	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	V
97	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	V
98	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	✓
99	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	✓
100	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	V
101	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	√
102	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	V
103	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	✓
104	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	✓
105	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	~
106	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	✓
107	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	✓
108	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	✓
109	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	✓
110	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	✓
111	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	V
112	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	✓
113	12/10/18 14:37	Photographs of Damaged Parts	0	Load JPG	V
Doc	umentation		1 per i	page V	V
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	-
1	10/10/18 11:02	OI GIA REPORT	O	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG18018206/ACBE2

Date:

17/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994800

Claimant Vehicle SKD5075A No:

Insured Vehicle No:

SLM8722L

Date of Loss:

01/10/2018

Nature of Claim:

TP

Claim No: 2418315022SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKD5075A

Make & Model:

VOLKSWAGEN SCIROCCO, 1.4 (A)

Engine No:

CAV323830

Reg. Date: Colour:

Black

09/12/2011 (Man. Year: 2011)

Chassis No: Odometer:

WWZZZ13ZCV003510 122780 km

Engine Capacity:

1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Handbrake (Serviceable):

Engine Modification:

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

235/40 R18

Rear Tyre Size:

235/40 R18

Front Left Side: Front Right Side:

Bridgestone 6 mm Bridgestone 6 mm Rear Left Side: Rear Right Side:

Bridgestone 6 mm Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

08/10/2018

Date Inspected:

08/10/2018 Inspected At:

Max Factor Garage Pte Ltd (HQ)

23 KAKI BT ROAD 4 \$01-21 SYNERGY @

Singapore 417801

Estimated Period of Repair:

12.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	_	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR NUMBER PLATE	Cut	0.00 F	*- F
2	1	*REAR NUMBER PLATE GARNISH	Cut	0.00 F	*- F
3	1	*REAR BUMPER	Broken	0.00 F	*- F
4	1	*REAR BUMPER LOWER	Broken	0.00 F	*- F
5	1	*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1	*REVERSE SENSOR	Dislodged	0.00 F	*- F
7	1	*REAR END PANEL	Dented	0.00 F	*- F
В	1	*REAR RH TAILLAMP	Broken	0.00 F	*- F
9	1	*TAILGATE	Dented	0.00 F	*- F
10	1	*TAILGATE EMBLEM	Necessary	0.00 F	*- F
11	1	*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
12	1	*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
13	1	*TAILGATE RUBBER	Cut	0.00 F	*- F
14	1	*REAR RH FENDER	Dented	0.00 F	*- F
15	1	*REAR RH FENDER INNER PANEL	Dented	0.00 F	*- F
16	1	*REAR RH FENDER INNER SHIELD	Torn	0.00 F	*- F
17	1	*REAR RH MUDFLAP	Missing	0.00 F	*- F
18	1	*REAR FENDER 1/4 GLASS RUBBER	Necessary	0.00 F	*- F
19	1	*REAR FENDER 1/4 GLASS SEALANT	Necessary	0.00 F	*- F
20	1	*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
21	1	*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*-F
22	1	*REAR FENDER AIR GRILLE	Missing	0.00 F	*- F
23	1	*SET REAR EXHAUST MUFFLER	Dented	0.00 F	*-F
24	1	*REAR WIRING HARNESS / LIGHTS & REVERSE SENSOR	Cut	0.00 F	*-F
25	1	*TAILGATE GARNISH	Bent	0.00 F	*-F
26	1	*REAR ANTI ROLL BAR	Bent	0.00 F	*-F
27	1	*REAR ANTI ROLL BAR LINKAGE	Not Necessary	0.00 F	*-F
28	1	*FRT RH BRAKE SENSOR WIRE	Cut	0.00 F	*-F
29	1	*REAR RH SHOCK ABSORBER	Bent	0.00 F	*-F
80	1	*REAR RH KNUCKLE ARM	Distorted	0.00 F	*-F
31	1	*REAR RH KNUCKLE ARM BEARING	Necessary	0.00 F	*-F
32	1	*REAR RH LOWER ARM	Bent	0.00 F	*-F
3	1	*REAR RH TRAILING ARM	Dented	0.00 F	*-F
34	1	*REAR RH BRAKE DISC ROTOR BACK PLATE	Repair	0.00 F	*-F
=Fran	nchise p		Company (Control	3,331	ARM.
			Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >