

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

PC 3417G
TP/LONPAC

M/S : LONPAC INSURANCE BERHAD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
TEL: 62507388
ATTN: Motor Claim Department

Estimate No: ES1891158/WS
Date: 09 Oct 2018
Policy No: 5068938166-03
Veh Reg No: PC3417G
Make/Model: TOYOTA TOYOTA
HIACE COMMUTER GL
3.0

WS Ref: TP/LONPAC
Claim Type: Third Party
Accident Date: 08/10/2018
TP Veh Reg No: GX1480G

FAX: 62963767

Not Authorized

U/Pay @ ?

Reserve After Paint

Chassis No: KDH2230021240
Engine No: 1KD2439305
Reg. Date: 10/12/2014

Estimate Repair Cost to Vehicle No :PC3417G

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	422.90	1 PC	422.90	✓
2 REAR BUMPER CLIPS	3.50	6 PC	21.00	✓
3 TAILGATE	2,211.67	1 PC	2,211.67	✓
4 TAILGATE LOGO	72.20	1 PC	72.20	✓
5 TAILGATE EMBLEM "HIACE"	35.50	1 PC	35.50	✓
6 TAILGATE EMBLEM "GL"	52.70	1 PC	52.70	✓
7 TAILGATE INNER LOCK	257.80	1 PC	257.80	✓
8 TAILGATE INNER RUBBER	329.60	1 PC	329.60	?
9 REAR PANEL (OUTER)	579.50	1 PC	579.50	?
10 REAR PANEL (INNER)	976.80	1 PC	976.80	?
11 LH TAILLAMP	277.62	1 PC	277.62	✓
12 LH TAILLAMP LWR GARNISH	84.00	1 PC	84.00	✓
13 LH TAILLAMP PANEL	661.30	1 PC	661.30	?
			5,982.59	
		Less 25%	1,495.65	4,486.94
Special Net				
14 REAR WINDSCREEN GUM	40.00	1 PC	40.00	✓
15 70KM/H STICKER	10.00	1 PC	10.00	✓
16 ISET REVERSE SENSOR	200.00	1 PC	200.00	✓
			250.00	250.00
Labour				
17 REMOVE & REFIT REAR WINDSCREEN GLASS.	100.00	1 PC	100.00	✓
18 PANEL BEATING-REMOVE & REFIT REAR BUMPER ASSY, TAILLAMP, TAILGATE, REAR MIRROR, THIRD BRAKE LIGHT, LOCK ASSY, REAR SPARE TYRE. TO CUT, WELD AND RENEW REAR PANEL OUTER&INNER. TO STRAIGHTEN, KNOCK AND REPAIR REAR FLOORBOARD PANEL AND REALIGN THE SAME.	1,200.00	1 PC	1,200.00	?
19 REMOVE AND REFIT REAR CARPET, GARNISH AND REAR SEAT.	120.00	1 PC	120.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : LONPAC INSURANCE BERHAD

300 BEACH ROAD

#17-04/07 THE CONCOURSE

SINGAPORE 199555

TEL: 62507388

FAX: 62963767

ATTN: Motor Claim Department

Estimate No: ES1891158/WS

Date: 09 Oct 2018

Policy No: 5068938166-03

Veh Reg No: PC3417G

Make/Model: TOYOTA TOYOTA
HIACE COMMUTER GL
3.0

WS Ref: TP/LONPAC

Claim Type: Third Party

Accident Date: 08/10/2018

TP Veh Reg No: GX1480G

Chassis No: KDH2230021240

Engine No: 1KD2439305

Reg. Date: 10/12/2014

Estimate Repair Cost to Vehicle No :PC3417G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
20 PUTTY AND RESPRAY ON REAR FLOORBOARD PANEL, REAR END PANELS, TAILGATE, REAR LH SIDE PANEL, LH TAILAMP PANEL AND REAR AFFECTED AREAS.	1,000.00	1 PC	1,000.00	1,000.00
21 RUSTPROOFING	80.00	1 PC	80.00	80.00
22 REMOVE AND REFIT REVERSE SENSOR.	30.00	1 PC	30.00	30.00
			2,530.00	2,530.00
			Total	S\$ 7,266.94
			Add GST @ 7%	508.69
			Total Amount Payable	S\$ 7,775.63

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: