

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 6632L

DATE 10/6/2018 11:13

MAKE :

MODEL : HYUNDAI i40

EQ JM

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Licence Lamp (LH) <i>— cut</i>		\$ 33.95	\$ 33.95
	Licence Lamp Cover <i>— cut</i>		(SN) 150	\$ 380.80 <i>2 price</i>
	Rear Bumper <i>x repair</i>			\$ 553.00
	Rear Bumper Clip 10 pcs <i>x m</i>			\$ 22.00
	Rear Bumper Under Cover <i>— cut</i>			\$ 228.00
SUB TOTAL				\$ 1,217.75
LESS 20%				\$ 243.55
DISCOUNTED TOTAL				\$ 974.20
	Rear No.Plate <i>— cut</i>			\$ 25.00 Nett
TOTAL				25.00
	Labour Charge			200
	Panel Beating			\$ 220.00
	Spray Painting Charge			\$ 220.00
TOTAL LABOUR				\$ 440.00
ESTIMATE TOTAL				\$ 1,439.20

Kalvin (K) 14
8/10/18 10 20 hrs
2 Days
U/S
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification is allowed
- Supplementary items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.