

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1153/2018/GW
Date : 10-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

FWD Insurance- Singapore

6 Temasek Boulevard

#18-01 Suntec Tower Four

Singapore 038986

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr.Richard Chandra
Address : 15 Sengkang East Ave
#15-12
Singapore 544806
Telephone : HP + 93680589
Type of Claim : Own Damage Claims
Policy No. : PNPV 2018 - 00008681
Vehicle No : **SLJ 9239 A**
Model Code : Audi A3 Sedan 1.40TFSI
Model / Year : Dec-16
Engine No : CHZ132253
Chassis No : WAUZZZ8V2H1012252
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Oct-18
Place of Accident : HDB Clementi 346 Clementi Avenue 5 S(12036) Open Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 9239 A.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid, check fucntion.	S/N \$	280.00	✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed .	S/N \$	900.00 600	
3	To respray rear bumper.	\$	800.00 600	
5	To carry out diagnostic check.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 2,172.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 9239 A .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Rehnd</i>	\$ 1,697.00	✓
2	REAR BUMPER STICKY PAD ?	-	?
3	REAR BUMPER FIXING PARTS <i>new</i>	\$ 166.00	X
4	ADAPTER WHEELS HOSUING LINER <i>new</i>	\$ 32.00	X
5	REAR BUMPER GUIDE SECTION-RH <i>new</i>	\$ 14.00	✓
6	REAR BUMPER LOCKING MECHANISM <i>new</i>	\$ 25.00	X
7	REAR BUMPER SPOILER <i>lt</i>	\$ 206.00	✓
8	REAR LIGHT REFLECTOR-LH/RH ?	2 \$ 70.00	?
9	REAR BUMPER SIDE REINFORCEMENT ?	\$ 501.00	?
10	REAR BUMPER BRACKET-RH <i>new</i>	\$ 24.00	X
11	REAR BUMPER GUIDE SECTION-RH <i>new</i>	\$ 57.00	X
12	REAR SENSOR ?	2 \$ 421.00	?
13	REAR SENSOR SEAL RING <i>new</i>	4 \$ 14.00	X
14	SUNDRIES ?	\$ 300.00	?
GRAND TOTAL SPARE PARTS		: \$ 3,527.00	
TOTAL LABOUR CHARGES		: \$ 2,172.00	
GRAND TOTAL		: <u>\$ 5,699.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 10/10/18
Authorised Date :
Excess Cost : \$500.
Liability :
Remarks : Not Authorised, 03 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant