

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

6-Oct-18

Our ref : TP/4586/18

Nyeo Ling Ling Clarice

TPA (K).
Poh Kin.

JHMGK 5850FX 202725

RE : estimate cost for vehicle no : SFY 7272H

1 pc	frt bumper	Rehnd	\$	694.90	✓	558
1 pc	frt bumper rh retainer	ne		22.40	✓	
1 pc	frt rh fender	Rehnd		562.00	✓	
1 pc	frt rh fender inner shield	Rehnd		176.80	✓	
10 pcs	frt rh fender inner shield clips	ne		39.00	30	
1 pc	frt rh wing mirror housing	Pangd		527.00	✓	
1 pc	frt rh wing mirror cover	Missing		80.90	✓	
1 pc	frt rh door	Rehnd		957.20	✓	
2 pcs	frt rh door hinges	ne		74.40	+	
1 pc	frt rh door ledge	ne		37.20	+	
1 pc	frt rh door outer handle	Pangd		322.70	✓	
1 pc	frt rh door key lock	ne		119.30	x	
1 pc	frt rh door trimboard	ne		449.40	x	
1 pc	frt rh door regulator gear w/motor	ne		482.90	x	
1 pc	frt rh door channel	ne		153.10	+	
1 pc	frt rh door lock w/centre lock motor	ne		299.20	x	
1 pc	frt rh door sticker	ne		52.90	✓	
1 pc	frt rh door outer moulding	ne		83.90	+	
1 pc	frt rh door rubber	ne		161.90	+	
1 pc	rear rh door	Distorted		903.40	✓	
2 pcs	rear rh door hinges	ne		71.60	+	
1 pc	rear rh door ledge	ne		37.20	+	
1 pc	rear rh door outer moulding	ne		142.70	x	
1 pc	rear rh door sticker	ne		55.40	✓	
1 pc	rear rh door trimboard	Rehnd		495.60	✓	
1 pc	rear rh door rubber	ne		125.40	✓	
1 pc	rear rh door lock	ne		299.60	+	
1 pc	rear rh door regulator gear w/motor	Pangd		492.60	✓	
1 pc	rear rh door speaker	ne		324.80	+	
1 pc	rh rocker panel	Repair		352.30	+	
1 pc	rh rocker garnish	Pangd		513.10	✓	
15 pcs	rh rocker garnish clips	ne		58.50	30	
1 pc	rear rh fender	Rehnd, Repair		759.30	+	
1 pc	rear bumper	Rehnd		692.60	✓	575
				10621.20		

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : estimate cost for vehicle no : SFY 7272H

Bal brought forward:	\$	10,621.20	
1 pc	rear bumper rh retainer <i>ne</i>	36.50	✓
6 pcs	rear bumper clips <i>ne</i>	23.40	✓
1 pc	rh door pillar <i>Reps</i>	759.80	x
2 pcs	rims <i>cut</i>	1,639.20	1000(SN)
1 pc	frt rh fender inner garnish <i>ne n</i>	38.20	✓
		13,118.30	
	less 20%	2,623.66	
		10,494.64	
2 pcs	tyres <i>new low cut</i>	600.00	snett x 220
1 pc	rear w/screen gum <i>new</i>	50.00	x
Panel beating.		1,500.00	1000
Spray painting.		2,000.00	1500
Transfer 2 door parts.		160.00	✓
Alignment.		80.00	✓
Remove & refit rearw/screen.		120.00	x.
		15,004.64	
	Plus 7% GST	1,050.32	
		16,054.96	

SD : Sixteen thousand fifty-four & cents ninety-six only.

Adrian Lim, total: \$321.76
H/s 08/10/18. 4/51 7.41C.
09 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: