

(08/11/13)

Surrey: Kelvin

REF:

C03/Tml18018236/K1tb2

Mufimen

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Insp'd Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SMA 553AX

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA' / .REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHA 7070B Yr Regt: 31 May 2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / T<sub>3</sub> / Prime Mover /

Truck / Trailer or

Make: Hyundai Santa Fe c.c. 1991

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 761681 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KM HET41VMB A81157

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Ignored / Jammed / Leaked / Burnt or

Brake: Ignored / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rrim or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front Rear

R/Bal. 2 mm R/Bal. 2 mm

L/Bal. 2 mm L/Bal. 2 mm

D.O.A. 6/10/18 D.O.I. 8/10/18

Survey held at CDE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SMA 7070B - CS / FCL / 501777 / 96XX

DIA: 181015 Tokyo

SMA 553AX - x

4

9/10/18 Insured C/S \$2800 / 3 Pys. (Red: 1904.90 : 40%)

RECEIVED 10 OCT 2018

Date/Time, File Pass to?

☐ : Prel. Report

1) 10110 Typist

☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL

250

10

260

Report Format: TP

Lump Sum / I.B.I. (\$) 2800

Date/Time: 08.10.2018 08:47

Page : 1

Team: IN ARC Repair TP(CLSO)1

**JOB CARD**

Sales Order:

JC NO.: 305222815

MEMBER

COMFORT TRANSPORTATION PTE LTD

7010045

MEMBER NO.

383 SIN MING DRIVE

ESS

Singapore SINGAPORE 575717

65508755

(R)

(O)

(P)

IDENTIFICATION CARD NO.

REGN NO.:

SHA7070B

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

SONATA

DATE/TIME IN

07.10.2018 08:40

YR OF MANU

31.05.2011

TARGET DATE

CHASSIS CODE

KMHET41VMB811571

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 06.10.2018

NATURE: 3P 06.10.18

*215/0016*


S/NO

LABOR CODE

DESCRIPTION

FRONT

*Front View*



*Back View*

ISSUED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Identification Slip

Exit Pass

No.:

SHA7070B

JU TOKIO

Vehicle No.:

SHA7070B

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/10/2018 08:22
Date Of Accident	06/10/2018 21:25
Exact Location Of Accident	SERANGOON RD SLIP RD TOWARDS PIE TOA PAYOH
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7070B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	TAN KEE CHENG
NRIC No	S0102778F
Date Of Birth	05/11/1954
Occupation	OUTDOOR
Date Of Driving Pass	04/05/1977
Driving Experience	41 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98460556
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 142 BEDOK RESERVOIR ROAD #11-1549
Postcode	470142
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : - GENDER: : FEMALE
Passenger 2	NAME: : - GENDER: : FEMALE
Passenger 3	NAME: : - GENDER: : FEMALE
Passenger 4	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMA5539X
Vehicle Make/Model/Colour	HONDA
Details Of Properties	

Vehicle Category	PRIVATE CAR
Name of Driver	AHMAD
NRIC/Passport Number	
Contact Number	90013929
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	TAN KEE CHENG
Approximate Age	
Injuries Sustain	NECK, SHOULDER AND BACK
Injured person in which vehicle?	SHA7070B
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 6-10-18 Q 2120hr, I was driving My taxi along Serangoon Rd toward PIE Tda Payoh and stop at Slip Road to check Oncoming traffic from right.  
Suddenly Vehicle (B) SMA5539X hit my taxi On the rear portion Cause damage.

There is Video Footage On the Scene.  
There is 4 PAX On board at my taxi  
Total 3 Female and 1 Male No Injury.

Taxi driver Mr Tan Kee cheng, Need Consult doctor Feel pain due to Impact.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 133303021R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)

Reporting Centre Personnel's Signature  
Name:







Our Job Ref No : 305222815

Date : 09/10/18

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

: SHA7070B

Date of Accident : 06/10/18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO --- SMA5539X  
###

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

###

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost


\$2,800.00

3. Estimated normal period for repairs: 3 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : Kalvin

Date : 9/10/18

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE\*

VEHICLE NO : SHA 7070B

DATE 8/10/2018 11:05

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>—</i> <i>Part</i>			\$ 1,349.50	
	Boot Lid Lock Upper <i>X su</i>			\$ 132.10	
	Boot Lid Lock Lower <i>X su</i>			\$ 30.30	
	Boot Lid Sonata Plate <i>—</i> <i>su</i>			\$ 43.60	
	Boot Lid Hyundai Plate <i>—</i> <i>su</i>			\$ 24.20	
	Boot Lid 'H' Emblem <i>—</i> <i>su</i>			\$ 26.10	
	Boot Lid CRDI Plate <i>—</i> <i>su</i>			\$ 22.70	
	Rear Bumper <i>—</i> <i>Part</i>			\$ 578.40	
	Rear Bumper Reinforcement <i>—</i> <i>su</i>			\$ 483.30	
	Rear Bumper Clip <i>—</i> <i>su</i>			\$ 22.00	
	Rear Bumper Sponge <i>X su</i>			\$ 137.40	
	Rear Bumper Under Cover <i>X su</i>			\$ 185.80	
	Rear Bumper Protector (LH/RH) <i>X su</i>		\$ 38.00	\$ 76.00	
	Rear Panel <i>X su</i>			\$ 391.80	
	Rear Panel Garnish <i>X su</i>			\$ 95.80	
	<b>SUB TOTAL</b>			<b>\$ 3,599.00</b>	
	<b>LESS 20%</b>			<b>\$ 719.80</b>	
	<b>DISCOUNTED TOTAL</b>			<b>\$ 2,879.20</b>	
	Boot Lid Comfort Logo & Tel No. Sticker <i>—</i> <i>su</i>			\$ 30.00	Nett
	Boot Lid Advertisement Logo <i>—</i> <i>su</i>			\$ 100.00	Nett
	Rear Bumper Reverse Sensor <i>X</i> <i>su</i>			\$ 135.70	Nett
	Rear Bumper Advertisement Logo <i>—</i> <i>su</i>			\$ 50.00	Nett
	Rear Bumper Rubber Mat <i>—</i> <i>su</i>			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) <i>—</i> <i>su</i>		\$ 100.00	\$ 200.00	Nett
				<b>\$ 565.70</b>	
	<b>Labour Charge</b>				
	Panel Beating			<del>\$ 400</del>	
	Spray Painting Charge			<del>\$ 440.00</del>	
	Wiring Charge			<del>\$ 660.00</del>	600
	Tuff Kote			<del>\$ 30.00</del>	X su
	Remove/Refix Reverse Sensor			<del>\$ 50.00</del>	20
				<del>\$ 80.00</del>	X su
	<b>TOTAL LABOUR</b>			<b>\$ 1,260.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$ 4,704.90</b>	
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					

LKK Auto Consultants hereby certify the Repaired Price (Insurance) as follows:

- To resurvey by the Insurance Company
- To display damaged parts for survey
- Parts prices are based on "Market Price" basis
- Third party survey by the Insurance Company
- No illegal modification or replacement
- Supplementary work must be supervised and is subject to final approval by Insurance Company

Acknowledged by Repairer  
Signature:

TOTAL LABOUR

ESTIMATE TOTAL


























## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Oct 2018 <a href="#">Sendback Est</a>	08 Oct 2018 12:07 <b>S\$4,714.90</b>	08 Oct 2018 17:10 <a href="#">Edit Adj Rpt</a>	<b>S\$2,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured: <b>SOON LAY KIAT</b> , ID: S1319764D									
Main Claimant: <b>CTPL</b> , Co. Reg. No.: 199303821R									
Vehicle Reg. No.: <b>SHA7070B</b>		Date of Loss: 06/10/2018 00:00 - :59 [88 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / M1805034</b>		Policy/Cover Note No.: MT102353 (Comprehensive) Coverage: 12/06/2018 - 11/06/2020							
Vehicle Reg. No. (Insured): <b>SMA5539X</b>		Policy No. (Claimant):							
		Excess: S\$600.00							
Repairer: <b>ComfortDelGro Engineering Pte Ltd (Loyang)</b> 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300									
Handling Insurer: <b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111 ... [Handled by <b>Zheng Hanyang</b> - 65926416]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KALVIN ANG WEI KUN</b> ] ... [Final Rpt due 17/10/2018]									
Adj Asg. Remarks: OUR INSD HAVE NOT REPORT THE ACCIDENT. PLS. CHECK CONSISTENCY OF THE DAMAGE.THKS									
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

SHA7070B (M1805034)  
[SMA5539X]  
TP  
CTPL  
Oct 6 2018 12:00AM  
[SOON LAY KIAT]  
ComfortDelGro Engineering Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		<b>Thumbnail</b> <b>Print</b>
1	08/10/18 12:07	<b>Repairer Estimates</b>		Load HTM
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		<b>Thumbnail</b> <b>Print</b>
1	08/10/18 16:24	<b>Accident Statement</b> From: SC - Reg. No: SMA5539X, Claimant: SOON LAY KIAT		Load HTM
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		<b>Thumbnail</b> <b>Print</b>
1	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
2	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
3	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
4	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
5	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
6	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
7	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
8	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
9	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
10	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
11	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
12	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
13	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
14	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
15	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
16	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
17	09/10/18 18:11	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
18	10/10/18 17:45	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
19	10/10/18 17:45	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
20	10/10/18 17:45	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		<b>Thumbnail</b> <b>Print</b>
1	17/10/18 09:07	<b>LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee</b>		Load PDF
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		<b>Thumbnail</b> <b>Print</b>
1	08/10/18 12:07	<b>E-filed GIA report</b>		Load PDF
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		<b>Thumbnail</b> <b>Print</b>
1	19/10/18 13:00	<b>Letter of Demand from Third Party</b>		Load TIF

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
----------------------------	-----------------------	----------------------	-----------------------

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18018236/K1TBE2

Date: 22/10/2018

## REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MT102353

Claimant Vehicle No: SHA7070B

Insured Vehicle No: SMA5539X

Date of Loss: 06/10/2018

Nature of Claim: TP

Claim No: M1805034

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHA7070B

Make &amp; Model: HYUNDAI SONATA, 2.0 CRDI (A)

Reg. Date: 31/05/2011 (Man. Year: 2011)

Colour: Blue

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: D4EAB965723

Chassis No: KMHET41VMB A811571

Odometer: 761681 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

## CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Hankook 7 mm

Rear Left Side: Hankook 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,444.90	2,469.84	975.06	28.30
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	1,260.00	1,020.00	240.00	19.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,714.90</b>	<b>3,499.84</b>	<b>1,215.06</b>	<b>25.77</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		
(S\$)	4,714.90	2,800.00	1,914.90	40.61
<b>+ GST 7.00/7.00% (S\$)</b>	330.04	196.00	134.04	40.61
<b>Nett Amount (S\$)</b>	<b>5,044.94</b>	<b>2,996.00</b>	<b>2,048.94</b>	<b>40.61</b>

## INSPECTION

Date of Assignment: 08/10/2018 Present Location:

ComfortDelGro Engineering Pte Ltd  
(Loyang)

Date Inspected: 08/10/2018 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 3.0 days

---

**Adjuster:** KALVIN ANG WEI KUN**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2018)
<b>Parts:</b> 143	HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA7070B)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,349.50 FL	*1,349.50 FL
2	1		*BOOTLID LOCK UPPER	Serviceable	132.10 FL	*- FL
3	1		*BOOTLID LOCK LOWER	Serviceable	30.30 FL	*- FL
4	1		*BOOTLID EMBLEM SONATA	Necessary	43.60 FL	*43.60 FL
5	1		*BOOTLID EMBLEM HYUNDAI	Necessary	24.20 FL	*24.20 FL
6	1		*BOOTLID EMBLEM H	Necessary	26.10 FL	*26.10 FL
7	1		*BOOTLID EMBLEM CRDI	Necessary	22.70 FL	*22.70 FL
8	1		*REAR BUMPER ASSY	Deformed	578.40 FL	*578.40 FL
9	1		*REAR BUMPER REINFORCEMENT	Cracked	483.30 FL	*483.30 FL
10	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
11	1		*REAR BUMPER SPONGE	Serviceable	137.40 FL	*- FL
12	1		*REAR BUMPER UNDER COVER	Serviceable	185.80 FL	*- FL
13	2		*REAR BUMPER PROTECTOR LH/RH	Repair	76.00 FL	*- FL
14	1		*REAR PANEL	Repair	391.80 FL	*- FL
15	1		*REAR PANEL GARNISH	Serviceable	95.80 FL	*- FL
16	1		*BOOTLID COMFORT LOGO & TEL.NO STICKER	Necessary	30.00 F	*30.00 FS
17	1		*BOOTLID ADVERTISEMENT LOGO	Necessary	100.00 F	*100.00 FS
18	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 F	*50.00 FS
19	2		*REAR FENDER ADVERTISEMENT LOGO	Necessary	200.00 F	*200.00 FS
20	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 FS
21	1		*REVERSE SENSOR	Not Necessary	135.70 F	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,164.70</b>	<b>2,979.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>719.80</b>	<b>509.96</b>
<b>Total Parts (\$\$)</b>	<b>3,444.90</b>	<b>2,469.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	440.00	400.00
2	SPRAYPAINT	New	660.00	600.00
3	WIRING	New	30.00	0.00
4	TUFF KOTE	New	50.00	20.00
5	REMOVE/REFIX REVERSE SENSOR	New	80.00	0.00
Gross Labour Cost (S\$)			1,260.00	1,020.00

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;