

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 11 Oct 2018

Preliminary Advice

Vehicle No	: SJD2265A	Accident Date	: 05/10/2018
Make	: HONDA STREAM	Policy No.	: PNPV2017-00001781-01
Assignment Date	: 08/10/2018	Excess	: S\$600.00
Date of Inspection	: 09/10/2018	Est. Duration of Repair	: 6.00
Inspection At	: ETHOZ PROTECT PTE LTD (BUKIT BATOK) 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and n/s body. The undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,579.00	(INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	9,226.00	(INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	1,850.00	
Total	:S\$	11,076.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	54,000.00
COE / PARF Rebate	:S\$	42,409.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,591.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SUPPLEMENTARY AMOUNT IS \$ 1,210.00.