

11/03/2018

ASS. REC. BY:

REF: es

FWD18018240/Usd32

Special Instruction:

Pending Amend G1A

Surveyor

Merimen

From (Person):

Marcus

Josey Luh

of

FWD

Date/Time:

8/10/18 @ 4:13pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJD 2265A

Insured:

at Workshop m/s

Ethoz Protect

Tel:

66547750 / 90404688

of

30 Bukit Bukit Crescent

Policy No:

PNPV2017-00001781-01

Claim No:

1201800012822

Sum Insured:

Excess:

\$600-00

Make of Veh:

(Client's Record)

D.O.A. 5/10/18

CA / REV / REP. / REV 24 HRS

(REV)

Insp. Ethoz (Tampines)

H.O.D. Endorsement:

Date/Time:

11:47am @ 9/10/18

Person Contacted:

Jimmy

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJD 2265A - X
9/10/18	Revert via merimen
9/10/18	Rece approved from Josey via merimen
9/10/18	Informed Jimmy CIA ex \$600 by email

Signature *no/cus*

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *2265*

at Workshop m/s: *6862*

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Makes of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

54/c.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *6* days Res: Yes or No

Lump Sum: *1.31* % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

12/3/2018

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: *STD2265A* Yr Regn: *3.08*

Type: *M. Car* / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CAI*

Make: *Honda stream* CC: *1799*

Colour: *Silver* A/C: Insured / Std / NI / NA

Sp. Reading: T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: *RN 6-1058149*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: *Order* / Jammed / Leaked / Burnt or

Brake: *Order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *215/65R15*

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Sincere*

Front

Rear

R/Bal: *6* mm R/Bal: *6* mm

L/Bal: *6* mm L/Bal: *6* mm

D.O.A: *5/10/18* D.O.I: *9/10/18*

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

als frt, als body
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

9 yrs. smth. LTA 42409 net 11591

part by part assessing Admin report. als frt portion

1/11/18 confirmed final fig \$10283.00 with J. may.

*01/11/18 Confirmed P/P \$10,283.00 @ 6 days with Marcus.
(\$5,296.00 Red - 34%)*

RECEIVED 01 NOV 2018

Date/Time: File Pass to:

01/11/18

Date/Time: File Return to:

☐ : Preli. Report
☒ : Final Report

Days Of Repair: *6*

Resurvey No. of Trip: *2*

Survey Fee

Transportation

5 + FS 34

Photo

Other

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Insp (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ *10,283.00 P/P*)

TOTAL

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Oct 2018 Sendback Est	08 Oct 2018 15:00 S\$13,719.00	08 Oct 2018 16:13 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	GWEE LAY HIONG, ID: S7232083B, Tel: +6597844895, Email: sylvlagwee@gmail.com		
Vehicle Reg. No.:	SJD2265A	Date of Loss:	05/10/2018 14:00 - :59 [126 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800012822	Policy/Cover Note No.:	PNPV2017-00001781-01 (Comprehensive)
		Excess:	S\$600.00
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/10/2018]		
Driver/Custodian:	GWEE LAY HIONG (46 / Female), NRIC: S7232083B, Tel: +6597844895		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

 Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 9 October 2018 4:19 PM
To: 'jimmy.gohkl@ethozgroup.com'; SUR
Subject: SJD 2265A-DOA: 5/10/2018 (FWD OD)

Dear Jimmy,

As instructed by our client, please proceed to repair the insured vehicle **SJD 2265A (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler on

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2083B

Vehicle Details

Vehicle No.: SJD2265A

Vehicle to be Exported: No

Intended Deregistration Date: 09 Oct 2018

Vehicle Make: HONDA

Vehicle Model: STREAM 1.8 A

Primary Colour: Silver

Manufacturing Year: 2007

Engine No.: R18A1765316

Chassis No.: RN61058149

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$17,755.00

Original Registration Date: 13 Mar 2008

First Registration Date: 13 Mar 2008

Transfer Count: 0

Actual ARF Paid: \$19,531.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 12 Mar 2028

COE Category: E - Open Category

COE Period(Years): 10

PQP Paid: \$44,998.00

COE Rebate Amount: \$42,409.00

Total Rebate Amount: \$42,409.00

The information contained herein is correct as at 09 Oct 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	2083B

Vehicle Details

Vehicle No.:	SJD2265A
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8 A
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	R18A1765316
Chassis No.:	RN61058149
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$17,755.00
Original Registration Date:	13 Mar 2008
First Registration Date:	13 Mar 2008
Transfer Count:	0
Actual ARF Paid:	\$19,531.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	12 Mar 2028
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$44,998.00
COE Rebate Amount:	\$42,397.00
Total Rebate Amount:	\$42,397.00

The information contained herein is correct as at 08 Oct 2018

OK

500+ dealers
competed to
buy my car!



- ▶ Sell ur Car for More Cash
- ▶ Highest Price or Get \$100 Free
- ▶ Get Paid Now, Handover Later

SELL YOUR CAR

Honda Stream

Price Range ▼

Depreciation ▼

> 10 year(s) ▼

Vehicle Type ▼

Home » Used Cars » 360 VR Cars » Honda Stream 1.8A RSZ (COE till 06/2028)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Honda Stream 1.8A RSZ (COE till 06/2028)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price	\$54,800	
Depreciation	\$5,640 /yr	?
Reg Date	27-Jun-2008 (9yrs 8mths 17days COE left)	
Manufactured	2008	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,799 cc	
Road Tax	\$978 /yr	?
Power	103.0 kW (138 bhp) View specs of the Honda Stream (2007-2014)	
Curb Weight	1,370 kg	?
Features	1.8L, Fuel Economical. Comfortable 7 Seaters. 16 Valves, DOHC, Auto Gear 5 Speed.	
Accessories	Audio System, Leather Seats, Sports Rims, Retractable Side Mirrors, Reverse Camera, Reverse Sensors, Solar Film.	
Description	Smooth Engine, Easy To Maintain Unit, Bank And In House Loan Available! Trade In Welcome. Call To View Now, Viewing By Appointment Only.	
COE	\$37,906	?
OMV	\$18,576	?
ARF	\$18,576	?
Dereg Value	\$36,847 as of today (change)	?
No. of Owners	2	?



Similar Images

Company

Address

Location

Office No

Contact Person

Compare

View Received Message

This mail is associated with :

SJD2265A (1201800012822)

OD

Oct 5 2018 2:00PM

[GWEE LAY HIONG]

ETHOZ Protect Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 12/10/2018 16:00 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$11076.00) - SJD2265A - Claim Handler: Josey Loh

Approved:11076.00.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SJD2265A (1201800012822)

OD

Oct 5 2018 2:00PM

[GWEE LAY HIONG]

ETHOZ Protect Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 09/10/2018 15:43 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$8941.00) - SJD2265A - Claim Handler: Josey Loh

Approved:8941.00:Hi! Please re-seek mandate on check items after being verified

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 11 Oct 2018

Preliminary Advice

Vehicle No	: SJD2265A	Accident Date	: 05/10/2018
Make	: HONDA STREAM	Policy No.	: PNPV2017-00001781-01
Assignment Date	: 08/10/2018	Excess	: S\$600.00
Date of Inspection	: 09/10/2018	Est. Duration of Repair	: 6.00
Inspection At	: ETHOZ PROTECT PTE LTD (BUKIT BATOK) 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and n/s body. The undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,579.00	(INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	9,226.00	(INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	1,850.00	
Total	:S\$	11,076.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	54,000.00
COE / PARF Rebate	:S\$	42,409.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,591.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SUPPLEMENTARY AMOUNT IS \$ 1,210.00.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 09 Oct 2018

Preliminary Advice

Vehicle No	: SJD2265A	Accident Date	: 05/10/2018
Make	: HONDA STREAM	Policy No.	: PNPV2017-00001781-01
Assignment Date	: 08/10/2018	Excess	: S\$600.00
Date of Inspection	: 09/10/2018	Est. Duration of Repair	: 6.00
Inspection At	: ETHOZ PROTECT PTE LTD (BUKIT BATOK) 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and n/s body. The undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,719.00
Revised Amount	:S\$	8,016.00
Check Items (Estimated)	:S\$	1,850.00
Total	:S\$	9,866.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	54,000.00
COE / PARF Rebate	:S\$	42,409.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,591.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/10/2018 17:18
Date Of Accident	05/10/2018 14:05
Exact Location Of Accident	JURONG GATEWAY RD & BOON LAY RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJD2265A
Insured/Policyholder	
Name Of Registered Owner	GWEE LAY HIONG
NRIC No	S7232083B
Email Address	SYLVIAGWEE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97844895
Alternative Phone No	OFFICE-97844895

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM 1.8 A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00001781-01
Cover Note Number	13/03/2018-12/03/2019

Driver

Name of Driver	GWEE LAY HIONG
NRIC No	S7232083B
Date Of Birth	09/06/1972
Occupation	INDOOR
Date Of Driving Pass	15/03/1996
Driving Experience	22 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	+65-97844895
Fax Number	
Contact Number	OFFICE-97844895
EEmail Address	SYLVIAGWEE@GMAIL.COM

Address	707 TAMPINES ST 71
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDF4505E
Vehicle Make/Model/Colour	NISSAN LATIO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHAN CHEONG CHOY
NRIC/Passport Number	S1821245E
Contact Number	90491121
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
138 Robinson Road #07-09
The Corporate Office
Singapore 068906
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS

Original Report No : MOR118129493 Vehicle Registration No : SJD2265A
Name(as shown in NRIC) : GWEE LAY HIONG
[("Vehicle Driver/Vehicle Owner) ("Please delete as appropriate
NRIC/Passport No : S72320838
Address :
Contact (Tel) : (H/P) : 97844895
(Email) :
Date Of Accident : 05/10/2018 Time Of Accident : 14:05
Place Of Accident : JURONG GATEWAY RD & BOON LAY RD
Insurance Company : FWD Singapore Pte. Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:-

amend statement on sketch plan


SIGNATURE OF VEHICLE OWNER/DRIVER

DATE: 10/10/2018

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 5/10

Driver's Signature
(If driver is not the policyholder)
Date & Time: 5/10

Reporting Centre Personnel's Signature
Name: [Signature]
NRIC/FIN No.: [Signature]

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- When approaching this junction, noticing that cars are moving even though in red light and some traffic lights are blinking in red and amber.
- Realized that traffic lights not working and waited.
- When right and left were cleared, and a few cars moved together. I was almost crossing the junction when suddenly SDF 4505E approached with speed and hit my ~~back~~ side.
- After that, witness pointed to me that there is traffic light maintenance. Spoken to the repair guy at the traffic light cabinet, he said the red light is not working.

You have been advised by workshop that in the event that you wish to claim against your own policy (OD claims), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only

☒ Claim OD

☐ Claim TP

☐ Claim OD / TP at Driver's Workshop

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time: 5/10

Driver's Signature
(If driver is not the policyholder)
Date & Time: 5/10

Reporting Centre Personnel's Signature
Name: [Signature]
NIC/FIN No.:

Sketch Plan

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
138 Robinson Road #07-09
The Corporate Office
Singapore 068906
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS

Original Report No: MOR118129493 Vehicle Registration No: SJD2265A
Name(as shown in NRIC): GWEE LAY HIONG
[Vehicle Driver/Vehicle Owner] (*Please delete as appropriate)
NRIC/Passport No: S7232083B
Address: _____
Contact (Tel): _____ (HIP) 97844895
(Email): _____
Date Of Accident: 05/10/2018 Time Of Accident: 14.05
Place Of Accident: JURONG GATEWAY RD & BOON LAY RD
Insurance Company: FWD Singapore Pte. Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:-


amend statement on sketch plan

SIGNATURE OF VEHICLE OWNER/DRIVER

DATE:

10/10/2018

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- When approaching this junction, noticing that cars are moving even though in red light and some traffic lights are blinking in red and amber.
- Realised that traffic lights not working and waited.
- When right and left was cleared, ~~see~~ a few cars moved together. I was almost crawling the junction when suddenly YDF 9505E approached with speed and hit my ~~back and left~~ side.
- After that, witness pointed to me that there is traffic light maintenance spoken to the repair guy at the traffic light cabinet, he said the red light is not working.

You have been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only
☒ Claim OD
☐ Claim TP
☐ Claim OD / TP at 01st or on-ship

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time: 5/10

Driver's Signature
(If driver is not the policyholder)
Date & Time: 5/10

Reporting Centre Personnel's Signature
Name: [Signature]
NIC/PIN No.:



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2017-00001781-01 (Comprehensive - Classic Plan)

Car plate number: SJD2265A

Your name (As the policyholder): Gwee Lay Hiong

Coverage start date: 13/03/2018

Coverage end date: 12/03/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company:

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 25/02/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.leg@fwd.com if any details
in this Certificate of Insurance need to be changed.



YOUR CLASSIC CAR INSURANCE SUMMARY

Please call +65-6322-2072 for FWD Emergency Assistance
 if Your Car breaks down or is involved in an accident.
 All accidents must be reported within 24 hours or the next working day of the incident
 regardless of whether it will lead to a claim.

POLICY NUMBER : PNPV2017-00001781-01

About this policy

Premium paid	: S\$631.77	Coverage start date	: 13/03/2018
(Inclusive of GST)		Coverage end date	: 12/03/2019
Who is insured to drive:	: You and any Authorised Driver		
Policy Type	: CLASSIC		

About you (As the policyholder)

Your name	: Gwee Lay Hiong		
Address	: 55 Tampines Avenue 1 #05-03 The Tropica Singapore 529773		
Email	: sgwee@esrisingapore.com.sg		
NRIC/FIN	: 57232083B	Date of birth	: 09/09/1972
Marital status	: Married	Gender	: Female
Current no claims discount	: 50%	Mobile Number	: 97844895
Years of driving experience	: Three or more	Certificate of merit	: Yes

About your car

Car make and model	: HONDA STREAM 1.8
Year of first registration	: 2008
Car plate number	: SJD2265A
Issued on:	: 25/02/2018

Abhishek Bhatia
 Chief Executive Officer
 FWD Singapore Pte Ltd

Please refer to contract for specific terms, conditions
 and exclusions of this policy.

Please immediately inform us at +65-6820-8888
 or email us to contact.sg@fwd.com if any details in
 this Car Insurance Summary need to be changed.

DRIVER IC

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7232083B



NAME
GWEE LAY HIONG
(WEI LIXIANG)
魏丽香
Race
CHINESE
Date of Birth
08-08-1972
Country of Birth
SINGAPORE



1043300



57232083B



24-01-1974

APT BLK 201 TAMMIL STREET 71 # 1-02
SINGAPORE 110071
APRIC 2005



INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00001781-01	Date of Loss:	05/10/2018
Vehicle Reg. No.:	SJD2265A	Driveable?	
Driver Age/Info:	46 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GWEE LAY HIONG	Contact No:	+6597844895
Driver:	GWEE LAY HIONG		
Make/Model:	HONDA STREAM, 1.8 (A)	Vehicle Reg. Date:	13/03/2008
Vehicle Colour:	SILVER		
Engine No:	R18A1765316	Chassis No:	RN61058149
Odometer:	298620 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Remarks:	VEHICLE IN WORKSHOP!		
Present Location:	ETHOZ PROTECT PTE LTD (TAMPINES)		

Present Location: ~~ETHOZ PROTECT PTE LTD (TAMPINES)~~

COST OF CLAIMS

Parts

Miscellaneous Items

Labour

Paintwork Labour

Towing

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Gross Total /

Gross Total (\$\$)	13,719	13,719.00
--------------------	--------	-----------

+ GST 7.00% (S\$)	960.33
-------------------	--------

Nett Amount (S\$)	14,679.33
-------------------	-----------

This claim is handled by: JIMMY GOH - 9040 4688

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Oct 2018)
 Parts: M1-MPV HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJD2265A)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>Deep cut</i>	0.00	0.00	*680.00 F ✓
2	1		*REAR BUMPER SIDE RETAINER LH <i>11</i>	0.00	0.00	*48.00 F X
3	10		*REAR BUMPER CLIPS <i>rec</i>	0.00	0.00	*40.00 F —
4	1		*REAR FENDER LH <i>rec</i>	0.00	0.00	*900.00 F X
5	1		*REAR FENDER QUARTER GLASS MOULDING LH <i>11</i>	0.00	0.00	*90.00 F X
6	1		*REAR DOOR LH <i>300500</i>	0.00	0.00	*850.00 F —
7	1		*REAR DOOR UPPER HINGE LH <i>11</i>	0.00	0.00	*65.00 F X
8	1		*REAR DOOR LOWER HINGE LH <i>11</i>	0.00	0.00	*65.00 F X
9	1		*REAR DOOR WEATHER STRIP LH <i>rec</i>	0.00	0.00	*160.00 F —
10	1		*REAR DOOR INNER LOCK LH <i>11</i>	0.00	0.00	*230.00 F X
11	1		*REAR DOOR FRAME STICKER LH <i>rec</i>	0.00	0.00	*60.00 F —
12	1		*ROCKER PANEL LH <i>rec</i>	0.00	0.00	*350.00 F X
13	1		*CENTRE DOOR PILLAR LH <i>rec</i>	0.00	0.00	— X
			REPAIR			
14	1		*FRONT DOOR LH <i>300500</i>	0.00	0.00	*900.00 F —
15	1		*FRONT DOOR UPPER HINGE LH <i>11</i>	0.00	0.00	*65.00 F X
16	1		*FRONT DOOR LOWER HINGE LH <i>11</i>	0.00	0.00	*65.00 F X
17	1		*FRONT DOOR WEATHER STRIP LH <i>rec</i>	0.00	0.00	*160.00 F —
18	1		*FRONT DOOR INNER LOCK LH <i>11</i>	0.00	0.00	*230.00 F X
19	1		*FRONT DOOR FRAME STICKER LH <i>rec</i>	0.00	0.00	*75.00 F —
20	1		*FRONT FENDER LH <i>300500</i>	0.00	0.00	*550.00 F —
21	1		*FRONT FENDER SIGNAL LAMP LH <i>one</i>	0.00	0.00	*38.00 F —
22	1		*FRONT FENDER INNER SHIELD LH <i>1000</i>	0.00	0.00	*138.00 F —
23	10		*FRONT FENDER INNER SHIELD CLIPS <i>rec</i>	0.00	0.00	*40.00 F —
24	1		*FRONT BUMPER <i>rec/nagab</i>	0.00	0.00	*750.00 F —
25	1		*FRONT BUMPER SIDE RETAINER LH <i>rec</i>	0.00	0.00	*55.00 F —
26	10		*FRONT BUMPER CLIPS <i>rec</i>	0.00	0.00	*40.00 F —
27	1		*FRONT SHOCK ABSORBER LH <i>300</i>	0.00	0.00	*330.00 F —
28	1		*FRONT KNUCKLE ARM LH <i>300</i>	0.00	0.00	*300.00 F —
29	1		*FRONT KNUCKLE BEARING LH <i>rec</i>	0.00	0.00	*95.00 F —
30	1		*FRONT WHEEL HUB LH <i>300</i>	0.00	0.00	*185.00 F —
31	1		*FRONT LOWER ARM LH <i>300</i>	0.00	0.00	*350.00 F —
32	1		*FRONT STABILIZER LINK LH <i>11</i>	0.00	0.00	*105.00 F X
33	1		*FRONT TIE ROD END LH <i>300</i>	0.00	0.00	*90.00 F —
Total Parts (\$S)						8,099.00

F=Franchise part

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

5883

P-7093
 S.N 360
 102830
 10283

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT SPORT RIM LH 15 <i>20/201</i>	550.00
2	1	FRONT TYRE LH (FALKEN) 205/65R15 <i>500</i>	180.00 X
3	1	REAR QUARTER GLASS SEALANT LH <i>11</i>	60.00
4	1	REAR SPORT RIM LH 15 <i>20/201</i>	550.00
5	1	REAR TYRE LH (FALKEN) 205/65R15 <i>500</i>	180.00 X
Sub Total (S\$)			1,520.00

360

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR TO FACILITATE REPAIR	New <i>1100</i>	1,500.00
2	TO REMOVE & INSTALL LHR FENDER QUARTER GLASS	New <i>11</i>	100.00 X
3	TO REMOVE & INSTALL SEATS, CAPETS & TRIMS TO FACILITATE REPAIR	New <i>60</i>	200.00
4	TO REMOVE & INSTALL LHR DOOR COMPONENTS	New <i>60</i>	80.00
5	TO REMOVE & INSTALL LHF DOOR COMPONENTS	New <i>60</i>	80.00
6	TO REMOVE & INSTALL LHR SPORT RIM INCLUDING TYRE BALANCING	New <i>11</i>	20.00 <i>1</i>
7	TO REMOVE & INSTALL LHF SPORT RIM INCLUDING TYRE BALANCING	New <i>11</i>	20.00 <i>1</i>
8	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	New	70.00 ✓
9	TO REMOVE & INSTALL LHF UNDERCARRIAGE PARTS	New <i>150</i>	200.00
10	TO CONDUCT ANTI RUST COATING ON AFFECTED AREAS	New <i>120</i>	100.00 X
11	TO CHECK & RECONNECT ALL NECESSARY WIRINGS	New	30.00 ✓
12	TO SPRAY PAINT ON AFFECTED AREAS	New <i>1300</i>	1,700.00
Gross Labour Cost (S\$)			4,100.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2830

ETHOZ PROTECT PTE LTD

Company Registration No. 199005791M

30 Bukit Batok Crescent, SINGAPORE 658075, Website: <http://www.orix.com.sg>

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 10 Oct 2018)**Parts:** M1-MPV HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ETHOZ Protect Pte Ltd/SJD2265A/10/10/2018 16:10**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR WINDOW OUTER MOULDING LH	0.00 <i>see</i>	0.00	*135.00 F ✓
2	1		*REAR POWER WINDOW REGULATOR LH	<i>skipped</i> 0.00 <i>see</i>	0.00	*400.00 F ✓
3	1		*FRONT WINDOW OUTER MOULDING LH	0.00 <i>see</i>	0.00	*135.00 F ✓
4	1		*FRONT POWER WINDOW REGULATOR LH	<i>skipped</i> 0.00 <i>see</i>	0.00	*400.00 F ✓
5	1		*HEADLAMP LH	0.00 <i>11</i>	0.00	*650.00 F X
6	1		*FRONT RACK END LH	0.00 <i>see</i>	0.00	*140.00 F ✓
Total Parts (S\$)						1,860.00

F=Franchise part.

ETHOZ Protect Pte Ltd/SJD2265A/10/10/2018 16:10. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)
No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496858 Fax: 67495866/67495007
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6369 / 6384 2235 Fax: 6384 2245
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197602013M



TAX INVOICE NO.: TL126668
INVOICE DATE : 10/10/2018
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : TBS
PAGE(S) : 1

No.: M2-00252314

ECLI
HOZ PROTECT PTE LTD
TAMPINES ST 92
D 2265 A(P/O:164642)
DER BY:JIMMY

AX INVOICE

RTS NO	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	AMOUNT
				(SIN)	(SIN)
715-SMA-000ZZ	FACE,RR BUMPER		1 PCS	680.000	680.00
503-SZ3-003	CLIP,BUMPER		10	4.000	40.00
550-SMC-000ZZ	PANEL ASSY,RR DOOR,LH		1	850.000	850.00
850-SMA-003	WEATHERSTRIP,RR DOOR OPNG,LH		1 PCS	160.000	160.00
864-SMA-003	TAPE,RR DOOR SASH,LH		1	60.000	60.00
050-SMA-000ZZ	PANEL ASSY,FR DOOR,LH		1	900.000	900.00
350-SMA-003	WAETHERSTRIP,FR DOOR OPNG,LH		1	160.000	160.00
364-SMA-003	TAPE,FR DOOR SASH,LH		1 PCS	75.000	75.00
260-SMA-300ZZ	FENDER,FR LH		1	550.000	550.00
301-S5H-T02	FENDER LAMP (WHITE)		1	38.000	38.00
151-SMA-000	COWLING,FR FENDER,LH		1 PCS	135.000	135.00

INDUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED


TOTAL

SIGNATURE

SIGNATURE

豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)
No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496858 Fax: 67495866/67495007
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6369 / 6384 2235 Fax: 6384 2245
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197602013M



TAX INVOICE NO.: TL126668
INVOICE DATE : 10/10/2018
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : TBS
PAGE(S) : 2

No.: M2-00252314

ECLI
HOZ PROTECT PTE LTD
TAMPINES ST 92
D 2265 A(P/O:164642)
DER BY:JIMMY

AX INVOICE

RTS NO	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	AMOUNT
				(SIN)	(SIN)
501-S04-003	CLIP		10	4.000	40.00
711-SMA-000ZZ	FACE,FR BUMPER		1 PCS	750.000	750.00
198-SMA-003	SPACER,FR BUMPER,LH		1 PCS	55.000	55.00
503-SZ3-003	CLIP,BUMPER		10	4.000	40.00
606-SMA-J03	SHOCK ABSORBER,FR LH		1	330.000	330.00
216-SMA-000	KNUCKLE,FR LH		1	300.000	300.00
300-SMA-A51	FR BEARING[A52]		1 PCS	95.000	95.00
360-SMA-030	ARM ASSY,FR LOWER,LH		1 PCS	350.000	350.00
560-SMA-003	END ASSY,TIE ROD,LH		1 PCS	90.000	90.00

INDUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED

TOTAL

No. 3 Kallang Way 2A Fong Tai Building Singapore 247493 Tel: 67493588/67493558 Fax: 67495666/67495007
25 Kaki Bukit Road 4, #01-23 Symmy @ KB Singapore 417800. Tel: 6396 6368 / 6394 2235 Fax: 6384 2245
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197602013M



BMW



 MITSUBISHI MOTORS

GENUINE PARTS

PAGE(S) : 3

RTS NO.	DESCRIPTION	LOC	QUANTITY	UNIT PRICE	AMOUNT
	Dept Head _____			(SIN)	(SIN)
	Agreement No _____				
	Job Card No _____				
	Finance _____				
	Control No _____			GST Excl Amount :	5698.00
	Invoice No _____			Special Discount :	
				GST @ 7 % :	398.86
	Remarks _____				
	Est. finalized Amt _____				

GOODS SOLD ARE NOT RETURNABLE FOR CASH. GOODS RECEIVED

TOTAL

6096.86

PRINT BY :
TBS 10/10/2018 11:51:42



Jimmy Goh

SIGNATURE

豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED
 (AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tat Building Singapore 347403 Tel: 67493588/67490958 Fax: 67490666/67495007
 25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800 Tel: 6396 6369 / 6394 2235 Fax: 6394 2245
 Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
 Co. Reg. No.: 197602913M



TAX INVOICE NO.: TL126681
 INVOICE DATE : 11/10/2018
 CREDIT TERMS : 30 DAYS
 SALES ORDER NO.:
 SALESMAN : TBS
 PAGE(S) : 1

No.: M2-00252314

ECLI

HOZ PROTECT PTE LTD
 TAMPINES ST 92
 D 2265 A(P/O:164642)
 DER BY:JIMMY

AX INVOICE

RTS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	AMOUNT
				(SIN)	(SIN)
600-SDA-A00	WHEEL HUB,FR		1 PCS ✓	185.000	185.00
950-SMA-003	REAR DOOR OUTER MOULDING,LH		1 PCS ✓	135.000	135.00
750-SMA-003	REAR DR WDO REGULATOR,LH EXCHANGE		1 PCS ✓	400.000	400.00
450-SMA-003	FR DOOR OUTER MOULDING,LH		1 PCS ✓	135.000	135.00
250-SMA-003	FR DOOR WDO REGULATOR LH		1 PCS ✓	400.000	400.00
010-SMA-003	RACK END LH ✓		1 PCS ✓	140.000	140.00

INDUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED

TOTAL

SIGNATURE

SIGNATURE

豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED
 (AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tat Building Singapore 347403 Tel: 67493588/67490958 Fax: 67490666/67495007
 25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800 Tel: 6396 6369 / 6394 2235 Fax: 6394 2245
 Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
 Co. Reg. No.: 197602913M



TAX INVOICE NO.: TL126681
 INVOICE DATE : 11/10/2018
 CREDIT TERMS : 30 DAYS
 SALES ORDER NO.:
 SALESMAN : TBS
 PAGE(S) : 2

No.: M2-00252314

ECLI

HOZ PROTECT PTE LTD
 TAMPINES ST 92
 D 2265 A(P/O:164642)
 DER BY:JIMMY

AX INVOICE

RTS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	AMOUNT
	Dept Head			(SIN)	(SIN)
	Agreement No				
	Job Card No				
	Finance				
	Control No				
	Invoice No				
	Remarks				
	Est. finalized Amt				
				GST Excl Amount :	1395.00
				Special Discount :	
				GST @ 7 % :	97.65

INDUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED

TOTAL

1492.65

PRINT BY :
 TBS 11/10/2018 10:43:40



SIGNATURE

Jimmy Goh

SIGNATURE

Ann: Marcus,

Date : 22/10/2018
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : GWEE LAY HIONG

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2017-00001781-01 Accident Date : 05/10/2018

Vehicle No : SJD-2265-A Make & Model : HONDA STREAM 1.8 (A)

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
<u>List Item</u>			
1	REAR WINDOW OUTER MOULDING LH - Supp	135.00	135.00
1	REAR POWER WINDOW REGULATOR LH - Supp	400.00	400.00
1	FRONT WINDOW OUTER MOULDING LH - Supp	135.00	135.00
1	FRONT POWER WINDOW REGULATOR LH - Supp	400.00	400.00
1	HEADLAMP (LH)	650.00	0.00
1	FRONT RACK END LH	140.00	140.00
1	REAR BUMPER	680.00	680.00
1	REAR BUMPER SIDE RETAINER (LH)	48.00	0.00
10	REAR BUMPER CLIPS	40.00	40.00
1	REAR FENDER (LH) RESTORE	900.00	0.00
1	REAR FENDER QUARTER GLASS MOULDING LH	90.00	0.00
1	REAR DOOR LH	850.00	850.00
1	REAR DOOR UPPER HINGE LH	65.00	0.00

PAGE : 1

Date : 22/10/2018

To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : GWEE LAY HIONG

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2017-00001781-01 Accident Date : 05/10/2018

Vehicle No : SJD-2265-A Make & Model : HONDA STREAM 1.8 (A)

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	REAR DOOR LOWER HINGE LH	65.00	0.00
1	REAR DOOR WEATHERSTRIPE L/H	160.00	160.00
1	REAR DOOR INNER LOCK (L/H)	230.00	0.00
1	REAR DOOR FRAME STICKER LH	60.00	60.00
1	ROCKER PANEL (LH) RESTORE	350.00	0.00
1	CENTRE DOOR PILLAR L/H RESTORE	0.00	0.00
1	FRONT DOOR (LH)	900.00	900.00
1	FRONT DOOR UPPER HINGE LH	65.00	0.00
1	FRONT DOOR LOWER HINGE LH	65.00	0.00
1	FRONT DOOR WEATHER STRIP LH	160.00	160.00
1	FRONT DOOR INNER LOCK L/H	230.00	0.00
1	FRONT DOOR FRAME STICKER LH	75.00	75.00
1	FRONT FENDER (LH)	550.00	550.00
1	FRONT FENDER SIGNAL LAMP LH	38.00	38.00
1	FRONT FENDER INNER SHIELD (LH)	138.00	135.00

PAGE: 2

Date : 22/10/2018

To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : GWEE LAY HIONG

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2017-00001781-01 Accident Date : 05/10/2018

Vehicle No : SJD-2265-A Make & Model : HONDA STREAM 1.8 (A)

FINAL ESTIMATED REPAIR COST DETAIL Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
10	FRONT FENDER INNER SHIELD CLIPS	40.00	40.00
1	FRONT BUMPER	750.00	750.00
1	FRONT BUMPER SIDE RETAINER (LH)	55.00	55.00
10	FRONT BUMPER CLIPS	40.00	40.00
1	FRONT SHOCK ABSORBER L/H - CHECK	330.00	330.00
1	FRONT KNUCKLE ARM L/H - CHECK	300.00	300.00
1	FRONT KNUCKLE BEARING LH - CHECK	95.00	95.00
1	FRONT WHEEL HUB LH - CHECK	185.00	185.00
1	FRONT LOWER ARM L/H - CHECK	350.00	350.00
1	FRONT STABILIZER LINK LH	105.00	0.00
1	FRONT TIE ROD END LH - CHECK	90.00	90.00
Sub Total		8709.00	7093.00
Add 0% On Parts		0.00	0.00

Special Nett Item

PAGE: 3

Date : 22/10/2018
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : GWEE LAY HIONG

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2017-00001781-01 Accident Date : 05/10/2018

Vehicle No : SJD-2265-A Make & Model : HONDA STREAM 1.8 (A)

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	REAR QUARTER GLASS SEALANT LH	60.00	0.00
1	FRONT SPORT RIM LH 15"	550.00	180.00
1	REAR SPORT RIM LH 15"	550.00	180.00
1	FRONT TYRE LH (FALKEN) 205/65R15	180.00	0.00
1	REAR TYRE LH (FALKEN) 205/65R15	180.00	0.00
Sub Total		1520.00	360.00

Labour & Misc

LABOUR TO FACILITATE REPAIR	1500.00	1100.00
TO REMOVE & INSTALL LHR FENDER QUARTER GLASS	100.00	0.00
TO REMOVE & INSTALL SEATS, CARPETS & TRIMS TO FACILITATE REPAIR	200.00	60.00
TO REMOVE & INSTALL LHR DOOR COMPONENTS	80.00	60.00

PAGE : 4

Date : 22/10/2018

To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : GWEE LAY HIONG

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2017-00001781-01 Accident Date : 05/10/2018

Vehicle No : SJD-2265-A Make & Model : HONDA STREAM 1.8 (A)

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	TO REMOVE & INSTALL LHF DOOR COMPONENTS	80.00	60.00
	TO REMOVE & INSTALL LHR SPORT RIM INCLUDING TYRE BALANCING	20.00	0.00
	TO REMOVE & INSTALL LHF SPORT RIM INCLUDING TYRE BALANCING	20.00	0.00
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	70.00	70.00
	TO REMOVE & INSTALL LHF UNDERCARRIAGE PARTS	200.00	150.00
	TO CONDUCT ANTI RUST COATING	100.00	0.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	30.00
	TO SPRAY PAINT ON AFFECTED AREAS	1700.00	1300.00

PAGE : 5

Date : 22/10/2018
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : GWEE LAY HIONG

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2017-00001781-01 Accident Date : 05/10/2018

Vehicle No : SJD-2265-A Make & Model : HONDA STREAM 1.8 (A)

FINAL ESTIMATED REPAIR COST DETAIL Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	4100.00	2830.00

Sub Total	15,579.00	10,283.00
GST 7.0 %	1,090.53	719.81
Total	16,669.	11,002.

Materials : \$ 7,093.00
Mark Up /
List Down :
S/N Items : \$ 360.00
Labour : \$ 2,830.00
Total : \$ 10,283.00
Lump Sum :
Excess : \$ 600.00
Total : \$ 9,683.00
7% GST : \$ 677.81
Grand Total : \$ 10,360.81 Repair Days : 06
Signature : 

Surveyor Name : MARCUS - LKK

Date & Time : 09/10/2018 14:00:00

Jimmy Goh K1

CLAIM DEPARTMENT

DID : 66547618

FAX : 6654 7648

PAGE : 6



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Oct 2018 Sendback Est	08 Oct 2018 15:00 \$13,719.00	08 Oct 2018 16:13 Edit Adj Rpt	\$10,283.00 Edit Estimates	\$10,283.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	10 Oct 2018 16:07	10 Oct 2018 16:10 \$1,860.00	10 Oct 2018 16:10			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured: **GWEE LAY HIONG**, ID: 57232083B, Tel: +6597844895, Email: sylviagwee@gmail.com

Vehicle Reg. No.: **SJD2265A** Date of Loss: 05/10/2018 14:00 - :59
[126 Months and 22 Days From LTA Reg Date (Man Yr)]

Claim Type: **OD / 1201800012822** Policy/Cover Note No.: PNPV2017-00001781-01 (Comprehensive)
Excess: \$4600.00

Repairer: **ETHOZ Protect Pte Ltd (Bukit Batok)** 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51

Handling Insurer: **FWD Singapore Pte. Ltd. (HQ)** - Tel: 6727 5700 ... [Handled by **Josey Loh**]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **MARCUS CHUA**] ... [Final Rpt due 17/10/2018]

Driver/Custodian: **GWEE LAY HIONG (46 / Female)**, NRIC: 57232083B, Tel: +6597844895

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- FWD_SG (17/10/2018): **Dispute from insured**
- FWD_SG (12/10/2018): **Alert - Adj Mandate Approved (\$11076.00) - SJD2265A - Claim Handler: Josey Loh**
- FWD_SG (09/10/2018): **Alert - Adj Mandate Approved (\$8941.00) - SJD2265A - Claim Handler: Josey Loh**

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJD2265A (1201800012822)

OD

Oct 5 2018 2:00PM

[GWEE LAY HIONG]

ETHOZ Protect Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	05/10/18 18:21	Video - Accident [Linked Accident Report Documents]	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	08/10/18 15:00	Repairer Estimates	Load HTM	
2	10/10/18 16:10	Repairer Estimates Suppl. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/10/18 15:22	Adjuster Immediate Advice	Load HTM	
2	11/10/18 14:12	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/10/18 15:06	General View	Load JPG	☒
2	09/10/18 15:06	General View	Load JPG	☒
3	09/10/18 15:06	General View	Load JPG	☒
4	09/10/18 15:06	General View	Load JPG	☒
5	09/10/18 15:06	General View	Load JPG	☒
6	09/10/18 15:06	General View	Load JPG	☒
7	09/10/18 15:06	General View	Load JPG	☒
8	09/10/18 15:06	General View	Load JPG	☒
9	09/10/18 15:06	General View	Load JPG	☒
10	09/10/18 15:06	General View	Load JPG	☒
11	09/10/18 15:06	General View	Load JPG	☒
12	09/10/18 15:06	General View	Load JPG	☒
13	09/10/18 15:06	General View	Load JPG	☒
14	09/10/18 15:06	General View	Load JPG	☒
15	09/10/18 15:06	General View	Load JPG	☒
16	09/10/18 15:06	General View	Load JPG	☒
17	09/10/18 15:06	General View	Load JPG	☒
18	09/10/18 15:06	General View	Load JPG	☒
19	09/10/18 15:06	General View	Load JPG	☒
20	09/10/18 15:06	General View	Load JPG	☒
21	09/10/18 15:06	General View	Load JPG	☒
22	09/10/18 15:06	General View	Load JPG	☒
23	09/10/18 15:06	General View	Load JPG	☒
24	09/10/18 15:06	General View	Load JPG	☒
25	09/10/18 15:06	General View	Load JPG	☒
26	09/10/18 15:06	General View	Load JPG	☒
27	09/10/18 15:06	General View	Load JPG	☒
28	09/10/18 15:06	General View	Load JPG	☒

Video			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
29	09/10/18 15:06	General View	 Load JPG	☒
30	09/10/18 15:06	General View	 Load JPG	☒
31	09/10/18 15:06	General View	 Load JPG	☒
32	09/10/18 15:06	General View	 Load JPG	☒
33	09/10/18 15:06	General View	 Load JPG	☒
34	09/10/18 15:06	General View	 Load JPG	☒
35	09/10/18 15:06	General View	 Load JPG	☒
36	09/10/18 15:06	General View	 Load JPG	☒
37	09/10/18 15:06	General View	 Load JPG	☒
38	09/10/18 15:06	General View	 Load JPG	☒
39	09/10/18 15:06	General View	 Load JPG	☒
40	09/10/18 15:06	General View	 Load JPG	☒
41	09/10/18 15:06	General View	 Load JPG	☒
42	09/10/18 15:06	General View	 Load JPG	☒
43	09/10/18 15:06	General View	 Load JPG	☒
44	09/10/18 15:06	General View	 Load JPG	☒
45	09/10/18 15:06	General View	 Load JPG	☒
46	09/10/18 15:06	General View	 Load JPG	☒
47	09/10/18 15:06	General View	 Load JPG	☒
48	09/10/18 15:06	General View	 Load JPG	☒
49	09/10/18 15:06	General View	 Load JPG	☒
50	09/10/18 15:06	General View	 Load JPG	☒
51	09/10/18 15:06	General View	 Load JPG	☒
52	09/10/18 15:06	General View	 Load JPG	☒
53	09/10/18 15:06	General View	 Load JPG	☒
54	09/10/18 15:06	General View	 Load JPG	☒
55	09/10/18 15:06	General View	 Load JPG	☒
56	09/10/18 15:06	General View	 Load JPG	☒
57	09/10/18 15:06	General View	 Load JPG	☒
58	09/10/18 15:06	General View	 Load JPG	☒
59	09/10/18 15:06	General View	 Load JPG	☒
60	09/10/18 15:06	General View	 Load JPG	☒
61	09/10/18 15:06	General View	 Load JPG	☒
62	09/10/18 15:06	General View	 Load JPG	☒
63	09/10/18 15:06	General View	 Load JPG	☒
64	09/10/18 15:06	General View	 Load JPG	☒
65	09/10/18 15:06	General View	 Load JPG	☒
66	09/10/18 15:06	General View	 Load JPG	☒
67	09/10/18 15:06	General View	 Load JPG	☒
68	09/10/18 15:06	General View	 Load JPG	☒
69	09/10/18 15:06	General View	 Load JPG	☒
70	09/10/18 15:06	General View	 Load JPG	☒
71	09/10/18 15:06	General View	 Load JPG	☒
72	09/10/18 15:06	General View	 Load JPG	☒
73	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
74	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
75	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
76	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
77	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
78	11/10/18 20:03	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
79	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
80	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
81	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
82	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
83	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
84	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
85	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
86	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
87	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
88	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
89	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
90	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
91	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
92	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
93	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
94	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
95	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
96	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
97	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
98	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
99	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
100	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
101	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
102	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
103	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
104	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
105	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
106	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
107	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
108	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
109	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
110	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
111	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
112	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
113	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
114	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
115	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
116	11/10/18 20:03	Reinspection Photo	 Load JPG	☒
117	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
118	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
119	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
120	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
121	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
122	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
123	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
124	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
125	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
126	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
127	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
128	01/11/18 14:05	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
129	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
130	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
131	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
132	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
133	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
134	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
135	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
136	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
137	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
138	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
139	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
140	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
141	01/11/18 14:05	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	22/10/18 14:31	Supplier's Bill	 Load PDF	
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/10/18 15:06	MARK ESTIMATE	 Load PDF	
2	10/10/18 12:11	TP GIA REPORT.PDF	 Load PDF	
3	11/10/18 15:49	SUPPLEMENTARY.pdf	 Load PDF	
4	01/11/18 14:16	ESTIMATE & SUPPLEMENTARY MARKED.pdf	 Load PDF	
5	01/11/18 15:47	Parts Invoice	 Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	05/10/18 18:21	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	05/10/18 18:21	Accident Statement	 Load HTM	
2	10/10/18 09:41	Addendum Sheet	 Load TIF	
3	10/10/18 09:42	Accident Statement Addm. #1	 Load HTM	
Photos/ Images			3 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	05/10/18 18:09	Accident Photo	 Load JPG	☒
2	05/10/18 18:09	Accident Photo	 Load JPG	☒
3	05/10/18 18:09	Driving License	 Load JPG	☒
4	05/10/18 18:09	Accident Photo	 Load JPG	☒
5	05/10/18 18:09	Accident Photo	 Load JPG	☒
6	05/10/18 18:09	Accident Photo	 Load JPG	☒
7	05/10/18 18:09	Accident Photo	 Load JPG	☒
8	05/10/18 18:09	Accident Photo	 Load JPG	☒
9	05/10/18 18:09	Accident Photo	 Load JPG	☒
10	05/10/18 18:09	Accident Photo	 Load JPG	☒
11	05/10/18 18:09	Accident Photo	 Load JPG	☒
12	05/10/18 18:09	Accident Photo	 Load JPG	☒
13	05/10/18 18:09	Accident Photo	 Load JPG	☒
14	05/10/18 18:09	Accident Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
15	05/10/18 18:09	Accident Photo	 Load JPG	☒
16	05/10/18 18:09	Accident Photo	 Load JPG	☒
17	05/10/18 18:09	Accident Photo	 Load JPG	☒
18	05/10/18 18:09	Accident Photo	 Load JPG	☒
19	05/10/18 18:09	Accident Photo	 Load JPG	☒
20	05/10/18 18:09	Accident Photo	 Load JPG	☒
21	05/10/18 18:09	Accident Photo	 Load JPG	☒
22	05/10/18 18:21	Accident Photo	 Load JPG	☒
23	05/10/18 18:21	Accident Photo	 Load JPG	☒
24	05/10/18 18:21	Accident Photo	 Load JPG	☒
25	05/10/18 18:21	Accident Photo	 Load JPG	☒
26	05/10/18 18:21	Accident Photo	 Load JPG	☒
27	05/10/18 18:21	Accident Photo	 Load JPG	☒
28	05/10/18 18:21	Accident Photo	 Load JPG	☒
29	05/10/18 18:21	Accident Photo	 Load JPG	☒
30	05/10/18 18:21	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	05/10/18 18:08	INSURANCE CERT	 Load TIF	
2	05/10/18 18:08	DRIVER IC	 Load JPG	☒
3	10/10/18 09:42	Sketch Plan	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKX Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18018240/USD3E2

Date: 01/11/2018

REFERENCE

Insured/Claimant: GWEE LAY HIONG Policy No: PNPV2017-00001781-01
Date of Loss: 05/10/2018 Nature of Claim: OD Claim No: 1201800012822

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJD2265A**
Make & Model: HONDA STREAM, 1.8 (A) Engine No: R18A1765316
Reg. Date: 13/03/2008 (Man. Year: 2007) Chassis No: RN61058149
Colour: Silver Odometer: 298620 km
Engine Capacity: 1799 cc
Market Value/New Car Price: S\$54,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R15 Rear Tyre Size: 215/65 R15
Front Left Side: Sincera 6 mm Rear Left Side: Sincera 6 mm
Front Right Side: Sincera 6 mm Rear Right Side: Sincera 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,959.00	7,093.00	2,866.00	28.78
Miscellaneous Items	1,520.00	360.00	1,160.00	76.32
Labour	4,100.00	2,830.00	1,270.00	30.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,579.00	10,283.00	5,296.00	33.99
- Excess (\$\$)	0.00	600.00	-600.00	
(\$\$)	15,579.00	9,683.00	5,896.00	37.85
+ GST 7.00/7.00% (\$\$)	1,090.53	677.81	412.72	37.85
Nett Amount (\$\$)	16,669.53	10,360.81	6,308.72	37.85

INSPECTION

Date of Assignment: 08/10/2018 Present Location: ETHOZ Protect Pte Ltd (Bukit Batok)
Date Inspected: 09/10/2018 Inspected At: ETHOZ Protect Pte Ltd (Bukit Batok)
30 Bukit Batok Crescent
Singapore 658075

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2018)
Parts: M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJD2265A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deep Cut	680.00 F	*680.00 F
2	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	48.00 F	*- F
3	10		*REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 F
4	1		*REAR FENDER LH	Repair	900.00 F	*- F
5	1		*REAR FENDER QUARTER GLASS MOULDING LH	Not Necessary	90.00 F	*- F
6	1		*REAR DOOR LH	Badly Dented	850.00 F	*850.00 F
7	1		*REAR DOOR UPPER HINGE LH	Not Necessary	65.00 F	*- F
8	1		*REAR DOOR LOWER HINGE LH	Not Necessary	65.00 F	*- F
9	1		*REAR DOOR WEATHER STRIP LH	Necessary	160.00 F	*160.00 F
10	1		*REAR DOOR INNER LOCK LH	Not Necessary	230.00 F	*- F
11	1		*REAR DOOR FRAME STICKER LH	Necessary	60.00 F	*60.00 F
12	1		*ROCKER PANEL LH	Repair	350.00 F	*- F
13	1		*CENTRE DOOR PILLAR LH (NPA)	Repair	-	-
14	1		*FRONT DOOR LH	Badly Dented	900.00 F	*900.00 F
15	1		*FRONT DOOR UPPER HINGE LH	Not Necessary	65.00 F	*- F
16	1		*FRONT DOOR LOWER HINGE LH	Not Necessary	65.00 F	*- F
17	1		*FRONT DOOR WEATHER STRIP LH	Necessary	160.00 F	*160.00 F
18	1		*FRONT DOOR INNER LOCK LH	Not Necessary	230.00 F	*- F
19	1		*FRONT DOOR FRAME STICKER LH	Necessary	75.00 F	*75.00 F
20	1		*FRONT FENDER LH	Badly Dented	550.00 F	*550.00 F
21	1		*FRONT FENDER SIGNAL LAMP LH	Cracked	38.00 F	*38.00 F
22	1		*FRONT FENDER INNER SHIELD LH	Torn	138.00 F	*135.00 F
23	10		*FRONT FENDER INNER SHIELD CLIPS	Necessary	40.00 F	*40.00 F
24	1		*FRONT BUMPER	Deformed / Warped	750.00 F	*750.00 F
25	1		*FRONT BUMPER SIDE RETAINER LH	Bent	55.00 F	*55.00 F
26	10		*FRONT BUMPER CLIPS	Necessary	40.00 F	*40.00 F
27	1		*FRONT SHOCK ABSORBER LH	Bent	330.00 F	*330.00 F
28	1		*FRONT KNUCKLE ARM LH	Bent	300.00 F	*300.00 F
29	1		*FRONT KNUCKLE BEARING LH	Necessary	95.00 F	*95.00 F
30	1		*FRONT WHEEL HUB LH	Bent	185.00 F	*185.00 F
31	1		*FRONT LOWER ARM LH	Bent	350.00 F	*350.00 F
32	1		*FRONT STABILIZER LINK LH	Not Necessary	105.00 F	*- F
33	1		*FRONT TIE ROD END LH	Bent	90.00 F	*90.00 F
Supplementary #1						
34	1		*REAR WINDOW OUTER MOULDING LH	Necessary	135.00 F	*135.00 F
35	1		*REAR POWER WINDOW REGULATOR LH	Shorted / Bent	400.00 F	*400.00 F
36	1		*FRONT WINDOW OUTER MOULDING LH	Bent	135.00 F	*135.00 F
37	1		*FRONT POWER WINDOW REGULATOR LH	Shorted / Bent	400.00 F	*400.00 F
38	1		*HEADLAMP LH	Not Necessary	650.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*FRONT RACK END LH	Bent	140.00 F	*140.00 F
F=Franchise part.						
Total Parts (S\$)					9,959.00	7,093.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT SPORT RIM LH 15 (DENTED / BENT)	550.00	180.00
2	1	FRONT TYRE LH (FALKEN) 205/65R15 (SERVICEABLE)	180.00	0.00
3	1	REAR QUARTER GLASS SEALANT LH (NOT NECESSARY)	60.00	0.00
4	1	REAR SPORT RIM LH 15 (CUT)	550.00	180.00
5	1	REAR TYRE LH (FALKEN) 205/65R15 (SERVICEABLE)	180.00	0.00
Sub Total (S\$)			1,520.00	360.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	1,500.00	1,100.00
2	TO REMOVE & INSTALL LHR FENDER QUARTER GLASS	New	100.00	0.00
3	TO REMOVE & INSTALL SEATS,CAPETS & TRIMS TO FACILITATE REPAIR	New	200.00	60.00
4	TO REMOVE & INSTALL LHR DOOR COMPONENTS	New	80.00	60.00
5	TO REMOVE & INSTALL LHF DOOR COMPONENTS	New	80.00	60.00
6	TO REMOVE & INSTALL LHR SPORT RIM INCLUDING TYRE BALANCING	New	20.00	0.00
7	TO REMOVE & INSTALL LHF SPORT RIM INCLUDING TYRE BALANCING	New	20.00	0.00
8	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	New	70.00	70.00
9	TO REMOVE & INSTALL LHF UNDERCARRIAGE PARTS	New	200.00	150.00
10	TO CONDUCT ANTI RUST COATING ON AFFECTED AREAS	New	100.00	0.00
11	TO CHECK & RECONNECT ALL NECESSARY WIRINGS	New	30.00	30.00
12	TO SPRAY PAINT ON AFFECTED AREAS	New	1,700.00	1,300.00
Gross Labour Cost (S\$)			4,100.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >