



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18018257/Asd3e2

ACCIDENT CLAIM SECTION(SINGAPORE POLICE
FORCE)1 MOUNT PLEASANT RD BLK8 OLD
POLICE ACADEMYSINGAPORE 298333

Date : 03-12-2018



ATTN : FRANKIE THAY

Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 705Y	Veh. Inspected	SKV 4455Z
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/119	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	09/10/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA3 1.6L HB	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JM6BL10Z1A0169975	Colour	RED
Odometer	133905	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R17	GOODYEAR	6 mm
L/H Front Tyre	205/50 R17	GOODYEAR	6 mm
R/H Rear Tyre	205/50 R17	GOODYEAR	6 mm
L/H Rear Tyre	205/50 R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/10/2018	Inspection Date	09/10/2018
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------