












































PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

• Report No: 0441-18-N51

01 August 2018

ACCIDENT VEHICLE SURVEY REPORT

Kan Chong Ho
10 Martaban Road #02-01
Singapore 328668

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SLA1844C	<i>Odometer:</i>	010277km
<i>Make & Model:</i>	Honda City 1.5 CVT	<i>Colour:</i>	Red
<i>Chassis number:</i>	MRHGM6660GP000448	<i>Date of accident:</i>	09/11/2017
<i>Year of Regn.:</i>	24/02/2016	<i>Date inspected:</i>	13/11/2017
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	23/11/2017

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

