

ASS. REC. BY:

REF:

CS/AG18018267/Ksd3

Special Instruction:

Surveyor
Munnen

Kenneth

ASSIGNMENT (Office)

From (Person):

Azlan Syazairidin

of

AG

Date/Time 8/10/18

Estimated Cost:

Bill to:

OD ☒ TP + WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 6185Y

Insured:

SGL 609Z

at Workshop m/s

Massive trading

Tel:

9108 2728

of

Blk 5038 Amk Ind. Park 2 #01-405

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 8/10/18

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 11:20am 8/10/18

Person Contacted:

Anthony

Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJR 6185Y - CS/FCI18010673/Ksd3n2 DOA: 10/6/18
	SGL 609Z - X
16/10/18	Confirmed Hs \$2,500/- @ 5 days with Kenneth (\$3,592.07 incl - 59%)

ASS. REC. BY:

REF: 1161

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STR 6185 Y

Yr Regn:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Vios

c.c.

1.6 PZ

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

217416

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR05314Y930517258

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: MAXXIS 195/60R15

R: K90

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

3

mm

Rear

R/Bal.

2

mm

L/Bal.

3

mm

L/Bal.

2

mm

D.O.A.

1/18

D.O.I.

9/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

110 File pass to Catherine

RECEIVED 16 OCT 2018

Date/Time, File Pass to?

16/10/18



Prell. Report



Final Report

1)

typist

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS \$

Fixtore

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

2,500/- H/S

- Pre repair inspection request - SJR6185Y VS SGL609Z (OI) DOA: 08/10/2018

From: Azlan, Syazairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Manesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi
Sent: 8/10/2018 3:57:18 PM
Attachments: 20181008162541628.pdf

Hi,

Please refer to the enclosed request from **Teo Keng Siang LLC**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours.

If you have any queries/concerns, please let us know.

Kindly assist to assign **Kenneth Kong** as **Single Joint Expert** as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Janice Kee [mailto:janice.kee@ksteoptr.com]

Sent: Monday, October 08, 2018 3:51 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Manesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Anthony Cheong

Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGL609Z AND SJR6185Y ON 08/10/2018

Dear Sir

Our client has agree to the usage of Mr Kenneth Kong from LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the Pre-Repair Survey.

Kindly proceed to engage Mr Kenneth Kong from LKK Auto Consultants Pte Ltd to perform the said Pre-Repair Survey in accordance to the NIMA Protocol.

Thank you.

Regards,
Janice Kee
c/o Teo Keng Siang LLC
111 North Bridge Road,
#29-07/08 Peninsula Plaza,
Singapore 179098
Tel: 6333 4222 Fax: 6333 5676

2018-10-08 15:24 GMT+08:00 Azlan, Syazairdina <Syazairdina.Azlan@aig.com>:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการใช้ความปลอดภัยของข้อมูลเพื่อเข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์แนบ

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-10-15 15:24 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual or entity named in the message. If you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina Azlan@aig.com

To: janice.kee@ksteoptr.com

Cc: Andy-SY.Fong@aig.com, Lee-

Ying.Chin@aig.com, NoorMarless.AbuKassim@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, yakeshi.chan@aig.com

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGL609Z AND SJR6185Y ON 08/10/2018

Date: Mon, 8 Oct 2018 07:23:57 +0000

Without Prejudice

Your Reference: TKSF/M492-ACC-40973.18/sf (mc)

Our Reference: SGL609Z

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

Teo Keng Siang LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098
ROC: 201510228C GST Reg No.: 201510228C

Tel: 6333 4222 Fax: 6333 5676 / 5688

Email: KSTEOCO@singnet.com.sg

(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)

Our Ref : TKSF/M492-ACC-40973.18/sf(mc)
Your Ref : SGL 609 Z
Date : 8 October 2018

Secretary in charge: Janice

Tel : 6333 4222 (ext 60)

Fax : 6333 5676 / 6333 5688

Email : janice.kee@ksteoptr.com

To: AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#07-16
Singapore 079120
Attn: Motor Claims Dept

WITHOUT PREJUDICE

BY PDX# 8181 & FAX 6835 7416 ONLY

Cc: Teo Kah Sze (Owner & Driver)
21 Tampines Street 34
#09-03
Singapore 529232

BY POST ONLY

Dear Sirs

RE: ACCIDENT INVOLVING SJR 6185 Y / SGL 609 Z ON 8/10/18 ALONG TAMPINES ST 34 TOWARDS TAMPINES AVE 7

We are instructed by **Chubby Limo** to notify you of a road traffic accident on 8/10/18 at about 07:00 hours at **ALONG TAMPINES ST 34 TOWARDS TAMPINES AVE 7** involving our client's vehicle registration number **SJR 6185 Y** and vehicle registration number **SGL 609 Z** driven by you at the material time. A copy of our client's Singapore accident statement is enclosed. Kindly let us have a copy your Singapore accident statement report on an urgent basis.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle **SJR 6185 Y** is now at the following workshop:-

Massive Trading & Auto
Blk 5038 Ang Mo Kio Industrial Park 2
#01-405
Singapore 569541
Contact: 9108 2728 Anthony

Yours faithfully,


M/s Teo Keng Siang LLC
encs

Teo Keng Siang
LL.M(Singapore),
LL.B (Hons) (Singapore)

****Survey was conducted by:-**

Name of Surveyor:

Date of Survey:

Time of Survey:

Signature

Wong Yong Sheng, Kenneth
LL.B (Hons) University of Bristol

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/10/2018 10:47
Date Of Accident	08/10/2018 07:00
Exact Location Of Accident	TAMPINES ST 34 TWDS TAMPINES AVE 7
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR6185Y
Insured/Policyholder	
Name Of Registered Owner	CHUBBY LIMO
Co Reg No	53342590E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91010105
Alternative Phone No	OFFICE-91010105

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091196338-01
Cover Note Number	

Driver

Name of Driver	ZYE
NRIC No	S7222879J
Date Of Birth	09/07/1972
Occupation	OUTDOOR
Date Of Driving Pass	04/03/1998
Driving Experience	20 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91010105
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 106 BISHAN ST 12 #04-218
Postcode	570106
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN - CIRCUMSTANCES OF THE ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGL609Z
Vehicle Make/Model/Colour	AUDI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TEO KAH SZE
NRIC/Passport Number	S7604527E
Contact Number	97462982
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Center Personnel's Signature
Name
NIC/PIN No:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 08/10/2018 @ ard 0700hrs, I was travelling along Tampines St 34 towards Ave 7. Just before the junction with Ave 7, I slowed down my vehicle due to heavy traffic. Suddenly, I felt an impact from the rear of my vehicle. I got out of my vehicle and realised that veh B (SG2609Z) had collided into my vehicle rear portion.

DECLARATION BY LING

(We declare that the above particulars are true in every respect.)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

07/09

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Chubby Limo
Blk 106 Bishan St 12
#04-218
Singapore 570106

Not Authenticated
11 Lys & 250 dr 5 days
Museum After Point

Vehicle No : SJR 6185 Y
Make : Toyota Vios
Year : 2009

Estimate Cost Of Repair

S. Nett Item

1 pc	Rear reverse sensor
1 pc	Rear no plate
10 pcs	Rear bumper clip

Labour Charges

Remove/renew the above parts including knocking, welding & cutting

balance c/f

\$1,000.00
<u>\$4,747.07</u>

6001

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

	Shog	\$200.00	✓
	Red	\$40.00	✓
\$3.00	Men	\$30.00	✓
		<u>\$270.00</u>	

SJR 6185 Y

balance b/f \$4,747.07

Labour Charges

To putty & spray paint on rear accident affected portion.

\$1,000.00

Check/reconnect wiring.

\$45.00

To spray anti rust on accident affected portion.

\$180.00

Remove/refit rear boot upholstery to facilitate repair

\$120.00

Total

\$6,092.07

6001

201

601

601

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Oct 2018 Edit Reg		08 Oct 2018 00:00 Edit Adj Rpt	S\$2,500.00 Edit Estimates	S\$2,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TEO KAH SZE, ID: S7604527E								
Main Claimant:	CHUBBY LIMO, Co. Reg. No.: 53342590E								
Vehicle Reg. No.:	SJR6185Y	Date of Loss:	08/10/2018 07:00 - :59 [111 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3966897654SG	Policy/Cover Note No.:	2100445382 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGL609Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Massive Trading & Auto () Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2, 569541 Ang Mo Kio - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 18/10/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (10/10/2018): No Policy Found - AIG_SG (10/10/2018): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJR6185Y (3966897654SG)
[SGL609Z]
TP
CHUBBY LIMO
Oct 8 2018 7:00AM
[TEO KAH SZE]
Massive Trading & Auto

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	16/10/18 11:21	General View														Load JPG	☒	
2	16/10/18 11:21	General View														Load JPG	☒	
3	16/10/18 11:21	General View														Load JPG	☒	
4	16/10/18 11:21	General View														Load JPG	☒	
5	16/10/18 11:21	General View														Load JPG	☒	
6	16/10/18 11:21	General View														Load JPG	☒	
7	16/10/18 11:21	General View														Load JPG	☒	
8	16/10/18 11:21	General View														Load JPG	☒	
9	16/10/18 11:21	General View														Load JPG	☒	
10	16/10/18 11:21	General View														Load JPG	☒	
11	16/10/18 11:21	General View														Load JPG	☒	
12	16/10/18 11:21	General View														Load JPG	☒	
13	16/10/18 11:21	General View														Load JPG	☒	
14	16/10/18 11:21	General View														Load JPG	☒	
15	16/10/18 11:21	Odometer Reading														Load JPG	☒	
16	16/10/18 11:21	Chassis Number														Load JPG	☒	
17	16/10/18 11:22	Reinspection Photo														Load JPG	☒	
18	16/10/18 11:22	Reinspection Photo														Load JPG	☒	
19	16/10/18 11:22	Reinspection Photo														Load JPG	☒	
20	16/10/18 11:22	Reinspection Photo														Load JPG	☒	
21	16/10/18 11:22	Reinspection Photo														Load JPG	☒	
22	16/10/18 11:22	Reinspection Photo														Load JPG	☒	
Documentation															1 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	12/10/18 12:06	TP GIA REPORT.pdf														Load PDF		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)														Thumbnail	Print	
1	15/10/18 11:19	OI GIA REPORT														Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18018267/KSD3Q2

Date: 23/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100445382
 Claimant Vehicle No: SJR6185Y Insured Vehicle No: SGL609Z
 Date of Loss: 08/10/2018 Nature of Claim: TP Claim No: 3966897654SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR6185Y
 Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 1NZX921426
 Reg. Date: 01/07/2009 (Man. Year: 2009) Chassis No: MR053HY9305117258
 Colour: Metallic Silver Odometer: 217416 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
 Front Left Side: Maxxis 3 mm Rear Left Side: LEAO 2 mm
 Front Right Side: Maxxis 3 mm Rear Right Side: LEAO 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,747.08	1,850.99	1,896.09	50.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,345.00	1,340.00	1,005.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,092.08	3,190.99	2,901.09	47.62
Approved Total (Overridden) (\$\$)		2,500.00		
Nett Amount (\$\$)	6,092.08	2,500.00	3,592.08	58.96

INSPECTION

Date of Assignment: 08/10/2018
 Date Inspected: 09/10/2018 Inspected At: Massive Trading & Auto
 Blk 5038 #01-405, Ang Mo Kio Industrial
 Pk 2
 Singapore 569541
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	649.10 FL	*- FL
2	1		*REAR BOOT LID INNER LOCK	Dented	165.70 FL	*165.70 FL
3	1		*REAR BOOT LID EMBLEM LOGO	Necessary	55.80 FL	*55.80 FL
4	1		*REAR BOOT LID EMBLEM VIOS	Necessary	53.20 FL	*53.20 FL
5	1		*REAR BOOT LID EMBLEM J	Necessary	35.10 FL	*35.10 FL
6	1		*REAR BOOT RUBBER (50%)	Cut	164.63 FS	*109.75 FS
7	1		*REAR TAIL-LAMP ASSY	N/S Mtg Cracked	709.80 FL	*354.90 FL
8	2		*REAR TAIL-LAMP PANEL	Repair	249.60 FL	*- FL
9	1		*REAR END PANEL	Bent	587.20 FL	*587.20 FL
10	1		*REAR END PANEL INNER GARNISH	Mtg Distorted	129.80 FL	*129.80 FL
11	1		*REAR SPARE TYRE PANEL	Repair	584.65 FL	*- FL
12	1		*REAR SPARE TYRE COVER BOARD	Serviceable	295.10 FL	*- FL
13	1		*REAR BUMPER	Buckled	429.55 FL	*429.55 FL
14	2		*REAR BUMPER SIDE RETAINER	Distorted	150.40 FL	*150.40 FL
15	2		*REAR BUMPER BRACKET	Repair	171.00 FL	*- FL
16	2		*REAR BUMPER REFLECTOR	Serviceable	150.60 FL	*- FL
17	1		*REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
18	1		*REAR NO PLATE	Dented	40.00 FS	*40.00 FS
19	10		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	4,851.23	2,341.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,104.15	490.41
Total Parts (\$\$)	3,747.08	1,850.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING	New	1,000.00	600.00
2	TO PUTTY & SPRAY PAINT ON REAR ACCIDENT AFFECTED PORTION	New	1,000.00	600.00
3	CHECK & RECONNECT WIRING	New	45.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	180.00	60.00
5	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00	60.00
Gross Labour Cost (S\$)			2,345.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >