

ASS. REC. BY:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Munir

Jence Goh

of

ICS

Date/Time:

8/10/18 @ 3:58pm

Estimated Cost:

OD / TR / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGC1044T

Insured:

8KG19E

at Workshop m/s

TK Motor workshop

Tel:

9627 3323

Policy No:

1 Kaki Bkt Ave 6 #02-56

MPC1FA00555200

Claim No:

DMPC1800381H/JG

Sum Insured:

Excess:

D.O.A. 05/10/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

(wp)

Date/Time: 3.37pm @ 9/10/18

Person Contacted:

Kenny

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SGC1044T - NA/INC18018133/K4	DOA: 5/10/18
	8KG19E - NA/INC18018133/K4	DOA: 5/10/18
10/10/18	vehicle still not In. (Kenny)	

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: _____

SGC1044T.

Yr Regn: _____

2006 Jan.

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Mazda 3

c.c

1598

Colour: _____

White

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

159502

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JM6BK106100182126.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

205/55R16

R: _____

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. _____

06

mm

R/Bal. _____

06

mm

L/Bal. _____

06

mm

L/Bal. _____

06

mm

D.O.A. _____

D.O.I. _____

22/10/18.

Survey held at _____

T.K.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____

Action / Instruction

TP ECICS.

MV: 15.5K
PV: 12.5K
Nett: 3.5K 3K

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: _____

3

1)

☐

Final Report

Resurvey No. of Trip: _____

1

Survey Fee: _____

Transportation: _____

Date/Time, File Return to?

2)

Add Fee: _____

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + PS. \$

) Photos

) Others

Report Format: _____

TP

Lump Sum / I.B.I. (\$ 2,000)

TOTAL

10

Catherine Chong (LKK Auto)

From: motorsurvey <motorsurvey@ecics.com.sg>
Sent: Monday, 8 October, 2018 3:58 PM
To: Kuru & Co; 'assignments'
Cc: motorsurvey
Subject: RE: Our Ref: L18.1431.AT//Your Ref: SKG 19E//PRS

Hi Anne

Thank you for your email.
We will appoint LKK for the TP survey.

Aside to LKK

Please assist to arrange TP survey.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Monday, 8 October, 2018 3:45 PM
To: motorsurvey
Subject: Re: Our Ref: L18.1431.AT//Your Ref: SKG 19E//PRS

Hi Janice

Our client is agreeable to the following surveyor as the SJE: **LKK Auto Consultants Pte Ltd**

Please arrange for your surveyor to survey our client's vehicle at the following address:

TK MOTOR WORKSHOP
1 Kaki Bukit Ave 6
#02-56 AutoBay@Kaki Bukit
Singapore 417883
Contact: 9627 3323/Kenny

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey.

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards
Anne
Kuru & Co

150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Monday, 8 October 2018, 3:29:21 PM SGT, motorsurvey <motorsurvey@ecics.com.sg> wrote:

WITHOUT PREJUDICE

Dear Anne

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,

Janice Goh

Claims Division

DID: +65 6303 0182

FAX: +65 6338 9267

ECICS Limited

10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to
motorsurvey@ecics.com.sg

directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Monday, 8 October, 2018 2:24 PM
To: motorsurvey
Subject: Our Ref: L.18.1431.AT//Your Ref: SKG 19E//PRS

Dear Sirs

ACCIDENT INVOLVING SGC 1044T & SKG 19E ON 05.10.2018

ALONG STEVENS ROAD TOWARDS ORCHARD ROAD

NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **Auto Trend Leasing Enterprise**, whose vehicle registration number **SGC 1044T** was damaged in the above accident.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Anne

Kuru & Co

150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/10/2018 16:47
Date Of Accident	05/10/2018 19:00
Exact Location Of Accident	STEVENS ROAD TWDS ORCHARD ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGC1044T
Insured/Policyholder	
Name Of Registered Owner	AUTOTREND LEASING ENTERPRISE
Co Reg No	53363236J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94509218
Alternative Phone No	OFFICE-94509218

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA 3 LUX
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093812308-01
Cover Note Number	

Driver

Name of Driver	TAN SIONG HOCK (CHEN XIANGFU)
NRIC No	S8111476E
Date Of Birth	26/04/1981
Occupation	OUTDOOR
Date Of Driving Pass	28/04/2014
Driving Experience	4 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91005557
Fax Number	
Contact Number	OTHERS-91005557
EEmail Address	NOEMAIL

Address	BLK 672 JALAN DAMAI #07-25
Postcode	410672
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKG19E
Vehicle Make/Model/Colour	TOYOTA LEXUS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG JIAN HAO JUSTIN
NRIC/Passport Number	S9326051A
Contact Number	91181561
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SGC1044T

IMPORTANT NOTICE

1. Please report the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and the Insured Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind the policy.
4. The issue and acceptance of the Family Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the Traffic Accident Claim Centre established by the General Insurance Association of Singapore (GIACC) for archiving and release of the report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of the report at the Centre and the copies of the report being made available as stated.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) my insurer, my workshop and the General Insurance Association of Singapore (GIACC) may be permitted to collect, use, disclose and/or process my personal data and/or information set out in this Report and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose such Personal Information to all person(s) who have insured vehicle(s) involved in the accident (all insured(s) who have insured vehicle(s) involved in the accident shall be collectively referred to as the "Insurers"), the Insurer's Insurance firm, the Ministry Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claim;

(iii) carrying out and/or dealing with my instructions or suspending, varying and/or by me;

(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of confidential data about me relating to delivery of the services, and/or on the external cover of correspondence packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all person(s) who have insured vehicle(s) involved in the accident and the Insurers' Insurance firm, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may be disclosed by any of the Insurers and/or GIACC to the relevant authority/agency/profession or against (including their Insurance firm), which may be outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Policing Centre Personnel


6/10/2018

Sketch Plan

(A) SGC1044T

Stevens Road

(B) SKG19E



Toward Orchard Road

Describe Circumstances of the Accident

On 5/10/2018 at about 19:04 hrs I was travelling along Stevens Road toward making a legal 'U' turn toward Scotts road to fetch passenger. The traffic was jammed. Suddenly a vehicle SKG 19F hit onto my vehicle SGC 1044T rear portion. After the accident the driver of SKG 19F admitted it was his fault and agreed to make a third party claim under SKG 19F insurance policy. My vehicle SGC 1044T have a video footage.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

6/10/2018

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	3236J
Vehicle Details	
Vehicle No.:	SGC1044T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Oct 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA 3 LUX
Primary Colour:	White
Manufacturing Year:	2005
Engine No.:	Z6402418
Chassis No.:	JM6BK106100182126
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$15,784.00
Original Registration Date:	09 Jan 2006
First Registration Date:	09 Jan 2006
Transfer Count:	1
Actual ARF Paid:	\$17,363.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$28,416.00
COE Rebate Amount:	\$12,451.00
Total Rebate Amount:	\$12,451.00
Message	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Oct 2018

OK



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Toyota Vios 1.5A G Model (New COE).

High Specs G Model. Low Mileage. Fuel Fuel Consumption. Well Maintained. Direct Owner StarAd

STAR AD

KA-HUP

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997 [View our cars](#)

Browse by Category [Save Search](#) [Print](#) Sort by Date Posted 20 results/page

8 vehicles | **Search** [Advanced Search](#) [Search](#) [View All](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	mazda 3	Any	Any	> 10 year(s) old	Any	Any	Any	Available
------------------	---------	-----	-----	------------------	-----	-----	-----	-----------



☐ **Mazda 323 1.3M (COE till 01/2019)** \$3,500 N.A. 05-Jan-1999 1,323 cc - Sedan Available

Engine Have Been Overhauled And Coe Can Be Renew For Another 10 Year. Vehicle In Good Condition. Feel Free To View.

★ Posted: 17-Sep-2018 Tags: 1999 Mazda 323, 1999 mazda 323, Mazda 323, mazda 323, Mazda 323, Used Mazda

DIRECT OWNER



☐ **Mazda 3 1.6A SP Luxury (COE till 01/2021)** \$16,888 \$7,410 /yr 20-Feb-2006 1,598 cc 159,600 km Sedan Available

We Are The COE Specialists, No Gimmicks, Honest Dealing. 2 Owner Car With Low Mileage Clocked, Car In Good Condition Interior And Exterior, No Repairs Needed. High Loan With \$2500 Down Payment Drive A...

★ Posted: 21-Sep-2018 Tags: 2006 Mazda 3, 2006 mazda 3, Mazda 3, mazda 3, Mazda 3, Used Mazda

PREMIUM AD



☐ **Mazda 3 GT (COE till 06/2021)** \$15,800 \$5,880 /yr 29-Jun-2006 1,598 cc - Hatchback Available

Mazda 3 GT Edition! \$0 Down Payment Full Loan Available At \$700 Plus Monthly x 24 Months! In-House Loan Or Bank Loan Available! No Need Guarantor Or Minimum Income! 5 Pass, EP Or LTV Pass Welcome To L...

68 Motor Trading

★ Posted: 18-Oct-2018 Tags: 2006 Mazda 3, 2006 mazda 3, Mazda 3, mazda 3, Mazda 3, Used Mazda



☐ **Mazda 3 1.6A (COE till 05/2021)** \$16,199 \$6,210 /yr 06-Jul-2006 1,598 cc - Sedan Available

1 & Only Full Body Kits Mazda 3, Black Interior, Sporty Look, Well Maintain By Owner, High Loan Available, Grab It Before It Gone, Call Now To View.

★ Posted: 04-Oct-2018 Tags: 2006 Mazda 3, 2006 mazda 3, Mazda 3, mazda 3, Mazda 3, Used Mazda

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ **Mazda 3 1.6A SP (COE till 07/2027)** \$49,800 \$5,670 /yr 31-Jul-2007 1,598 cc 89,000 km Sedan Available

\$0 Down Payment And Monthly \$728 Only! High P/Q Paid! 9 Years Of COE To Go With Option To Scrap For COE Rebate! 1 Owner Only! Very Low Mileage Of 89k Km! Excellent Condition! Low Depreciation! Safe Bu...

Don Motoring

★ Posted: 29-Oct-2018 Tags: 2007 Mazda 3, 2007 mazda 3, Mazda 3, mazda 3, Mazda 3, Used Mazda

PREMIUM AD



☐ **Mazda 3 1.6A SP (OPC) (COE till 10/2022)** \$21,800 \$5,500 /yr 08-Oct-2007 1,598 cc - Sedan Available

Selling Slightly Above Scrap, Low Depreciation, Low Risk, Low Down Payment, Well Maintained, Wear & Tear Replaced, High Loan Available, Do Not Miss, Call Now.

★ Posted: 04-Oct-2018 Tags: 2007 Mazda 3, 2007 mazda 3, Mazda 3, mazda 3, Mazda 3, Used Mazda

SHORTLISTED HISTORY

[Compare](#)

☐ **Mazda 3 1.6A SP (COE till 02/2023)** \$22,999 \$5,280 /yr 01-Apr-2008 1,598 cc 163,000 km Sedan Available

1 Owner, Just Arrival! Sporty Red In Black Color Mazda 3 SP Edition! Very Well Maintained By Careful Owner And 100% Accident Free. Stable Good

T K MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 96273323 FAX: 68442641
CO. REG NO :53049097L

Third party: ECICS Ins.

AUTOTREND LEASING ENTERPRISE
BLK 672 JALAN DAMAI #07-25
SINGAPORE 410672

TPECICS
Tanice

DATE: 31/10/2018

Lump Sum: 3 day

DEAR SIR

By Hand: 28/11/18

ACCIDENT DATE: 05/10/2018

ESTIMATE COST OF REPAIRS BILL TO MAZDA 3 LUX CAR NO:SGC1044T

1 PC REAR BOOTLID	Repair		S\$ 670.50	670.50	X
1 PC REAR BOOTLID RUBBER	new		293.40	293.40	X
1 PC REAR BOOTLID R/H REFLECTOR LAMP	new		624.40	624.40	X
3 PC REAR BOOTLID EMBLEM	new	191.60	191.60	191.60	X
1 PC REAR R/H TAILLAMP	cracked	683.40	659.80	659.80	X
1 PC REAR BUMPER	Replaced	832	626.20	626.20	X
2 PC REAR BUMPER SIDE RETAINER	new		129.40	129.40	70
8 PC REAR BUMPER CLIP	new	45	30.40	30.40	X
2 PC REAR BUMPER REFLECTOR	cracked	126	74.80	74.80	X
1 SET REAR BUMPER REVERSE SENSOR	2nd	1770.80	200.00	200.00	S/NETT
1 PC REAR BUMPER REINFORCEMENT BEAM	new		357.20	357.20	X
1 PC REAR END PANEL	Repair	1416.64	497.10	497.10	X
1 PC REAR END PANEL GARNISH	new		171.60	171.60	X
1 PC REAR NO. PLATE	cracked		30.00	30.00	S/NETT
2 PC REAR NO. PLATE LAMP	cracked	92.40	92.40	92.40	X
2 PC REAR BUMPER SIDE CLIP	new	25.60	25.60	25.60	X

S.W: 230.41

TO CHECK WRING .

TO SPRAY PAINTING (PEARL WHITE)

TO REMOVE & REFIX REAR INTERIOR UPHOLSTY.

TO LABOUR CHARGE FOR PANEL BEATING, WELDING, REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC.

TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION.

TO MEASURE, DRILL THE REPLACED BUMPER, POSITION & REINSTALL REAR

REAR REVERSE SENSOR, CONTROL UNIT, CHECK & TEST FOR FUNCTIONING.

50.00	50.00	30
650.00	650.00	300
80.00	80.00	40
500.00	500.00	300
80.00	80.00	X
80.00	80.00	50

TOTAL S\$

6,114.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2566.64

4/5: 2k

08 Days

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jan 2019 17:25 Edit Reg		08 Oct 2018 00:00 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -, Email: EMAIL@YAHOO.COM		
Main Claimant:	-		
Vehicle Reg. No.:	SGC1044T	Date of Loss:	05/10/2018 19:00 - :59 [152 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / DMPC1800381H/JG	Policy/Cover Note No.:	MPC17A00555200
Vehicle Reg. No. (Insured):	SKG19E	Policy No. (Claimant):	
		Excess:	
Repairer:	Tk Motor (HQ) BLK 1 KAKI BUKIT AVE 6 #02-56 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 6746 6896		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 18/10/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGC1044T (DMPC1800381H/JG)

[SKG19E]

TP

-

Oct 5 2018 7:00PM



















[-]

Tk Motor

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#)
[View in Browser](#)

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page	Thumbnail	Print
1	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
2	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
3	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
4	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
5	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
6	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
7	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
8	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
9	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
10	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
11	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
12	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
13	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
14	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
15	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
16	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
17	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
18	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
19	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
20	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
21	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
22	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
23	28/01/19 10:41	General View		Load JPG	<input checked="" type="checkbox"/>
24	28/01/19 10:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
25	28/01/19 10:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	28/01/19 10:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	28/01/19 10:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
28	28/01/19 10:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
29	28/01/19 10:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
30	28/01/19 10:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
31	28/01/19 10:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	28/01/19 10:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
33	28/01/19 10:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
34	28/01/19 10:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	28/01/19 10:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
37	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
38	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
39	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
40	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
41	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
42	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
43	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
44	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
45	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
46	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
47	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
48	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
49	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
50	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
51	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
52	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
53	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
54	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
55	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
56	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
57	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
58	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
59	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
60	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
61	28/01/19 10:42	Reinspection Photo	 Load JPG	✓
62	28/01/19 10:43	Reinspection Photo	 Load JPG	✓
63	28/01/19 10:43	Reinspection Photo	 Load JPG	✓
64	28/01/19 10:43	Reinspection Photo	 Load JPG	✓
65	28/01/19 10:43	Reinspection Photo	 Load JPG	✓
66	28/01/19 10:43	Reinspection Photo	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18018273/ACD3S2

Date: 28/01/2019

REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC17A00555200
 Claimant Vehicle No: SGC1044T Insured Vehicle No: SKG19E
 Date of Loss: 05/10/2018 Nature of Claim: TP Claim No: DMPC1800381H/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGC1044T**
 Make & Model: MAZDA 3, 1.6 LUX (A) Engine No: Z6402418
 Reg. Date: 09/01/2006 (Man. Year: 2005) Chassis No: JM6BK106100182126
 Colour: White Odometer: 159502 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,674.40	1,646.64	3,027.76	64.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,440.00	920.00	520.00	36.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,114.40	2,566.64	3,547.76	58.02
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	6,114.40	2,000.00	4,114.40	67.29

INSPECTION

Date of Assignment: 08/10/2018
 Date Inspected: 22/10/2018 Inspected At: Tk Motor (HQ)
 Estimated Period of Repair: 3.0 days BLK 1 KAKI BUKIT AVE 6 #02-56 AUTOBAY @ KAKI BUKIT
 Singapore 417883

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2019)
Parts:	143	MAZDA 3 1.6 LUX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGC1044T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Repair	670.50 F	*- FL
2	1		*REAR BOOTLID RUBBER	Not Necessary	293.40 F	*- FL
3	1		*REAR BOOTLID R/H REFLECTOR LAMP	Not Necessary	624.40 F	*- FL
4	1		*REAR BOOTLID EMBLEM	Necessary	191.60 F	*191.60 FL
			3pcs			
5	1		*REAR R/H TAILLAMP	Cracked	659.80 F	*659.80 FL
6	1		*REAR BUMPER	Deformed	626.20 F	*626.20 FL
7	2		*REAR BUMPER SIDE RETAINER	Necessary	129.40 F	*70.00 FL
8	8		*REAR BUMPER CLIP	Necessary	30.40 F	*30.40 FL
9	2		*REAR BUMPER REFLECTOR	Cracked	74.80 F	*74.80 FL
10	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	357.20 F	*- FL
11	1		*REAR END PANEL	Repair	497.10 F	*- FL
12	1		*REAR END PANEL GARNISH	Not Necessary	171.60 F	*- FL
13	2		*REAR NO. PLATE LAMP	Cracked	92.40 F	*92.40 FL
14	2		*REAR BUMPER SIDE CLIP	Necessary	25.60 F	*25.60 FL
15	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
16	1		*REAR NO. PLATE	Cracked	30.00 FS	*30.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	4,674.40	2,000.80
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	354.16
Total Parts (S\$)	4,674.40	1,646.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING.	New	50.00	30.00
2	TO SPRAY PAINTING (PEARL WHITE)	New	650.00	500.00
3	TO REMOVE & REFIX REAR INTERIOR UPHOLSTERY.	New	80.00	40.00
4	TO LABOUR CHARGE FOR PANEL BEATING, WELDING, REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC.	New	500.00	300.00
5	TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION.	New	80.00	0.00
6	TO MEASURE, DRILL THE REPLACED BUMPER, POSITION & REINSTALL REAR REAR REVERSE SENSOR, CONTROL UNIT, CHECK & TEST FOR FUNCTIONING.	New	80.00	50.00
Gross Labour Cost (\$\$)			1,440.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >