

ASS. REC. BY:

REF: CS/FCI18018276/Kqd3

n2

Special Instruction:

Surveyor:

WS

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

8/10/18 @ 4:24pm

Estimated Cost:

Bill to:

OD-TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SMC 6236C

Insured:

SHC 8818U

at Workshop m/s

eheng hui Motor

Tel:

6 755 6142

of

BLK 1019, Yishun Ind. Park A #01-374

Policy No:

Claim No:

D18007320 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 05/10/18

CA / REV / REP. / REV 24 HRS

DS

H.O.D. Endorsement:

Date/Time:

11:36am 9/10/18

Person Contacted:

june

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMC 6236C-X
	SHC 8818U - CC3/EQ18017441/Klw93 DOA: 21/9/18
10/10/18 @ 1:40pm	revised to Eileen Lee by email.
20/10	21486.32 Confirmed Total Used \$68296, 31%

ASS. REC. BY:

REF: FCZ /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.


L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.



RECEIVED 20 NOV 2018

Date/Time, File Pass to?

1) 20/10/18

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$)

7P

1486.32

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

110

50

50+50

17

277



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007320MFSH

Date: 10 October 2018

Our Ref: CS/FCI18018276/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMC 6236C

Please be informed that we had conducted the inspection of the abovementioned vehicle on 09/10/2018 at the premises of M/s CHENG HOE, and have the following to report:-

Workshop Estimate Amount	: S\$ 2,169.28 .
Revised Estimate Amount	: S\$ 1,199.60 .
"Check" Items Amount	: S\$ 460.24 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the n/s rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	08-10-2018	Our Ref No. D18007320MFSH
Accident Date	05-10-2018	Claim Type. Third Party
Insured Vehicle	SHC8818U	Third Party Vehicle. SMC6236C
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 10 October 2018 1:40 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007320MFSH/1
Attachments: CSFCI18018276Kqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SMC 6236C.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 9 October 2018 11:43 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007320MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 8 October 2018 4:23 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007320MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0705Z
Vehicle Details	
Vehicle No.:	SMC6236C
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Oct 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ACCENT (RB) 1.4 CVT
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	G4LCJU005883
Chassis No.:	KMHCU41BTKU435015
Maximum Power Output:	73.6 kW (98 bhp)
Open Market Value:	\$8,342.00
Original Registration Date:	13 Jul 2018
First Registration Date:	13 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$8,342.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jul 2028
PARF Rebate Amount:	\$6,256.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jul 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,000.00
COE Rebate Amount:	\$21,922.00
Total Rebate Amount:	\$28,178.00

The information contained herein is correct as at 05 Oct 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMC 6236C

TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: ES1891157/WS

Date: 09 Oct 2018

Policy No: 5102666003

Veh Reg No: SMC6236C

Make/Model: HYUNDAI HYUNDAI
ACCENR (RB) 1.4 CVT

WS Ref: TP/FC

Claim Type: Third Party

Accident Date: 05/10/2018

TP Veh Reg No: SHC8818U

Chassis No: KMHC41BT KU435015

Engine No: G4LCJU005883

Reg. Date: 13/07/2018

Estimate Repair Cost to Vehicle No :SMC6236C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	443.00	1 PC	443.00	✓
2 REAR BUMPER LH SIDE RETAINER	28.00	1 PC	28.00	—
3 REAR BUMPER CLIPS	3.50	6 PC	21.00	—
4 REAR BUMPER LH REFLECTOR	45.00	1 PC	45.00	✓
5 REAR BUMPER REINFORCEMENT	365.40	1 PC	365.40	X
6 REAR PANEL	499.30	1 PC	499.30	X
7 REAR LH SENSOR	195.90	1 PC	195.90	✓
8 REAR LH FENDER INN.SHIELD CLIPS	3.50	4 PC	14.00	X
			1,611.60	
		Less 20%	322.32	1,289.28
Labour				
9 PANEL BEATING	500.00	1 PC	500.00	450
10 PUTTY AND RESPRAY ON REAR LH FENDER, REAR PANEL, REAR BUMPER & SENSOR.	600.00	1 PC	600.00	320
			1,100.00	450
		Less 20%	220.00	2389.28
			880.00	
			Total	S\$ 2,169.28
			Add GST @ 7%	151.85
			Total Amount Payable	S\$ 2,321.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18018276/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-11-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SHC 8818U	Veh. Inspected
			SMC 6236C
	Policy No.		Coverage (\$)
			0.00
	Claim No.	D18007320MFSH	Excess (\$)
			0.00
	Assign From	EILEEN	Assign Date
			08/10/2018
2. Vehicle Particulars & Condition			
	Make & Model	HYUNDAI ACCENT (A)	c.c
			1368
	Engine No.	HIDDEN	Year of Reg.
			2018
	Chassis No.	KMHCU41BT KU435015	Colour
			METALLIC RED
	Odometer	3047	Steering
			IN ORDER
	Brakes	IN ORDER	Modification
			NIL
	General	GOOD	
3. Conditions of Tyres			
		Size	Make
			Balance
	R/H Front Tyre	175/70 R14	KUMHO
			9 mm
	L/H Front Tyre	175/70 R14	KUMHO
			9 mm
	R/H Rear Tyre	175/70 R14	KUMHO
			9 mm
	L/H Rear Tyre	175/70 R14	KUMHO
			9 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.		
	DAMAGES SEE DETAILS.		
5. General Information			
	Accident Date	05/10/2018	Inspection Date
			09/10/2018
	Survey held at	CHENG HOE MOTOR PL	
		BLK 1019 YISHUN IND. PARK A	
		#01-374/382	
		SINGAPORE 768761	
5a. Remarks			
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT.		
	B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.		
	C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 6236C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BUCKLED	443.00	443.00
1	REAR BUMPER LH SIDE RETAINER	DISTORTED	28.00	28.00
6	REAR BUMPER CLIPS @\$3.50	NECESSARY	21.00	21.00
1	REAR BUMPER LH REFLECTOR	SCRATCHED	45.00	45.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	365.40	-
1	REAR PANEL	TO REPAIR SEE LABOUR	499.30	-
1	REAR LH SENSOR	SHORTED	195.90	195.90
4	REAR LH FENDER INN SHIELD CLIPS @\$3.50	NOT NECESSARY	14.00	-
	LESS 20% DISCOUNT		-322.32	-146.58
			1,289.28	586.32
	LABOUR			
	PANEL BEATING, INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND REAR PANEL.		500.00	450.00
	PUTTY AND RESPRAY ON REAR LH FENDER, REAR PANEL, REAR BUMPER & SENSOR.		600.00	450.00
			1,100.00	900.00
	GRAND TOTAL		2,389.28	1,486.32
	RECOMMENDED COST OF REPAIRS			1,486.32

Report Ref No. CS/FCI18018276/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.