

ASS. REC. BY:

REF:

CS/FCI/8018290/R13d3

n2

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

CWS

From (Person):

Gerone Ler

of

FCI

Date/Time: 9/10/2018 @ 5:18pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 1605Z

Insured:

SHA 2619C

at Workshop m/s

Car life Auto

Tel: 6273 3810

of

Blk 1002 Blk Merah Lane 3 #01-75

Policy No:

Claim No:

D18007336 MPSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 06/10/2018

10/10/18

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS (DS)

Date/Time:

5:27pm @ 9/10/18

Person Contacted:

Mr. Tan

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLK 1605Z - NBA / CFI 18018190 / Y DoA: 6/10/18
	SHA 2619C - NS/INC 11000442 / Dri DoA: 6/11/2011
11/10/18	@ 15:17 p.m. revised PO to Gerone Ler via email.

REF: FCI

0681B

ASSIGNMENT

From:

Date: 10/10/18

Veh No: SLK 1605Z Yr Regn: 2017 JAN

Estimated Cost:

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SLK 1605Z

Make: TOYOTA WSH 1.8X C.C. 1797

at Workshop m/s

Carlisle tuto

Colour: GOLD A/C: Insured / Std / NI / NA

of Blk 1002, Bkt merah lane 3 # 01-75

Sp. Reading: 13673 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No: 29E 2060294 36

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:


Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 195/65 R15

R: -

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Report:

Consistent?: Yes or No

R/Bal. 6 mm

R/Bal. 6 mm

GIA / PR Seen:

Consistent?: Yes or No

L/Bal. 6 mm

L/Bal. 6 mm

Est. Repairs:

days

Res.: Yes or No

D.O.A. 06/10/18

D.O.I. 10/10/18

Lump Sum:

%

3 Val.: Yes or No

Survey held at

Carlisle

CA / REV / REP. / 24 HRS 'DS'

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/02/19 Continued P/P \$ 3,894.01 @ 5 days with Resu
(\$ 1,260.01 Red - 25%)

RECEIVED 28 FEB 2019

Date/Time: File Pass to?

28/02/19

☐ : Preli. Report

1) Typ 34

☒ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$ 3,894.01 P/P)

140

50

50

24

264



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007336MFSH

Date: 11 October 2018

Our Ref: CS/FCI18018290/R1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLK 1605Z

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/10/2018 at the premises of M/s Car Life Auto Engineering Services and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 5,154.02</u>
Revised Estimate Amount	: <u>S\$ 3,894.20</u>
"Check" Items Amount	: <u>S\$ 200.00</u>
Market Value	: <u>S\$</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 5 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	08-10-2018	Our Ref No. D18007336MFSH
Accident Date	06-10-2018	Claim Type. Third Party
Insured Vehicle	SHA2619C	Third Party Vehicle. SLK1605Z
Survey Location	BLK 1002 BUKIT MERAH LANE 3 # 01-75	
Contact Person.	NA	
Contact No.	62733810/ 0	Fax No. 62787522
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CAR LIFE AUTO ENGINEERING SERVICES	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: CarLife <autolife_sin@yahoo.com.sg>
Sent: Tuesday, 26 February 2019 3:22 PM
To: Shirley Hiew (LKK Auto)
Subject: Re: SLK 1605Z DOA 06/10/2018

Hi Ms. Shirley Hiew

Thank you for recommendation, we are agreeable to figure shall proceed to send LOD to First Capt.

Regards
Tan

On Tuesday, 26 February 2019, 9:41:28 am GMT+8, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Mr.Tan,

Please confirm final fig \$ 3,894.01 @ 5 days of repairs.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 11 October 2018 3:17 PM
To: 'CWS Motor Claims'
Cc: 'Serene Ler'; SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18007336MFSH/1
Attachments: SLK 1605Z - Preli Advise.pdf

Dear Serene,

Enclosed preliminary revised of vehicle SLK 1605Z.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 9 October 2018 5:31 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Serener@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007336MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 10/10/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 9 October 2018 5:18 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Serener@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007336MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CAR LIFE AUTO ENGINEERING SERVICES

c/o: workshop address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : autolife_sin@yahoo.com.sg

Tel: 6273 3810 Fax: 6278 7522

Date : 08-Oct-18

Address : PERIATHAMBI SETHILMURUGAN
BLK 2 HOLLAND AVENUE
#09-90
SINGAPORE 271002

Reference : TP 1174/10/18
Vehicle No : SLK 1605Z
Make/Model : TOYOTA WISH
Insurance Co. : CHINA TAIPING

RE : QUOTATION FOR REPAIRS TO SLK 1605Z FOR THIRD PARTY CLAIMS.

PARTS REQUIRED

		QTY		AMT \$
1)	REAR BUMPER	1	\$	1,355.80 DE
2)	REAR BUMPER RETAINER	1	\$	69.30 ne
3)	REAR BUMPER BRACKET	1	\$	52.65 ne
4)	TAILGATE	1	\$	1,447.14 PY
5)	TOYOTA LOGO	1	\$	64.70 ne
6)	"WISH" ENBLEM	1	\$	62.40 ne
7)	TAILGATE WEATHERSTRIPE	1	\$	286.70 ne
LIST PRICE TOTAL			\$	3,338.69
LESS DISCOUNT 25%			\$	834.67
LIST PRICE TOTAL AFTER LESS			\$	2,504.02

8)	REVERSE SENSOR	1	\$	230.00 200? XSC
9)	WINDSCREEN SEALANT	1	\$	50.00 ne
NETT PRICE TOTAL				\$280.00

TOTAL PARTS COST

\$2,784.02

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE REAR BUMPER, TAIL GATE AND TO PANEL BEAT & ALIGN END PANEL AND OTHER AFFECTED AREAS.	\$	1,200.00 500 (6 DAYS)
2)	TO PUTTY & SPRAY PAINT REAR BUMPER, TAILGATE (INNER & OUTER) AND OTHER AFFECTED AREA.	\$	800.00 600 (4 PANEL)
3)	TO REMOVE & REFIT REAR WINDSCREEN GLASS AND CHECK FOR WATER TIGHT.	\$	300.00 120
4)	TUFF KOTE	\$	350.00 60
5)	TO REMOVE AND REWIRE NEW REVERSE SENSOR.	\$	180.00 60

[Signature]
11/10/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FC118018290/R1sd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 01-03-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 2619C	Veh. Inspected	SLK 1605Z
Policy No.		Coverage (\$)	0.00
Claim No.	D18007336MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	09/10/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH 1.8X	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZGE206029436	Colour	GOLD
Odometer	13673	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	06/10/2018	Inspection Date	10/10/2018
Survey held at	CAR LIFE AUTO ENGINEERING SERVICES BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 1605Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,355.80	1,355.80
1	REAR BUMPER RETAINER	NECESSARY	69.30	69.30
1	REAR BUMPER BRACKET	NECESSARY	52.65	52.65
1	TAILGATE	BENT	1,447.14	1,447.14
1	TOYOTA LOGO	NECESSARY	64.70	64.70
1	"WISH" EMBLEM	NECESSARY	62.40	62.40
1	TAILGATE WEATHERSTRIPE	NECESSARY	286.70	286.70
	LESS 25% DISCOUNT		-834.68	-834.68
			2,504.01	2,504.01
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	SERVICEABLE	230.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
			280.00	50.00
<u>LABOUR</u>				
	TO REMOVE & REPLACE REAR BUMPER, TAIL GATE AND TO PANEL BEAT & ALIGN END PANEL AND OTHER AFFECTED AREAS.		1,200.00	500.00
	TO PUTTY & SPRAY PAINT REAR BUMPER, TAILGATE (INNER & OUTER) AND OTHER AFFECTED AREA.		800.00	600.00
	TO REMOVE & REFIT REAR WINDSCREEN GLASS AND CHECK FOR WATER TIGHT.		300.00	120.00
	TUFF KOTE.		350.00	60.00
	TO REMOVE AND REWIRE NEW REVERSE SENSOR.		180.00	60.00
			2,830.00	1,340.00
GRAND TOTAL			5,614.01	3,894.01
RECOMMENDED COST OF REPAIRS				3,894.01

Report Ref No. CS/FCI18018290/R1sd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING**B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.