

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1156/2018/PH
Date	:	10-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : SKW 9990 G

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Active Fire Protection Systems Pte Ltd
Address	:	87 Pasir Ris heights #16-10 Singapore 519285
Telephone	:	HP +65 63533371
Type of Claim	:	Third Party Damage Claim
Policy No.	:	5088252327- 01
Vehicle No	:	SKW 9990 G
Model Code	:	Audi Q7 3.0 TFSI
Model / Year	:	Sep-15
Engine No	:	CRE 052115
Chassis No	:	WAUZZZ4M0GD011966
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	7-Oct-18
Place of Accident	:	Lower Delta Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKW 9990 G.

FRONT

S/n	Nature of Jobs	Estimated Charges	Remarks
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper. To repair rear lid. Re-organize rear crash management components. Reinstall all parts removed.	\$ 1,600.00 600	
3	To respray rear bumper, rear lower bumper, rear lid and both rear wheel arc covers.	\$ 2,800.00 1200	Upper Bumper 400 Lower Bumper 400 Ar lower x2 : 200 x 2 = 400 1200
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>4,952.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKW 9990 G .

(Front)

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Repair</i>	\$ 2,706.00	X
2	REAR BUMPER FIXING PARTS <i>Not New</i>	\$ 178.00	X.
3	REAR BUMPER SPOILER - BARCELONETA SILVER <i>del</i>	\$ 1,095.00	✓
4	REAR BUMPER SPOILER - SATIN BLACK ?	\$ 92.00	?
5	CONTROL UNIT FOR OPENING BOOT LID <i>Not m</i>	\$ 334.00	X.
6	REAR BUMPER CARRIER <i>Not m</i>	\$ 1,189.00	X
7	GUIDE SECTION - CENTRE <i>Not m</i>	\$ 121.00	X
8	HOLDING STRAP <i>Not m</i>	\$ 156.00	X
9	REAR SENSOR <i>Not m</i>	2 \$ 421.00	X
10	REAR SENSOR SEAL RING	4 \$ 14.00	X
11	PACKING ADHESIVE	\$ 15.00	X
12	AUDI LOGO	\$ 108.00	X
13	Q7' EMBLEM	\$ 83.00	X
14	TFSI' EMBLEM	\$ 83.00	X
15	QUATTRO' EMBLEM	\$ 83.00	X
16	REAR BUMPER THIRD BRAKE LIGHT - LH/RH <i>Not m</i>	2 \$ 626.00 313.	
17	REAR WHEEL COVER - LH/RH <i>Not m</i>	2 \$ 662.00	✓
18	REAR CAR PLATE <i>Not m</i>	S/N \$ 25.00	X.
19	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		: \$ 8,291.00	
TOTAL LABOUR CHARGES		: \$ 4,952.00	
GRAND TOTAL		: <u>\$ 13,243.00</u>	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 12/10/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant