

ASS. REC. BY:

REF: CS/FCI18018354/Gvd3/12

Special Instruction:

Surveyor:

CWS

Gwo Orancy

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

5/10/18 @ 12:17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHF 579X

Insured:

SHD 7026P

at Workshop m/s

Trans cub

Tel:

6287 6666

of

No. 2 Amk St-63

Policy No:

Claim No:

D18007223MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/09/18

CA / REV / REP. / REV 24 HRS

(PS)

Date/Time:

12:21pm @ 5/10/18

Person Contacted:

Candy

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHF 579X - NBA / INC17005027/Y

DOA: 1/3/2017

SHD 7026P - NSI / NC16003066 / H1 qbn2

DOA: 6/2/2016

10/10/18

Email preli revised to FCI

29/10/18

LS \$ 2450 Confirmed by email (Red 37,483.69, 9470)

Surveyor

xcl.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s

trans - carb

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

SHF579X

Yr Regn:

20 Jun 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

nema H latitude c.c 1995

Colour

red

A/C: Insured / Std / NI / NA

Sp. Reading

-

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABC 15A4 C 278418

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/60R16
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

05-10-18

Survey held at

w/s 3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 29 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

29/10 - typist

Report Format :

CWS

Lump Sum / I.B.I. (\$

24506

Days Of Repair: 2

Resurvey No. of Trip: -

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

12x15=

170+180

50

15

670

415



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18007223MFSH
Our ref: CS/FC118018354/Gvd3

Date: 10/10/2018

The Motor Claims Department
M/s First Capital Insurance Limited

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHF 579X


We thank you for your instruction on 5/10/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 5/10/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	:S\$39,933.69
Revised Estimate Amount	:S\$3,095.34
"Check" Items Amount	:S\$102.12
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

XING GUO QIANG (HP 8288 0282)

M.MATAL, AMSAE-A

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	02-10-2018	Our Ref No.	D18007223MFSH
Accident Date	29-09-2018	Claim Type.	Third Party
Insured Vehicle	SHD7026P	Third Party Vehicle.	SHF579X
Survey Location	NO. 2 ANG MO KIO STREET 63		
Contact Person.	CANDY KONG		
Contact No.	62876666/ 0	Fax No.	62571330
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	KARENT		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 29 October 2018 11:10 AM
To: 'Ng Wai Yin'
Cc: 'Candy Kong'; claims@transcab.com.sg; SUR
Subject: RE: SHF 579X-DOA: 29/9/2018 -- AAD1810-018

Dear Wai Yin,

Noted with thanks.

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Monday, 29 October 2018 11:04 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: 'Candy Kong' <candy.kong@transcab.com.sg>; claims@transcab.com.sg; SUR <sur@lkkauto.com>
Subject: FW: SHF 579X-DOA: 29/9/2018 -- AAD1810-018

WITHOUT PREJUDICE

Dear Veron

We confirmed COR \$2,450.00 (before GST).

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Friday, 12 October, 2018 11:19 AM
To: claims@transcab.com.sg; Candy Kong <candy.kong@transcab.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: SHF 579X-DOA: 29/9/2018

Dear Candy/Calvin,

WITHOUT PREJUDICE

Offer Lump Sum \$2450/- @ 2 working days.

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 10 October 2018 4:42 PM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007223MFSH/1, SHF 579X
Attachments: SHF 579X PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHF 579X
Date of survey: 5/10/2018
Number of days : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 5 October 2018 12:22 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007223MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 5 October 2018 12:16 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007223MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHF579X
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001563
Chassis No.:	VF1ABL15AUC278418
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	20 Jun 2014
First Registration Date:	20 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$26,459.00
Total Rebate Amount:	\$35,832.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Oct 2018

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHF579X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	01 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001563
Chassis No.:	VF1ABL15AUC278418
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	20 Jun 2014
First Registration Date:	20 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	19 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$26,638.00
Total Rebate Amount:	\$36,011.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 01 Oct 2018

OK

Trans-cab Auto Services Pte Ltd**AAD1810-018**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 579X

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 579X

VF1ABL15AUC278418

RENAULT

LATITUDE

29.9.2018

FCIL

PART		LIST	
1	1 BUMPER COVER REAR / <i>ae</i>	\$	1,108.46
2	1 BUMPER LOWER REAR / <i>ca</i>	\$	768.84
3	1 BUMPER BRACKET CTR REAR <i>X NN</i>	\$	113.47
4	1 BUMPR BRACKET SIDE RH REAR <i>X</i>	\$	135.97
5	1 BUMPR RETAINER RH REAR <i>X</i>	\$	44.99
6	1 BUMPER REFLECTOR RH <i>X</i>	\$	43.61
7	1 BUMPR BRACKET SIDE LH REAR <i>X</i>	\$	135.97
8	1 BUMPER RETAINER LH REAR <i>X</i>	\$	44.99
9	1 BUMPER REFLECTOR LH <i>X</i>	\$	43.61
10	1 BUMPER BEAM REAR <i>X BT.</i>	\$	777.52
11	1 BUMPER BEAM BRACKET LH REAR <i>X</i>	\$	225.95
12	1 BUMPER BEAM BRACKET RH REAR <i>X</i>	\$	225.95
13	1 OUTER PANEL REAR (End Panel) <i>X</i>	\$	1,471.77
14	1 OUTER PANEL REAR (End Panel) TRIM <i>X NN</i>	\$	404.56
15	1 TAILLAMP RH <i>X</i>	\$	552.55
16	1 TAILLAMP PANEL RH <i>X</i>	\$	986.70
17	1 TAILLAMP LH <i>X</i>	\$	552.55
18	1 TAILLAMP PANEL LH <i>X</i>	\$	986.70
19	1 BOOT REAR <i>X</i>	\$	2,872.68
20	1 BOOT FINISHER <i>X</i>	\$	470.06
21	1 BOOT WHEATERSTRIP <i>X</i>	\$	323.05
22	1 BOOT REFLECTOR LAMP LH <i>X</i>	\$	493.35
23	1 BOOT REFLECTOR LAMP RH <i>X</i>	\$	493.35
24	1 BOOT BADGE 'RENAULT' <i>X</i>	\$	225.36
25	1 BOOT BADGE <i>X</i>	\$	225.36
26	1 BOOT STRUT LH <i>X</i>	\$	276.08
27	1 BOOT STRUT RH <i>X</i>	\$	276.08
28	1 BOOT HINGE LH <i>X</i>	\$	367.84
29	1 BOOT HINGE RH <i>X</i>	\$	367.84

Trans-cab Auto Services Pte Ltd

AAD1810-018

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 579X

30	1 BOOT INNER TRIM	X	\$	586.45
31	1 BOOT SWITCH	X	\$	168.13
32	1 BOOT LOCK	X	\$	202.67
33	1 BOOT LOCK CATCH	X	\$	74.40

} ~ ~

	\$	16,046.87
10%	\$	7.44
	\$	<u>16,039.43</u>

14442.17

Special Nett

1	1SET PARKING AID	/ DM	\$	700.00
2	1SET REAR BUMPER CLIP	/ ME	\$	66.00
3	1SET BUMPER BRACKET CTR CLIP	X	\$	33.00
4	1SET BUMPER BRACKET SIDE CLIP RH RR	X	\$	10.00
5	1SET BUMPER RETAINER RH CLIP RR	X	\$	20.00
6	1SET BUMPER BRACKET SIDE CLIP LH RR	X	\$	10.00
7	1SET BUMPER RETAINER CLIP LH RR	X	\$	20.00
8	1SET BUMPER LOWER REAR RIVET	X	\$	22.00
9	1SET BUMPER LOWER REAR CLIP	X	\$	66.00
10	1 EXHAUST MOUNTING REAR	X	\$	17.82
11	2 REAR WINDSCREEN SELANT	X	\$	80.00
12	1 WINDSCREEN MOULDING	X	\$	100.00
13	1 REAR WINDSCREEN INNER SPONGE SEAL	X	\$	100.00

} ~ ~

TOTAL \$ 1,244.82**TOTAL PARTS \$ 17,284.25****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00

Trans-cab Auto Services Pte Ltd

AAD1810-018

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 579X

To Rust-Proofing Of The Affected Areas.	\$	170.00	X <i>mm</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>40</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X <i>mm</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X

TOTAL \$ 6,610.00**Over All Total \$ 39,933.69***22296.99***(LUMP SUM)****Repair Days****10 DAYS**

2 Days
Uniform repair
After repair photo.
Car is ok.
05/10/18.

LKP Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18018354/Gvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 7026P	Veh. Inspected	SHF 579X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007223MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	05/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC278418	Colour	RED	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	6 mm	
L/H Front Tyre	215/60 R16	GITI	6 mm	
R/H Rear Tyre	215/60 R16	GITI	6 mm	
L/H Rear Tyre	215/60 R16	GITI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/09/2018	Inspection Date	05/10/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 579X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	DEFORMED	1,108.46	1,108.46
1	BUMPER LOWER REAR	CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	NOT NECESSARY	113.47	-
1	BUMPER BRACKET SIDE RH REAR	NOT NECESSARY	135.97	-
1	BUMPER RETAINER RH REAR	NOT NECESSARY	44.99	-
1	BUMPER REFLECTOR RH	NOT NECESSARY	43.61	-
1	BUMPER BRACKET SIDE LH REAR	NOT NECESSARY	135.97	-
1	BUMPER RETAINER LH REAR	NOT NECESSARY	44.99	-
1	BUMPER REFLECTOR LH	NOT NECESSARY	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	NOT NECESSARY	225.95	-
1	BUMPER BEAM BRACKET RH REAR	NOT NECESSARY	225.95	-
1	OUTER PANEL REAR (END PANEL)	NOT NECESSARY	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	NOT NECESSARY	404.56	-
1	TAILLAMP RH	NOT NECESSARY	552.55	-
1	TAILLAMP PANEL RH	NOT NECESSARY	986.70	-
1	TAILLAMP LH	NOT NECESSARY	552.55	-
1	TAILLAMP PANEL LH	NOT NECESSARY	986.70	-
1	BOOT REAR	NOT NECESSARY	2,872.68	-
1	BOOT FINISHER	NOT NECESSARY	470.06	-
1	BOOT WEATHERSTRIP	NOT NECESSARY	323.05	-
1	BOOT REFLECTOR LAMP LH	NOT NECESSARY	493.35	-
1	BOOT REFLECTOR LAMP RH	NOT NECESSARY	493.35	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	NOT NECESSARY	276.08	-
1	BOOT STRUT RH	NOT NECESSARY	276.08	-
1	BOOT HINGE LH	NOT NECESSARY	367.84	-
1	BOOT HINGE RH	NOT NECESSARY	367.84	-
1	BOOT INNER TRIM	NOT NECESSARY	586.45	-
1	BOOT SWITCH	NOT NECESSARY	168.13	-

Report Ref No. CS/FCI18018354/Gvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK	NOT NECESSARY	202.67	-
1	BOOT LOCK CATCH	NOT NECESSARY	74.40	-
	LESS 10% DISCOUNT		-1,604.69	-265.48
			14,442.17	2,389.34
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	DAMAGED	700.00	200.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	17.82	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
			1,244.82	266.00
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	200.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.		2,200.00	200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	40.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-

Report Ref No. CS/FCI18018354/Gvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			6,610.00	440.00
GRAND TOTAL			22,296.99	3,095.34
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,450.00

Report Ref No. CS/FCI18018354/Gvd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.