

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

EQ

Owner : Nor Kamaruzzaman
Bin Kamalrudin

Accident Date : 29-Sep-18

Vehicle No : FBE 5575 A

Vehicle Model : Yamaha RXZ

Estimated Repair Costs

Qty	Description <u>List Items</u>	Amount S(\$)
1	Front fender	\$ cur 65.00
2	Fork inner tubes 105	\$ 213.4 210.00
2	Fork outer tubes 110	\$ 015.00 220.00
1	Fork under bracket	\$ 145.00
1	Front brake disc	\$ 135.00
1	Front sport rim	\$ 250.00
1	Front rim shaft	\$ 38.00
1	Top cowling	\$ 85.00
1	Windshield	\$ 32.00
1	Lampstay	\$ 50.00
1	Headlamp	\$ 70.00
2	Side mirrors 35	\$ 70.00
2	Front signals 40	\$ 80.00
1	Handle bar	\$ 68.00
1	Hand grip (1 set)	\$ 35.00
1	Handle bar end	\$ 18.00
1	Brake lever	\$ 25.00
1	Clutch lever	\$ 25.00
1	Meter assy	\$ 420.00
1	Fuel tank	\$ 400.00
1	Front footrest	\$ 32.00
1	Front footrest bracket -R/H	\$ 55.00
1	Front footrest rubber -R/H	\$ 15.00
1	Brake pedal	\$ 32.00
1	Rear footrest -R/H	\$ 28.00
1	Exhaust assy	\$ 450.00
1	Rear tailboard	\$ 70.00
		\$ 3,123.00
Less 10%		\$ 312.30
		\$ 2,810.70

not allocated
new
2/5
10/10/18
Theophan Athanasios
4 dr.

1203
1082.7

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Owner : Nor Kamaruzzaman
Bin Kamalrudin

Accident Date : 29-Sep-18

Vehicle No : FBE 5575 A

Vehicle Model : Yamaha RXZ

Estimated Repair Costs

c/f: \$ 2,810.70

Special Nett Items

1	Number plate (1 set)	\$	500	28.00	10
2	Fork oils	\$	20	30.00	—
2	Fork oil seals	\$	20	56.00	—
1	Steering cone (1 set)	\$	20	75.00	—
1	Sticker (1 set)	\$	20	90.00	—
		\$		279.00	

S/No.

Labour

1	To provide towing service.	\$	35	70.00	
2	To check wiring and reset headlamp focusing.	\$	11	80.00	x
3	To provide labour.	\$	320	380.00	
4	To repair body frame.	\$	11	350.00	x
		\$		860.00	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Grand Total

\$ 3,949.70

16887
1358

Dollars: Three Thousand Nine Hundred Forty-Nine And Seventy Cents Only.

EROFIA MOTOR TRADING PTE LTD

OFFICIAL RECEIPT

No. _____

Date. 2/10/18

Received from _____

FALCON

The sum of dollars FRE 5575 Tow to AXA TO EROFIA

2 way

Being payment of _____

\$ 70

Cash/Cheque No.

2

27497925

1