

CC 4, III 180 18382 *Dira's 2* LKK: *Jay* IDAC: *10/10/18*

DOI: *10/10/18* Date / Time: *10/10/18* Registered in Merlimen: *10/10/18*

Pre-assign / CCU / FTE



Insured Vehicle No.: *SHA 31416*
 Name of Insured: *UPM*
 Insured Tel No.: *HP:*
 Excess Sec II :S\$ *D.O.A: 9/10/18*
 Is driver the owner? (YES / NO) *(YES)* Nature of Accident:
 If NO, Driver Name / Age:
 Driver Tel No.: *(V/L: YES/NO)*

Claim No.:
 Policy No.: *Wx*
 Make / Model:
 Place of Accident:

OI GIA REPORT: *(YES)* / NO ; TP GIA REPORT: *(YES)* / NO
 Insured Liability: % Final? Yes / No

SHA 31416 → *CHAM* → *INSRS:* WSP: *CHAM* Tel: *CHAM* Liability: *CHAM* RMKS:
INSRS: WSP: Tel: Liability: RMKS:
INSRS: WSP: Tel: Liability: RMKS:
INSRS: WSP: Tel: Liability: RMKS:

Date / Time	STAGE	DATE / PIC
<i>19/10</i>	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	S\$	(days) Reduction: %
FINAL SETTLEMENT	Date/Time: <i>26-9-19</i>	Confirm with: <i>WILLIAM</i>
Final Liability:	% <i>100</i>	(Agreed / Assessed) BOLA S/N No.: <i>10</i>
Repair Cost:	S\$ <i>20,330.xx</i>	
Loss of Rental (LOR):	S\$ <i>1265</i> (<i>11</i> days) <i>115</i>	
Loss of Use (LOU):	S\$ <i>—</i> (\$ x days)	
Loss of Income (LOI):	S\$ <i>440</i> (<i>246</i> x <i>11</i> days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	S\$ <i>—</i>	
Medical:	S\$ <i>—</i>	
Disbursement:	S\$ <i>—</i>	(e.g. Tow/ Independent)
Legal Cost	S\$ <i>—</i>	
Total:	S\$ <i>22,035.xx</i>	Global Sum S\$: <i>17,755.xx</i>
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	<i>17,755.00</i>	Name 1: <i>CHUNNI MOTOR WORK PTE LTD</i>
Payee 2: (Strike if N.A.)	<i>X</i>	Name 2: <i>X</i>
Payee 3: (Strike if N.A.)	<i>X</i>	Name 3: <i>X</i>

COPY SENT 11/6/2019

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format:
- 3) Survey fee:

REF:

ASSIGNMENT

COE Jan 2024

8HC 8728X

Yr Regn: 2016 / Jan

From:

Date:

Estimated Cost:

OO / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop no:

of

Insured:

Policy No:

Claims No:

Gum Insured:

Excess:

(Client's Record)

Make of Vehicle:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen: 20

Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40

Yr 1685

Colour:

Blue

A/C: Insured / Std / Nil / NA

Sp. Roading:

371513

T/Cable: Insured / Std / Nil / NA

Eng/No:

D4FD FV581657

C/No:

KMHLB41UM6U083301

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Mod: STD / S/Rim / STD A/Rim or

Tyre Size:

P:

205/60 R16

R:

11

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Waste Lake

Front

Rear

R/Bal:

S

mm

R/Bal:

S

mm

L/Bal:

S

mm

L/Bal:

S

mm

D.O.A:

09/10/2018

D.O.A: 10/10/2018

Survey held at

Chunni Amk

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

N/S Front 4 4/S Body 4/S Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TH 8HA 3141 G

27/11/18 Janya 4/S 190001 - with 12 days of rev

R (\$ 11,711.84 / 38%)

Dated Time, F20 Pages 107



: Preli. Report

1)



: Final Report

Dated Time, File Ref: 107

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee:

Transportation:

) 2 + 10, 34

) Photos

) Others

Report Format:

Lump Sum / LBA: (\$

REPAIR ESTIMATE*

DATE : 10.10.2018

TEL : 6542 5119

FAX : 6542 6039

INDIA

[illegible]

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 8728 X

Technician:

Mileage: 371513

Time Printed 10.10.18 3:25 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
10°52'		-3°00' 3°00'
4°01'		-0°19' 5°41'
9°12'		-1°30' 1°30'
9°59'		
20°51'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
2°05'		-3°00' 3°00'
3°58'		-0°19' 5°41'
0°59'		-1°30' 1°30'
11°37'		
13°41'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
8°48'		-3°00' 3°00'
0°03'		-3°00' 3°00'
-1°38'		-3°00' 3°00'
10°11'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
4°18'		-3°30' 2°30'
8°23'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
0°43'		-3°30' 2°30'
0°09'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
3°35'		-3°00' 3°00'
8°33'		-3°00' 3°00'
4°07'		-3°00' 3°00'

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MCD618131282 Vehicle Registration No: SHC 8728X
Name(as shown in NRIC) : Lim Lian Yeu NRIC/FIN/Passport No : S 1432409G
(☒ **Vehicle Driver** ☐ Vehicle Owner) (*) Please delete as appropriate
Address : Blk 662 Buffalo Road # 24-16 Singapore(210662)
Contact (Tel) : 6297 1630 Mobile No. : 8348 9948
Email Address : _____
Date of Accident : 09.10.2018 Time of Accident : 15:55 Hrs
Place of Accident : East Coast Road Twds Mountbatten Road (Roxy Square)
Insurance Company : MS First Capital Insurance Ltd

(B) ADDITIONAL INFORMATION **AMENDMENTS**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend the third party vehicle category : remove the private car. 3P is 'taxi' & not 'private car'

P. Lim

Policyholder / Driver's Signature
Date: 10.10.2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:

Catherine Chong (LKK Auto)

18302 / DWG3

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Wednesday, 10 October, 2018 12:12 PM
To: assignments
Subject: FW: Accident involving veh no: SHC 8728X & SHA 3141G on 09.10.18
Attachments: 10102018110903.pdf

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

10.10.2018 @ 1:44pm
Tone veh in

Byun.

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 10 October 2018 11:58 AM
To: SUR <sur@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Cc: Chunni Motor <chunnimotor@gmail.com>; Mekavathanan Sarangapani <mekavathanan@iii.com.sg>; Zuhaidah Samsuri <aida@iii.com.sg>
Subject: FW: Accident involving veh no: SHC 8728X & SHA 3141G on 09.10.18

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SHC 8728X and let us have your report urgently.

This claim will be handled by Ms AIDA.

*Kindly upload this survey request email to merimen.

Thank You.

Joel Nah

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Wednesday, 10 October, 2018 11:19 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Accident involving veh no: SHC 8728X & SHA 3141G on 09.10.18

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey in AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

View Received Message

This mail is associated with :

***SHC8728X (MCT18100266)**
[SHA3141G]

TP

COMFORT TRANSPORTATION PTE LTD
Oct 9 2018 12:00AM

Chunni Motor Work Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 24/10/2018 11:12 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$0.00) - SHC8728X - Claim Handler: Zuhaidah Bte Samsuri

Approved:0.00.

DOCUMENTS SUMMARY

There are no documents.

Our Ref : SHC 8728 X (091018)

Your Ref : SHA 3141 G (III)

Date : 7 June 2019

M/S LKK Auto Consultants Pte Ltd
Blk 51 Paya Ubi Industrial Park
#02-25 Ubi Avenue 1
Singapore 408933

WITHOUT PREJUDICE

Attention : Joy Irene
Case Handler

Dear Sir/Madam

ACCIDENT INVOLVING SHC 8728 X & SHA 3141 G ALONG EAST COAST ROAD ON 09-10-2018

Your email of 04-06-2019 refers.

Strictly on a without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair and the loss of income and rental during the period of repair) at a global sum of \$17,755.00.

Please note that the settlement reached is strictly for the aforesaid property damage claim only and is without prejudice to the hirer of SHC 8728 X, Lim Lian Yeu's rights to claim damage for his injury against your insured, if any.

As requested, we return the attached Discharge Voucher duly executed together with the original Letter of Demand dated 03-12-2018 for your onward transmission.

Kindly expedite payment and forward us your cheque for the settlement sum of **\$17,755.00** made in favour of **M/s Chunni Motor Work Pte Ltd** as soon as possible.

Thank you.

Your faithfully

For **Chunni Motor Work Pte Ltd**

Claims Department

Enc

Print Received Message

This mail is associated with :

***SHC8728X (MCT18100266)**

[SHA3141G]

TP

COMFORT TRANSPORTATION PTE LTD

Oct 9 2018 12:00AM

[-]

Chunni Motor Work Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 17/04/2019 15:40 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$17755.00) - SHC8728X - Claim Handler: Zuhaidah Bte Samsuri

Approved:17755.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Oct 2018 Edit Reg		10 Oct 2018 00:00 Edit Adj Rpt	S\$19,000.00 Edit Estimates	S\$19,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHC8728X	Date of Loss:	09/10/2018 00:00 - :59 [32 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18100266	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHA3141G	Policy No. (Claimant):	D-18088936MFSH
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 19/10/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (17/04/2019): Alert - Adj Mandate Approved (S\$17755.00) - SHC8728X - Claim Handler: Zuhaidah B...
- III_SG (26/03/2019): Alert - Adj Mandate Maintained - SHC8728X - Claim Handler: Zuhaidah Bte Samsuri
- III_SG (15/03/2019): Alert - Adj Mandate Maintained - SHC8728X - Claim Handler: Zuhaidah Bte Samsuri
- III_SG (12/02/2019): Alert - Adj Mandate Maintained - SHC8728X - Claim Handler: Zuhaidah Bte Samsuri
- III_SG (11/02/2019): Alert - Adj Mandate Maintained - SHC8728X - Claim Handler: Zuhaidah Bte Samsuri
- III_SG (01/02/2019): Alert - Adj Mandate Maintained - SHC8728X - Claim Handler: Zuhaidah Bte Samsuri
- III_SG (24/10/2018): Alert - Adj Mandate Approved (S\$0.00) - SHC8728X - Claim Handler: Zuhaidah Bte S...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC8728X (MCT18100266)

[SHA3141G]

TP

COMFORT TRANSPORTATION PTE LTD

Oct 9 2018 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

Chunni Motor Work Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/11/18 14:46	Front View Right	 Load JPG	✓
2	25/11/18 14:46	Front View Left	 Load JPG	✓
3	25/11/18 14:47	General View	 Load JPG	✓
4	25/11/18 14:47	General View	 Load JPG	✓
5	25/11/18 14:47	General View	 Load JPG	✓
6	25/11/18 14:47	General View	 Load JPG	✓
7	25/11/18 14:47	General View	 Load JPG	✓
8	25/11/18 14:47	General View	 Load JPG	✓
9	25/11/18 14:47	General View	 Load JPG	✓
10	25/11/18 14:47	General View	 Load JPG	✓
11	25/11/18 14:47	General View	 Load JPG	✓
12	25/11/18 14:47	General View	 Load JPG	✓
13	25/11/18 14:47	General View	 Load JPG	✓
14	25/11/18 14:47	General View	 Load JPG	✓
15	25/11/18 14:47	General View	 Load JPG	✓
16	25/11/18 14:47	General View	 Load JPG	✓
17	25/11/18 14:47	General View	 Load JPG	✓
18	25/11/18 14:47	General View	 Load JPG	✓
19	25/11/18 14:47	General View	 Load JPG	✓
20	25/11/18 14:47	General View	 Load JPG	✓
21	25/11/18 14:47	General View	 Load JPG	✓
22	25/11/18 14:47	General View	 Load JPG	✓
23	25/11/18 14:47	General View	 Load JPG	✓
24	25/11/18 14:47	General View	 Load JPG	✓
25	25/11/18 14:47	General View	 Load JPG	✓
26	25/11/18 14:47	General View	 Load JPG	✓
27	25/11/18 14:47	General View	 Load JPG	✓
28	25/11/18 14:47	General View	 Load JPG	✓
29	25/11/18 14:47	General View	 Load JPG	✓
30	25/11/18 14:47	General View	 Load JPG	✓
31	25/11/18 14:47	General View	 Load JPG	✓
32	25/11/18 14:47	General View	 Load JPG	✓
33	25/11/18 14:47	General View	 Load JPG	✓
34	25/11/18 14:47	General View	 Load JPG	✓
35	25/11/18 14:47	General View	 Load JPG	✓

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	25/11/18 14:47	General View	 Load JPG	☒
37	25/11/18 14:47	General View	 Load JPG	☒
38	25/11/18 14:47	General View	 Load JPG	☒
39	25/11/18 14:47	General View	 Load JPG	☒
40	25/11/18 14:47	General View	 Load JPG	☒
41	25/11/18 14:47	General View	 Load JPG	☒
42	25/11/18 14:47	General View	 Load JPG	☒
43	25/11/18 14:47	General View	 Load JPG	☒
44	25/11/18 14:47	General View	 Load JPG	☒
45	25/11/18 14:47	General View	 Load JPG	☒
46	25/11/18 14:47	General View	 Load JPG	☒
47	25/11/18 14:47	General View	 Load JPG	☒
48	25/11/18 14:47	General View	 Load JPG	☒
49	25/11/18 14:47	General View	 Load JPG	☒
50	25/11/18 14:47	General View	 Load JPG	☒
51	25/11/18 14:47	General View	 Load JPG	☒
52	25/11/18 14:47	General View	 Load JPG	☒
53	25/11/18 14:47	General View	 Load JPG	☒
54	25/11/18 14:47	General View	 Load JPG	☒
55	25/11/18 14:47	General View	 Load JPG	☒
56	25/11/18 14:47	General View	 Load JPG	☒
57	25/11/18 14:47	General View	 Load JPG	☒
58	25/11/18 14:47	General View	 Load JPG	☒
59	25/11/18 14:47	General View	 Load JPG	☒
60	25/11/18 14:47	General View	 Load JPG	☒
61	25/11/18 14:47	General View	 Load JPG	☒
62	25/11/18 14:47	General View	 Load JPG	☒
63	25/11/18 14:47	General View	 Load JPG	☒
64	25/11/18 14:47	General View	 Load JPG	☒
65	25/11/18 14:47	General View	 Load JPG	☒
66	25/11/18 14:47	General View	 Load JPG	☒
67	25/11/18 14:47	General View	 Load JPG	☒
68	25/11/18 14:47	General View	 Load JPG	☒
69	25/11/18 14:47	General View	 Load JPG	☒
70	25/11/18 14:47	General View	 Load JPG	☒
71	25/11/18 14:47	General View	 Load JPG	☒
72	25/11/18 14:47	General View	 Load JPG	☒
73	25/11/18 14:47	General View	 Load JPG	☒
74	25/11/18 14:47	General View	 Load JPG	☒
75	25/11/18 14:47	General View	 Load JPG	☒
76	25/11/18 14:47	General View	 Load JPG	☒
77	25/11/18 14:47	General View	 Load JPG	☒
78	25/11/18 14:47	General View	 Load JPG	☒
79	25/11/18 14:47	General View	 Load JPG	☒
80	25/11/18 14:47	General View	 Load JPG	☒
81	25/11/18 14:47	General View	 Load JPG	☒
82	25/11/18 14:47	General View	 Load JPG	☒
83	25/11/18 14:47	Odometer Reading	 Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	25/11/18 14:47	Chassis Number	 Load JPG	☒
85	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
86	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
87	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
88	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
89	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
90	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
91	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
92	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
93	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
94	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
95	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
96	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
97	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
98	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
99	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
100	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
101	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
102	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
103	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
104	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
105	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
106	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
107	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
108	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
109	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
110	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
111	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
112	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
113	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
114	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
115	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
116	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
117	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
118	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
119	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
120	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
121	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
122	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
123	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
124	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
125	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
126	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
127	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
128	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
129	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
130	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
131	25/11/18 14:48	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
132	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
133	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
134	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
135	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
136	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
137	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
138	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
139	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
140	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
141	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
142	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
143	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
144	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
145	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
146	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
147	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
148	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
149	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
150	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
151	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
152	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
153	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
154	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
155	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
156	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
157	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
158	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
159	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
160	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
161	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
162	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
163	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
164	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
165	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
166	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
167	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
168	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
169	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
170	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
171	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
172	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
173	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
174	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
175	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
176	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
177	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
178	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
179	25/11/18 14:48	Reinspection Photo	Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
180	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
181	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
182	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
183	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
184	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
185	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
186	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
187	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
188	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
189	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
190	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
191	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
192	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
193	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
194	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
195	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
196	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
197	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
198	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
199	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
200	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
201	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
202	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
203	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
204	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
205	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
206	25/11/18 14:48	Reinspection Photo	 Load JPG	☒
207	25/11/18 14:49	Finishing Photo	 Load JPG	☒
208	25/11/18 14:49	Finishing Photo	 Load JPG	☒
209	25/11/18 14:49	Finishing Photo	 Load JPG	☒
210	25/11/18 14:49	Finishing Photo	 Load JPG	☒
211	25/11/18 14:49	Finishing Photo	 Load JPG	☒
212	25/11/18 14:49	Finishing Photo	 Load JPG	☒

Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/10/18 11:00	ACKNOWLEDGEMENT EMAIL TO III DD 10.10.2018	 Load PDF	
2	16/10/18 11:00	TP ESTIMATE + TP GIA REPORT	 Load PDF	
3	23/10/18 17:38	TP ESTIMATE - MARKED	 Load PDF	
4	23/10/18 17:38	WHEEL ALIGNMENT REPORT	 Load PDF	
5	15/01/19 14:58	AUTHORISATION TO ACT	 Load PDF	
6	15/01/19 14:58	LOD	 Load PDF	
7	15/01/19 14:58	RENTAL MILEAGE	 Load PDF	
8	15/01/19 14:58	RENTAL RECEIPT	 Load PDF	
9	15/01/19 14:58	WORKSHOP INVOICE	 Load PDF	
10	11/06/19 14:25	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	11/10/18 08:58	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18018382/DJA3S2

Date: 11/06/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SHC8728X	Insured Vehicle No :	SHA3141G
Date of Loss:	09/10/2018	Nature of Claim:	TP
		Claim No:	MCT18100266

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8728X		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4DFU581657
Reg. Date:	21/01/2016 (Man. Year: 2015)	Chassis No:	KMHLB41UMGU083301
Colour:	Blue	Odometer:	371513 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,601.84	20,008.72	4,593.12	18.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,110.00	2,710.00	3,400.00	55.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,711.84	22,718.72	7,993.12	26.03
Approved Total (Overridden) (S\$)		19,000.00		
(S\$)	30,711.84	19,000.00	11,711.84	38.13
+ GST 7.00/7.00% (S\$)	2,149.83	1,330.00	819.83	38.13
Nett Amount (S\$)	32,861.67	20,330.00	12,531.67	38.13
+ Loss of Use (11.0 x S\$40.00/day) (S\$)		440.00		
+ Car Rental (11.0 x S\$115.00/day) (S\$)		1,265.00		
Nett Liability (S\$)		22,035.00		
Global Sum Settlement (S\$)		17,755.00		

INSPECTION

Date of Assignment: 10/10/2018

Date Inspected: 10/10/2018 Inspected At:

Chunni Motor Work Pte Ltd (HQ)
Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 12.0 days

Adjuster: BRYAN TANI

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Jun 2019)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC8728X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Repair	1,052.20 FL	*- FL
2	1		*FRONT BUMPER BRACKET (LH)	Serviceable	24.60 FL	*- FL
3	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
4	1		*HEADLAMP (LH)	Broken	1,388.00 FL	*1,388.00 FL
5	1		*FRONT FENDER (LH)	Bent	566.30 FL	*566.30 FL
6	1		*FRONT FENDER SHIELD (LH)	Serviceable	174.90 FL	*- FL
7	1		*FRONT DOOR (LH)	Buckled	2,256.40 FL	*2,256.40 FL
8	1		*FRONT DOOR RUBBER	Necessary	290.50 FL	*290.50 FL
9	1		*FRONT DOOR GEAR / REGULATOR (LH)	Cracked	250.60 FL	*250.60 FL
10	1		*FRONT DOOR POWER MOTOR, LH	Not Necessary	172.70 FL	*- FL
11	1		*FRONT DOOR TRIM BOARD (LH)	Mtg Cracked	973.50 FL	*973.50 FL
12	1		*FRONT WHEEL RIM (LH)	Bent	325.30 FL	*325.30 FL
13	1		*FRONT WHEEL HUB CAP (LH)	Bent	107.10 FL	*107.10 FL
14	1		*FRONT WHEEL BEARING	Damaged	150.90 FL	*150.90 FL
15	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Distorted	342.20 FL	*342.20 FL
16	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	108.80 FL	*- FL
17	1		*FRONT DRIVE SHAFT (LH)	Distorted	1,030.80 FL	*1,030.80 FL
18	1		*RACK & PINION ASSY	Distorted	969.60 FL	*969.60 FL
19	1		*STG TIE END	Distorted	62.60 FL	*62.60 FL
20	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	529.30 FL	*529.30 FL
21	1		*KNUCKLE ARM (LH)	Distorted	552.00 FL	*552.00 FL
22	1		*ENGINE UNDER COVER	Not Necessary	334.60 FL	*- FL
23	1		*ENGINE CROSSMEMBER	Distorted	2,094.40 FL	*2,094.40 FL
24	1		*ABS SENSOR, LH	Not Necessary	234.00 FL	*- FL
25	1		*FRONT FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
26	1		*FRONT DOOR COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS
27	1		*FRONT DOOR ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
28	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS
29	1		*REAR FENDER WITH HOUSING (LH)	Dented	4,736.80 FL	*2,020.20 FL
30	1		*REAR FENDER INNER LINING (LH)	Not Necessary	169.30 FL	*- FL
31	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
32	1		*REAR DOOR (LH)	Buckled	2,201.10 FL	*2,201.10 FL
33	1		*REAR DOOR RUBBER (LH)	Necessary	280.50 FL	*280.50 FL
34	1		*REAR DOOR GEAR / REGULATOR (LH)	Cracked	242.80 FL	*242.80 FL
35	1		*REAR DOOR POWER MOTOR (LH)	Not Necessary	158.60 FL	*- FL
36	1		*REAR DOOR HINGE UPPER (LH)	Not Necessary	45.90 FL	*- FL
37	1		*REAR DOOR HINGE LOWER (LH)	Bent	45.90 FL	*45.90 FL
38	1		*REAR DOOR CHECK (LH)	Not Necessary	62.90 FL	*- FL
39	1		*REAR DOOR TRIM BOARD (LH)	Mtg Cracked	808.70 FL	*808.70 FL
40	1		*DOOR CENTRE PILLAR OUTER (LH)	Dented	2,527.80 FL	*2,527.80 FL
41	1		*ROCKER PANEL OUTER GARNISH (LH)	Dented	341.40 FL	*341.40 FL
42	1		*REAR TYRE RIM (LH)	Bent	325.30 FL	*325.30 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR WHEEL HUP-CAP (LH)	Bent	107.10 FL	*107.10 FL
44	1		*REAR WHEELBEARING ING & HUB	Damaged	362.00 FL	*362.00 FL
45	1		*REAR TRAILING ARM (LH)	Distorted	192.00 FL	*192.00 FL
46	1		*REAR ASSIST (LH)	Distorted	145.70 FL	*145.70 FL
47	1		*REAR SHOCK ABSORBER (LH)	Distorted	276.30 FL	*276.30 FL
48	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Not Necessary	81.30 FL	*- FL
49	1		*REAR UPPER ARM (LH)	Distorted	335.75 FL	*335.75 FL
50	1		*REAR LOWER ARM (LH)	Distorted	353.80 FL	*353.80 FL
51	1		*REAR KNUCKLE ARM (LH)	Distorted	545.60 FL	*545.60 FL
52	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
53	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
54	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
55	1		*REAR DOOR ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
56	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
57	1		*REAR TYRE (LH) (50%)	Cut	216.00 FS	*108.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,456.55	24,796.15
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,854.71	4,787.43
Total Parts (\$\$)	24,601.84	20,008.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	2,200.00	1,000.00
2	SPRAY PAINTING CHARGE.	New	1,800.00	1,000.00
3	WIRING CHARGE.	New	100.00	30.00
4	TUFF KOTE.	New	150.00	40.00
5	TOWING CHARGE.	New	50.00	0.00
6	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.	New	150.00	80.00
7	REMOVE / REFIX REAR WINDSCREEN GLASS.	New	120.00	80.00
8	REMOVE / REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
9	REMOVE / REFIX FUEL TANK.	New	150.00	0.00
10	TRANSFER OF DOOR.	New	240.00	120.00
11	REMOVE / REFIX UNDERCARRIAGE (RR)	New	200.00	150.00
12	FOUR WHEEL ALIGNMENT.	New	120.00	60.00
13	REMOVE / REFIX AIRCON & REFILL GAS.	New	150.00	0.00
14	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	New	480.00	0.00

Gross Labour Cost (\$\$)

6,110.00

2,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >