



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

ESTATE OF LIM CHA BO

Attention : THE OWNER
Contact : 91149280

Not Withheld
Lily & ?
Resurvey After Paint
3 days

Estimate : ES006466

Date : 08/10/2018
Vehicle Num. : SFY7502U
Make/Model : MAZDA 3-2005
Chassis/Eng# : JM6BK106100166664/Z6367093
Accident Date : 07/10/2018
Claim No. :
Reference :
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

1.	1	LIST ITEMS :
2.	1	BOOT LID
3.	2	BOOT LID LOCK
4.	4	TAIL LAMP
5.	2	TAIL LAMP CLIP
6.	1	BOOT LID SHOCK ABSORBER
7.	1	REAR END PANEL
8.	1	REAR END PANEL TOP GARNISH
9.	1	BOOT WEATHERSTRIP
10.	1	REAR BUMPER
11.	6	REAR BUMPER REINFORCEMENT
12.	2	REAR BUMPER CLIP
13.	2	REAR BUMPER BRACKET
14.	2	REAR BUMPER SIDE RETAINER
15.	1	REAR NUMBER PLATE LAMP
16.	2	REAR NUMBER PLATE LAMP GARNISH
		BOOT LID REFLECTOR

List TotalS\$:
15.00% Discount S\$:

<i>R</i>	992.00	<i>X</i>
<i>nu</i>	241.80	<i>✓</i>
<i>n/s</i>	392.00	784.00 <i>✓</i>
<i>n/s</i>	6.65	26.60 <i>✓</i>
	128.10	256.20 <i>X</i>
		686.30 <i>?</i>
<i>Dist</i>		262.00 <i>✓</i>
<i>R</i>	1,182.60	172.00 <i>500m</i>
		478.10 <i>✓</i>
<i>nu</i>	6.80	40.80 <i>✓</i>
	58.00	116.00 <i>?</i>
<i>n/s</i>	78.10	156.20 <i>✓</i>
	155.60	311.20 <i>✓</i>
		185.00 <i>?</i>
	284.00	568.00 <i>X</i>
		6,458.80
		968.82
		5,489.98

1.	1	SPECIAL NETT ITEMS :
2.	1	MAZDA 3 EMBLEM
3.	2	MAZDA LOGO
4.	1	REAR BUMPER REFLECTOR
5.	1	REVERSE SENSOR
6.	1	REAR NUMBER PLATE
		REAR NUMBER PLATE HOLDER

Special Nett Total S\$:

<i>nu</i>	68.50	<i>✓</i>
<i>nu</i>	69.00	<i>✓</i>
<i>CM</i>	120.00	240.00 <i>X</i>
<i>200m</i>		280.00
		25.00
<i>R</i>		33.00 <i>45m</i>
		715.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CONTINUE / ...



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

ESTATE OF LIM CHA BO

Estimate : ES006466

Attention : THE OWNER
Contact : 91149280

Date : 08/10/2018
Vehicle Num. : SFY7502U
Make/Model : MAZDA 3-2005
Chassis/Eng# : JM6BK106100166664/Z6367093
Accident Date : 07/10/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		RUST PROOFING TREATMENT		100.00
		CHANGE TAIL LAMP AND CHECK LIGHTING		65.00
		SPRAY PAINT DAMAGED AREA AFFECTED		1,100.00
		TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR		
		CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS		1,100.00
		Labour Total S\$:		2,365.00

SingDollars : Eight Thousand Five Hundred Seventy & Cents Forty-Eight Only

Total S\$: 8,570.48

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun