

CARTIMES

autolution



*Not Authorized
 U Rep B?
 Resurvey After Paint
 9 days*

pg.1....

VEHICLE NO:GBF 2079 E

MODEL:NISSAN NV200

QTY	DESCRIPTION	REPAIRER'S ESTIMATE(S\$)	SURVEYORS ADJUSTMENT(S\$)
NETT ITEM			
1	Rear bumper	B ₁ 650.00	✓
2	Rear bumper side retainers	ols D11 72.00	✓
1	Rear end panel outer	B ₁ 168.00	✓
1	Rear end panel inner	472.00	✓
1	Rear RHS taillamp	B ₁₀ 252.10	✓
2	Rear RHS & LHS bumper reflector	115.00	✓
1	Rear boot hinge top	R 105.00	X
1	Rear boot hinge lower	105.00	✓
1	Rear LHS boot lower lock	135.00	✓
1	Rear LHS boot top lock	135.00	✓
1	Rear RHS boot lower lock	135.00	✓
1	Rear RHS boot top lock	135.00	✓
1	Rear LHS boot	B ₁ 1281.10	✓
1	Rear RHS boot	B ₁ 960.90	✓
1	Rear RHS fender	R 1554.30	X
1	Rear bumper sponge	95.00	✓
1	Rear boot rubber	Cur 115.00	✓
1	Rear boot outer granish	Su 365.00	X
		6850.40	
		10% 685.04	
		6165.36	
SPECIAL NETT ITEMS			
1	Rear reverse sensor	Shon 280.00	200sn
1	sticker 70km/hour	Mei 15.00	✓
1	Sticker 6 pax	Me 15.00	125sn
1	Rear number plate/w holder	Su 45.00	X
1	Rear bumper clips	Me 60.00	✓
specila nett		415.00	
TOTAL PART		6580.36	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



CARTIMES

autolution

VEHICLE NO:GBG 6058 J

pg.2
MODEL:NISSAN NAVARA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYORS ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1000.00	900
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired (pearl white)	900.00	800
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	120.00	200
4	To remove & replace reverse sensor & check for proper function	120.00	500
5	To remove & refit rear windscreen	250.00	1200
5	To provide anti-rust treatment on affected areas	150.00	900
	Labour Total :	2540.00	
	TOTAL (PARTS & LABOUR):	9120.36	