

趙源摩哆 Chew Goon Motor

Bik 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Withheld
L1 Sup @ 6.7000
Paying After Paint
5 days

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 08.10.2018

Accident Date : 08.10.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Mercedes C200" Reg. No. SKK4742C Claiming Against Your Insured Reg. No. SJS8184G			
1pc	Front Bumper	4.00	1,170.00
10pcs	Front Bumper Clips	9.00	40.00
6pcs	Front Bumper Rivets		54.00
1pc	Front Bumper Corner Retainer RH		30.00
2pcs	Front Bumper Sensors	265.00	530.00
6pcs	Front Bumper Sensor Holders	16.00	96.00
2pcs	Front Bumper Sensor Rubber Ring	10.00	20.00
2pcs	Front Bumper Mouldings	76.00	152.00
1pc	Front Bumper Fog Lamp RH		285.00
1pc	Front Bumper Fog Lamp Cover		45.00
1pc	Front Bumper Fog Lamp Chrome		103.00
1pc	Front Bumper Top Retainer RH		13.00
1pc	Front Bumper Corner Holder RH		85.00
1pc	Front Bumper Reinforcement		310.00
1pc	Front Bumper Reinforcement Ext		33.00
1pc	Front Bumper Plastic Core		89.00
1pc	Front Bumper Sponge RH		170.00
1pc	Headlamp Assy RH (LED/HID)		2,600.00
1pc	Headlamp Panel (Aluminium)		245.00
1pc	Bonnet Emblem		80.00
1pc	Front Fender RH		885.00
1pc	Front Fender Badge		57.00
1pc	Front Fender Shield		293.00
5pcs	Front Fender Shield Clips	9.00	45.00
1pc	Front Fender Chrome Moulding		62.00
1pc	Front Wheel Rim (AMG)		1,635.00
1pc	Front Shock Absorber		620.00
1pc	Front Upper Arm		495.00
1pc	Front Knuckle Arm		675.00
1pc	Front Knuckle Arm Bearing		620.00
1pc	Front Lower Arm		355.00
1pc	Front Track Arm		536.00
			12,428.00
	Less 10%		1,242.80
			11,185.20
1pc	Fender Inner Sound Insulation		150.00 SN
			11,335.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

C/F

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 08.10.2018

Accident Date : 08.10.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Mercedes C200" Reg. No. SKK47420 Claiming Against Your Insured Reg. No. SJS8184G		
		B/F	11,335.20
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		30.00 201
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		nn 60.00 X
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		nn 250.00 X
	To Conduct Computerize Wheel Alignment Test		80.00 601
	To Conduct High Speed Balancing		70.00 201
	To Adaptation / Reprogram Headlamp LED		nn 150.00 X
	Labour Charge - Panel Beating, Repairing Of Bonnet, Headlamp Panel, Fender Inner Panel and Parts Replacement		600.00 500
	To Respray Affected Areas		900.00 600
		Total :	<u>13,475.20</u>