

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 9620K**AAD1810-095***Not Authorised*
1/Sup &

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHD 9620K

KL1LA69RJB107966

CHEVROLET

EPICA 2.0

5.10.2018

III**PART****LIST**

- | | | |
|----|---|-------------------------------------|
| 1 | 1 | Rear Bumper |
| 2 | 1 | Rear Bumper Beam |
| 3 | 1 | Rear Bumper Centre Absorber |
| 4 | 1 | Rear Bumper Side Retainer RH |
| 5 | 1 | Rear Bumper Side Retainer LH |
| 6 | 1 | Rear Bumper Reflectors RH |
| 7 | 1 | Rear Bumper Reflectors LH |
| 8 | 1 | Rear Bumper Tow Hook Cover |
| 9 | 1 | Rear End Panel Outer |
| 10 | 1 | Rear End Panel Inner Trim |
| 11 | 1 | Rear Luggage Floor Panel |
| 12 | 1 | Rear Luggage Floor Panel Insulator |
| 13 | 1 | Rear Luggage Floor Panel Trim Board |
| 14 | 1 | Bootlid |
| 15 | 1 | Bootlid inner trim board |
| 16 | 1 | Bootlid Weatherstrip |
| 17 | 1 | Bootlid Lock - Top |
| 18 | 1 | Bootlid 'CHEVROLET' Badge |
| 19 | 1 | Bootlid Logo |
| 20 | 1 | Bootlid 'EPICA LT' Badge |
| 21 | 1 | Bootlid Reflector Centre |
| 22 | 1 | Bootlid Reflector RH |
| 23 | 1 | Bootlid Reflector LH |
| 24 | 1 | Rear Tail Lamp RH |
| 25 | 1 | Rear Tail Lamp LH |
| 26 | 1 | Rear Exhaust Box (Muffler A-EXH,RR) |
| 27 | 1 | Rear Fender RH |
| 28 | 1 | Rear Fender Inner Trim RH |
| 29 | 1 | Rear Fender LH |

\$	Bu	1,202.00	—
\$	Bu	239.94	✓
\$	Sn	260.00	X
\$	Dis	68.76	—
\$	Sn	68.76	X
\$	CM	119.74	—
\$	Sn	119.74	X
\$	Sn	93.00	X
\$	Bu	623.76	✓
\$	Sn	263.84	X
\$	R	973.00	X
\$	Sn	63.50	X
\$	Sn	378.00	X
\$	Bu	973.00	✓
\$	Sn	400.00	X
\$	Gr	344.28	50% Sn
\$	R	466.56	X
\$	Sn	120.62	—
\$	Sn	138.84	—
\$	Sn	119.84	—
\$	Sn	217.97	X
\$	Sn	128.40	X
\$	Sn	128.40	X
\$	CM	479.30	✓
\$	Sn	479.30	X
\$	R	1,110.00	X
\$	R	1,145.00	X
\$	Sn	418.44	X
\$	R	1,145.00	X

Trans-cab Auto Services Pte Ltd

AAD1810-095

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9620K

30	1	Rear Fender Inner Trim LH	\$	<i>Sn</i> 418.44 X
----	---	---------------------------	----	--------------------

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Special Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>nn</i> 40.00 X
2	1Set	Rear Bumper Parking Sensor	\$	<i>Sn</i> 300.00 X
3	1Set	Rear Bumper Fastener Clip	\$	<i>na</i> 44.00 ✓
4	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i> 30.00 X
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i> 30.00 X
6	1	Rear Exhaust Mounting	\$	<i>Sn</i> 300.00 X
7	2	Rear Windscreen Sealant	\$	<i>nn</i> 80.00 X
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>na</i> 100.00 X
9	1	Spare Tyre	\$	<i>Sn</i> 180.00 X
10	1	Spare Wheel Rim	\$	<i>Sn</i> 126.74 X
11	1	Rear boot sticker 'Trans-cab'	\$	<i>nn</i> 80.00 — <i>30sn</i>
12	1	Rear boot sticker '6555-3333'	\$	<i>nn</i> 80.00 — <i>30sn</i>

TOTAL	\$	1,390.74
--------------	----	-----------------

TOTAL PARTS	\$	12,827.43
--------------------	----	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	3,500.00	<i>600</i>
----	----------	------------

To Check Electrical Lighting Concerned.

\$	170.00	<i>200</i>
----	--------	------------

To Rust-Proofing Of The Affected Areas.

\$	170.00	<i>600</i>
----	--------	------------

Putty And Spray Painting Of The Affected Portion.

\$	3,000.00	<i>600</i>
----	----------	------------

To reinstall rear bumper parking sensor.

\$	170.00	<i>600</i>
----	--------	------------

Trans-cab Auto Services Pte Ltd

AAD1810-095

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9620K

To transfer of end panel fittings and conduct
water seepage test. \$ 170.00 *601*

To transfer of boot fittings and conduct water
seepage test. \$ 170.00 *601*

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair. \$ 380.00 *601*

To check steering geometry and computer wheel
alignment \$ *nn* 220.00 *x*

\$ 7,950.00

TOTAL \$ 20,777.43

Repair Days (LUMP SUM)

~~10 DAYS~~
5 days