

INS. CASE OWNER:

3, EN 180 18450, fpa3 sz

LKK:

IDAG:

Surveyor:

KSL

DOI:

ASSIGNMENT

9-10-18

Date/Time:

9-10-18

Registered in Merimen:

Pre-assign / CCU / FTE

GBA 6364G



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(VL: YES / NO)

Insured Liability: %

Final ? Yes / No

SHC 5300R



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans-cab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

GBA 6364G x

SHC 5300R - 62/44090/1208/44090/1208/16/09

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

24/1/18 - Old rear ended up.

1/6/19 - fire -> MR to drive

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.: 2F.

If No or B 28, Ass. Lia:

Repair Cost: w/651

S\$

4475.50

Loss of Rental (LOR):

S\$

248.90

(25 days)

x \$ 91.32

Loss of Use (LOU):

S\$

(\$ - x - days)

Loss of Income (LOI):

S\$

125.00

(\$ 50 x 2.5 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/Independent)

Legal Cost

S\$

-

Total:

S\$

5356.25

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

5356.25

Name 1:

Transcend Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT 3/6/19

on 12/6/19

ASS. REC. BY:

REF:

EQ /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 1/2 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

100 File pass to Catherine

28/3 L1 Sm 846501 Confirmed Tension (2 1/2 x 99.32 + 125)

(Reel # 3528.319/88)

Veh No:

S17C 5300R

Yr Regn:

03, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude c.c.

1995

Colour:

M. White / R

A/C: Insured / Std / NI / NA

Sp. Reading

639847

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 276783

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

R/Bal.

2

mm

Rear

R/Bal.

2

mm

L/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

5/10/18

D.O.I.

9/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fixtios

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5300R**AAD1810-086**

Not Authorised
11 Sep @ 46501

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5300R

VF1ABL15AUC276783

RENAULT

LATITUDE

5.10.2018

EQ**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Br</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>nd/hr</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	} X
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	
5	1 BUMPR RETAINER RH REAR	\$	<i>Sn</i> 44.99	
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99	
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	
13	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77	} X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56	
15	1 TAILLAMP RH	\$	<i>Sn</i> 552.55	
16	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70	
17	1 TAILLAMP LH	\$	<i>Sn</i> 552.55	
18	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70	
19	1 BOOT REAR	\$	<i>R</i> 2,872.68	✓
20	1 BOOT FINISHER	\$	<i>Sn</i> 470.06	X
21	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	X
22	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	X
23	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	X
24	1 BOOT BADGE 'RENAULT'	\$	<i>R</i> 225.36	✓
25	1 BOOT BADGE	\$	<i>R</i> 225.36	✓
26	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	X
27	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	X
28	1 BOOT HINGE LH	\$	<i>R</i> 367.84	X
29	1 BOOT HINGE RH	\$	<i>R</i> 367.84	X

15015-21

Trans-cab Auto Services Pte Ltd

AAD1810-086

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5300R

30	1 BOOT INNER TRIM	\$	Sn 586.45 X
31	1 BOOT SWITCH	\$	Sn 168.13 X
32	1 BOOT LOCK	\$	N 202.67 X
33	1 BOOT LOCK CATCH	\$	N 74.40 X
		\$	16,046.87 16046.86
		10% \$	7.44
		\$	16,039.43 14442.17

Special Nett

1	1SET PARKING AID	\$	Sn 700.00 X
2	1SET REAR BUMPER CLIP	\$	na 66.00 ✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00 ✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00 X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na 20.00 X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na 10.00 X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00 ✓
10	1 EXHAUST MOUNTING REAR	\$	na 17.82 X
11	2 REAR WINDSCREEN SELANT	\$	na 80.00 X
12	1 WINDSCREEN MOULDING	\$	na 100.00 X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na 100.00 X
	TOTAL	\$	1,244.82

TOTAL PARTS	\$	17,284.25	15686.99
--------------------	----	------------------	----------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00 4001

Trans-cab Auto Services Pte Ltd

AAD1810-086

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5300R

To Rust-Proofing Of The Affected Areas.	\$	170.00	3ok
To reinstall rear bumper parking sensor.	\$	170.00	6ok
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	6ok
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	4 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
TOTAL	\$	6,610.00	

Over All Total \$ 39,933.69**(LUMP SUM)****Repair Days****10 DAYS****2 1/2 days**

27,296.99

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/EQ118018400/Kpa3

Date: 10/10/2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 5300R


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09.10.2018 at the premises of M/s Trans-cab Auto Services Pte Ltd have the following to report:-

Workshop Estimate Amount	: S\$	39,933.69
Revised Estimate Amount	: S\$	5,835.63
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	5,835.63
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, 18 May 2019 10:56 AM
To: 'jasminetan@transcab.com.sg'; Ng Wai Yin; claims@transcab.com.sg
Subject: Your ref: AAD1810-086 (SHC 5300R) *Our Ref: CC3/EQI18018400/Kpa3 [ACCIDENT INVOLVING GBA 6364G(EQ) AND SHC 5300R ON 05/10/2018]

Your ref: **AAD1810-086 (SHC 5300R)**
Our Ref: CC3/EQI18018400/Kpa3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING GBA 6364G(EQ) AND SHC 5300R ON 05/10/2018

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 4,975.50
2. Loss of Rental (2.5days x \$99.32)	\$ 248.30
3. Loss of Income (2.5days x \$50.00)	\$ 125.00
4. LTA/ GIA Search Fee	\$ 7.45
Total	<u>\$ 5,356.25</u>

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Jasmine Tan <jasminetan@transcab.com.sg>
Sent: Tuesday, 21 May 2019 6:45 PM
To: Hsiao Tong (LKKAUTO); 'Ng Wai Yin'; claims@transcab.com.sg
Subject: RE: Your ref: AAD1810-086 (SHC 5300R) *Our Ref: CC3/EQ18018400/Kpa3 [ACCIDENT INVOLVING GBA 6364G(EQ) AND SHC 5300R ON 05/10/2018]

Without Prejudice

Dear Hsiao Tong

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Saturday, 18 May 2019 10:56 AM
To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; Ng Wai Yin <waiyin.ng@transcab.com.sg>; claims@transcab.com.sg
Subject: Your ref: AAD1810-086 (SHC 5300R) *Our Ref: CC3/EQ18018400/Kpa3 [ACCIDENT INVOLVING GBA 6364G(EQ) AND SHC 5300R ON 05/10/2018]

Your ref: **AAD1810-086 (SHC 5300R)**
Our Ref: CC3/EQ18018400/Kpa3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING GBA 6364G(EQ) AND SHC 5300R ON 05/10/2018

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 4,975.50
2. Loss of Rental (2.5days x \$99.32)	\$ 248.30
3. Loss of Income (2.5days x \$50.00)	\$ 125.00
4. LTA/ GIA Search Fee	\$ 7.45
Total	\$ 5,356.25

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQI18018400/Kpa3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 13-06-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 6364G	Veh. Inspected	SHC 5300R
Policy No.	DMCPHQ18-001745	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/10/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC276783	Colour	METALLIC WHITE / RED
Odometer	639847	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	FALKEN	8 mm
L/H Front Tyre	215/60R16	FALKEN	8 mm
R/H Rear Tyre	215/60R16	FALKEN	8 mm
L/H Rear Tyre	215/60R16	FALKEN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/10/2018	Inspection Date	09/10/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2.500 Working Days
-------------------------------------	---------------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5300R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-

Report Ref No. CC3/EQI18018400/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
	LESS 10% DISCOUNT		-1,604.69	-520.07
			14,442.17	4,680.63
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	17.82	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
			1,244.82	165.00
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00

Report Ref No. CC3/EQ118018400/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE POF THE REPAIR OF BUMPER BEAM REAR, BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, OUTER PANEL REAR (END PANEL), TAILLAMP PANEL RH, TAILLAMP PANEL LH, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK AND BOOT LOCK CATCH.		2,200.00	400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			6,610.00	990.00
GRAND TOTAL			22,296.99	5,835.63
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,650.00

Report Ref No. CC3/EQ118018400/Kpa3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.