

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5300R**AAD1810-086***Not Authorised
1/1/2018*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5300R

VF1ABL15AUC276783

RENAULT

LATITUDE

5.10.2018

EQ**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>Not bu</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	} X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99	
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99	
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	
13	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77	} X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56	
15	1 TAILLAMP RH	\$	<i>Sn</i> 552.55	
16	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70	
17	1 TAILLAMP LH	\$	<i>Sn</i> 552.55	} X
18	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70	
19	1 BOOT REAR	\$	<i>Bu</i> 2,872.68	✓
20	1 BOOT FINISHER	\$	<i>Sn</i> 470.06	X
21	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	X
22	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	X
23	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	X
24	1 BOOT BADGE 'RENAULT'	\$	<i>R</i> 225.36	✓
25	1 BOOT BADGE	\$	<i>R</i> 225.36	✓
26	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	X
27	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	X
28	1 BOOT HINGE LH	\$	<i>R</i> 367.84	X
29	1 BOOT HINGE RH	\$	<i>R</i> 367.84	X

Trans-cab Auto Services Pte Ltd

AAD1810-086

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5300R

30	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45 X
31	1 BOOT SWITCH	\$	<i>Sn</i> 168.13 X
32	1 BOOT LOCK	\$	<i>n</i> 202.67 X
33	1 BOOT LOCK CATCH	\$	<i>n</i> 74.40 X
		\$	16,046.87
	10%	\$	7.44
		\$	16,039.43

Special Nett

1	1SET PARKING AID	\$	<i>Sn</i> 700.00 X
2	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00 ✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 ✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 X
5	1SET BUMEP R RETAINER RH CLIP RR	\$	<i>na</i> 20.00 X
6	1SET BUMEP R BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 X
7	1SET BUMEP R RETAINER CLIP LH RR	\$	<i>na</i> 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 ✓
10	1 EXHAUST MOUNTING REAR	\$	<i>na</i> 17.82 X
11	2 REAR WINDSCREEN SELANT	\$	<i>na</i> 80.00 X
12	1 WINDSCREEN MOULDING	\$	<i>na</i> 100.00 X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00 X

TOTAL \$ 1,244.82**TOTAL PARTS \$ 17,284.25****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>4401</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00 <i>4001</i>

Trans-cab Auto Services Pte Ltd**AAD1810-086**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5300R

To Rust-Proofing Of The Affected Areas.	\$	170.00	30k
To reinstall rear bumper parking sensor.	\$	170.00	60k
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60k
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	⚡ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	⚡ 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	⚡ 170.00	X
To check steering geometry and computer wheel alignment	\$	⚡ 220.00	X

TOTAL \$ 6,610.00**Over All Total \$ 39,933.69****(LUMP SUM)****Repair Days**~~10 DAYS~~

2 1/2 days