



Co. Reg: 200922097K GST Reg.No: 200922097K
 Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) #178
 • Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com

Date: 9/10/2018

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____ Total Pages: 1

Not Appraised here
n/s#
\$ day.
10/10/18
Take photo After repair

TO: AXA INSURANCE SINGAPORE PTE LTD
 8 Shenton Way
 #27-01 AXA Tower
 Singapore 068811

Our Customer: Silk Air (Singapore)
 Vehicle No: SFS96255
 Model: Toyota Vios
 Manufacture Year: 2005
 Date of Accident: 5/10/2018
 Total Estimate Repair Days: 8

P-2990.9
less 50%

1495.45
S.N + 15'.00
Labour + 1690.00

3200.45

Attn: Motor Claim Department
 Email: motor.survey@axa.com.sg

Re: Repair Estimate For Third Party Claim against SHD1485

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A. Spare Parts					
1	Rear no plate	1	\$50.00	\$50.00	SCA 15%
2	Rear trunk lid <i>584.20</i>	1	\$650.20	\$650.20	Scuff/Scr ✓
3	Rear trunk lid hinges	2	\$95.20	\$190.40	R X
4	Rear trunk lid lock	1	\$120.50	\$120.50	Tr. ✓
5	"Vios" emblem	1	\$38.10	\$38.10	RM ✓
6	"E" emblem	1	\$18.20	\$18.20	RM ✓
7	"WTTI" emblem	1	\$30.20	\$30.20	RM ✓
8	Trunk lid logo	1	\$72.10	\$72.10	RM ✓
9	Airport sticker	1	\$32.00	\$32.00	RM ✓
10	"1.5" emblem	1	\$23.90	\$23.90	RM ✓
11	Trunk lid weather strip <i>101.60</i>	1	\$310.10	\$310.10	Tr. / Tr. ✓
12	Rear bumper <i>341.70</i>	1	\$598.50	\$598.50	D.D ✓
13	Rear bumper clips	8	\$2.50	\$20.00	RM ✓
14	Rear bumper retainer	1	\$68.50	\$68.50	RM ✓
15	Rear end panel	1	\$590.50	\$590.50	Scuff/Scr ✓
16	Rear end panel top garnish	1	\$135.20	\$135.20	Tr. ✓
17	Rear spare tyre board ctr <i>188</i>	1	\$295.10	\$295.10	Torn ✓
18	Rear spare tyre compt LH board	1	\$82.10	\$82.10	RM X
19	RH taillamp <i>289.60</i>	1	\$380.10	\$380.10	RM ✓
20	LH taillamp <i>289.60</i>	1	\$380.10	\$380.10	RM ✓
21	Taillamp panel LH	1	\$120.10	\$120.10	R X
22	Panel joint sealant	2	\$25.00	\$50.00	RM ✓
				Sub Total	\$4,255.90
				Less 20%	\$851.18
				Sub Total 1	\$3,404.72
				Total Spare Parts	\$3,404.72
B. Labour					
1	To knock & straighten LHR chassis, spare tyre compt, cut & weld damaged panel, adjust & realign the same			\$1,300.00	700
2	To putty & spray both rear fender, trunk lid complete, rear bumper, end panel complete & rear spare tyre compt			\$1,300.00	900
3	To transfer trunk lid fitting & fixture and conduct water seepage test			\$180.00	60
4	To check wiring and all lighting			\$80.00	30
				Total Labour	\$2,860.00

1690



Co. Reg: 200922097K GST Reg.No: 200922097K
Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883
• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

		Total Repair Cost	\$6,264.72
	* The above quoted are exclusive of GST.		

Yours faithfully,

Darla
f Auto N Cars Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	

DATE	Remark From MR CHOO
6/9/2018	Please arrange for survey asap