

22/03/2002

ASS. REC. BY:

REF: CS/SMO18018405/Rlvdsⁿ² Special Instruction:Surveyor: Rani ASSIGNMENT (Office)From (Person): Thelma choo of SMO Date/Time: 10/10/18 @ 1:55pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLZ 589P Insured: FBH 8312Gat Workshop m/s Mova Automotive Tel: 62723892 / 97762311of Blk 1008, 8K Meruh Lane 3 # 01-04Policy No: D17MTMC01002135 Claim No: CMTD1804345

Sum Insured: Excess:

Make of Veh: D.O.A. 05/10/2018
(Client's Record)CA / REV / REP. / REV 24 HRS ^(up) H.O.D. Endorsement:Date/Time: 2:01pm @ 10/10/18 Person Contacted: Nitha Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLZ 589P - NBA / INC 18018099 / Y</u> D.O.A: <u>5/10/2018</u>
<u>15/10/18</u>	<u>Send preli revised via merimen</u>
<u>22/10/18</u>	<u>final fig \$4347.54, (Red 378.50, 1690) confirmed by email</u>

Signature: *[Signature]*

REF: SMO

70890

ASSIGNMENT

From: Date: 12.10.2018

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLZ 589P

at Workshop m/s: MOLA

of Blk 1008 Bukit Merah Lane 3 #01-04

Insured:

Policy No:

Claims No:

Sum Insured: Excess:


(Client's Record)

Make of Veh:

11.45 am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLZ 589P Yr Regn: 2018 / AYK

Type (M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN NOTE 1.2 CVA c.c. 1198

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 43 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMLTAE12Z080410

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front

Rear

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 05/10/18 D.O.I. 12/10/18

Survey held at: MOLA (RM)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 23 OCT 2018

[Signature]
19/10/2018

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

Date/Time: File Return to?

2) 22/10 - typist

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: merimen

Lump Sum / I.B.I.: (\$ 4347.54

) \$ + RS SI

) Photos

) Others

TOTAL

250
10

260

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Oct 2018 Sendback Est	10 Oct 2018 13:50 S\$5,253.04	10 Oct 2018 13:55 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	MUHAMMAD QUTHAM BIN ABDL MUTALIB, ID: S9305606Z		
Main Claimant:	LEE HAK SOON, ID: S1497089D		
Vehicle Reg. No.:	SLZ589P	Date of Loss:	05/10/2018 11:00 - :59 [5 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1804345	Policy/Cover Note No.:	D17MTMC01002135 (Third Party Only)
Vehicle Reg. No. (Insured):	FBH8312G	Policy No. (Claimant):	
		Excess:	
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/10/2018]		
Driver/Custodian (Insured):	MUHAMMAD KHIRZAIM BIN ABDUL KARIM (), NRIC: S87390298, Tel: +6582571932		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 15 Oct 2018

Preliminary Advice

Insured Vehicle No	: FBH8312G	Accident Date	: 05/10/2018
TP Vehicle No	: SLZ589P	Assignment Date	: 10/10/2018
Make	: NISSAN NOTE	Est. Duration of Repair	: 4.00
Date of Inspection	: 12/10/2018		
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) BLK 1008, #01-04/06/08/94, BUKIT MERAH LANE 3 SINGAPORE 159722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,253.04
Revised Amount	:S\$	4,113.26
Check Items (Estimated)	:S\$	134.28
Total	:S\$	4,247.54

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Vehicle survey on "Without Prejudice" basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/10/2018 14:12
Date Of Accident	05/10/2018 11:15
Exact Location Of Accident	ALONG LOWER DELTA ROAD TOWARDS SENTOSA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ589P
Insured/Policyholder	
Name Of Registered Owner	LEE HAK SOON
NRIC No	S1497089D
Email Address	GINBOBCOM@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96908070
Alternative Phone No	OTHERS-96908070

Vehicle Particulars

Manufacturer	NISSAN
Model	NOTE
Exact Purpose for which vehicle was being used at time of accident	DRIVING GRAB
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099986254
Cover Note Number	

Driver

Name of Driver	LEE HAK SOON
NRIC No	S1497089D
Date Of Birth	13/11/1961
Occupation	OUTDOOR
Date Of Driving Pass	09/07/1985
Driving Experience	33 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96908070
Fax Number	
Contact Number	OTHERS-96908070
Email Address	GINBOBCOM@GMAIL.COM

Address	BLK 101 BUKIT PURMEI ROAD #02-24
Postcode	090101
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBH8312G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	MUHAMMAD KHIRZAIM BIN ABDUL KARIM
NRIC/Passport Number	S8739029B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLN8235X
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As I was travelling along Lower Delta Road towards Sentosa. On approaching the junction of Lower Delta Road and Telok Blangah Way. A vehicle (SLN 8235X) signal to switch lane I slow down to allow the car to enter my lane. All of a sudden my car was hit on the right back by this motorcycle. This is all I have to say.

The vehicle that switch lane and causes this accident was vehicle No SLN 8235X.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

05/10/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0068854-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



TP INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)
MUHAMMAD QUTHAM BIN ABDUL MUTALIB
0
Singapore 0

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	D17MTMC01002135	Date of Loss:	05/10/2018
Vehicle Reg. No.:	SLZ589P	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	MUHAMMAD KHIRZAIM BIN ABDUL KARIM		
Make/Model:	NISSAN NOTE, 1.2 CVT (A)	Vehicle Reg. Date:	21/04/2018
Vehicle Colour:	GREY	Chassis No:	JN1TAAE12Z0980410
Engine No:	HR12284700B		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	30.00 %	Nett Item Discount:	10.00 %
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	PLEASE REFER TO REPORT ATTACHED.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	2,993.04
Miscellaneous Items	0.00
Labour	2,260.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	5,253.04
+ GST 7.00% (\$\$)	367.71
Nett Amount (\$\$)	5,620.75

This claim is handled by: AH WEI

Generated using Merlimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Oct 2018)

Parts: 144 NISSAN NOTE 1.2 CVT (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLZ589P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT	10.00	0.00	*1,345.40 FN <i>PH</i>
2	1		*REAR BOOT EMBLEM	10.00	0.00	*89.70 FN <i>Ne</i>
3	1		*REAR BOOT LOGO NOTE	10.00	0.00	*93.60 FN <i>Ne</i>
4	1		*REAR TAIL LAMP RH	10.00	0.00	*566.70 FN <i>Bro</i>
5	1		*REAR BUMPER RETAINER RH	10.00	0.00	*74.00 FN <i>Ne</i>
6	1		*REAR BUMPER	10.00	0.00	*814.00 FN <i>Ne</i>
7	1		*REAR REFLECTOR LIGHT GARNISH RH	10.00	0.00	*95.00 FN <i>X 77</i>
8	1		*REAR REFLECTOR LIGHT RH - <i>CHECK NN</i>	10.00	0.00	-
9	1		*REAR MUDFLAP RH	10.00	0.00	*101.20 FN <i>? 77</i>
10	10		*REAR MUDFLAP CLIPS	10.00	0.00	*48.00 FN <i>? 77</i>
11	10		*REAR BUMPER CLIPS	10.00	0.00	*48.00 FN <i>Ne</i>
12	1		*REAR FENDER RH - REPAIR <i>R</i>	10.00	0.00	-
13	1		*REAR WINDSCREEN SEALANT	0	0.00	*45.00 FS <i>Ne</i>

F=Franchise part, S=SpcNett, N=NettItemDisc.

Sub Total (\$\$) 3,320.60

- Nett Item Discount on N Items (\$\$) 327.56

Total Parts (\$\$) 2,993.04

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR REAR TAIL LAMP INNER PANEL RH, REAR FENDER RH, REAR WHEEL HOUSE RH. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS	New	800.00 500
2	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS	New	1,000.00 600
3	TO REMOVE REAR WINDSCREEN & REPLACE REAR WINDSCREEN	New	100.00
4	TO REMOVE & REPLACE REAR PARKING SENSORS & CHECK WIRING	New	60.00 40
5	TO REMOVE REAR BOOT MECHANISM, REAR BOOT LOCK & OTHER ATTACHMENT PARTS	New	100.00 60
6	TO REMOVE REAR SIDE TRIM BOARD L + R, SPARE TYRE & OTHER ATTACHMENT PARTS	New	120.00 100 ✓
7	TO RUST PROOF ACCIDENT AFFECTED AREAS	New	80.00 40
Gross Labour Cost (S\$)			2,260.00

Report was unsubmitted during this print-out.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rasul
 Hp 90010068
 4 days
 P/P
 12/10/18 @ 1150
 Resy 54 part

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Main Office: No. 22, Jalan Kilang, Singapore 159410
Tel: 6476 3333 Fax: 6271 5891

Service Centre: Block 1008, Bukit Merah Lane 3,
#01-04/08/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0068854-2

Mova Spray Centre
2K Over Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



INSURER: Sampo Insurance Singapore Pte. Ltd. (HQ)
MUHAMMAD QUTHAM BIN ABDUL MUTALIB
Singapore 0

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	D17MTMC01002135	Date of Loss:	05/10/2018
Vehicle Reg. No.:	SLZ589P	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	MUHAMMAD KHIRZAIM BIN ABDUL KARIM		
Make/Model:	NISSAN NOTE, 1.2 CVT (A)	Vehicle Reg. Date:	21/04/2018
Vehicle Colour:	GREY	Chassis No:	JN1TAAE12Z0980410
Engine No:	HR12284700B		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	30.00 %	Nett Item Discount:	10.00 %
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	PLEASE REFER TO REPORT ATTACHED.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	2,993.04
Labour	0.00
Paintwork Labour	2,260.00
Towing	0.00
	0.00
Gross Total (S\$)	5,253.04
+ GST 7.00% (S\$)	367.71
Nett Amount (S\$)	5,620.75

This claim is handled by: AH WEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Oct 2018)
 Parts: 144 NISSAN NOTE 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLZ589P)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT	10.00	0.00	*1,345.40 FN <i>Pt</i>
2	1		*REAR BOOT EMBLEM	10.00	0.00	*89.70 FN <i>rec</i>
3	1		*REAR BOOT LOGO NOTE	10.00	0.00	*93.60 FN <i>rec</i>
4	1		*REAR TAIL LAMP RH	10.00	0.00	*566.70 FN <i>Bto</i>
5	1		*REAR BUMPER RETAINER RH	10.00	0.00	*74.00 FN <i>ra</i>
6	1		*REAR BUMPER	10.00	0.00	*814.00 FN <i>sc</i>
7	1		*REAR REFLECTOR LIGHT GARNISH RH	10.00	0.00	*95.00 FN <i>X</i>
8	1		*REAR REFLECTOR LIGHT RH - CHECK	10.00	0.00	-
9	1		*REAR MUDFLAP RH	10.00	0.00	*101.20 FN <i>?</i>
10	10		*REAR MUDFLAP CLIPS	10.00	0.00	*48.00 FN <i>man?</i>
11	10		*REAR BUMPER CLIPS	10.00	0.00	*48.00 FN <i>ra</i>
12	1		*REAR FENDER RH - REPAIR	10.00	0.00	-
13	1		*REAR WINDSCREEN SEALANT	0	0.00	*45.00 FS <i>ra</i>

F=Franchise part, S=SpcNatl, N=NetItemDisc.

Sub Total (\$\$) 3,320.60
 - Nett Item Discount on N Items (\$\$) 327.56
Total Parts (\$\$) 2,993.04

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Parts \$ 3180.60

SN item \$ 45 SN

Labour \$ 1440

total \$ 4665.60 P/P 4 DAYS
 ————

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR REAR TAIL LAMP INNER PANEL RH, REAR FENDER RH, REAR WHEEL HOUSE RH. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS	New	800.00 500
2	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS	New	1,000.00 600
3	TO REMOVE REAR WINDSCREEN & REPLACE REAR WINDSCREEN	New	100.00
4	TO REMOVE & REPLACE REAR PARKING SENSORS & CHECK WIRING	New	50.00 40
5	TO REMOVE REAR BOOT MECHANISM, REAR BOOT LOCK & OTHER ATTACHMENT PARTS	New	100.00 60
6	TO REMOVE REAR SIDE TRIM BOARD L + R, SPARE TYRE & OTHER ATTACHMENT PARTS	New 100	120.00 X
7	TO RUST PROOF ACCIDENT AFFECTED AREAS	New	80.00 40
Gross Labour Cost (S\$)			2,260.00

Report was unsubmitted during this print-out
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

Rasul
Hp 90010068
4 days
P/P
12/10/18 @ 1150
Resy by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 22 October 2018 3:29 PM
To: 'Tan Yoong Wei'
Cc: SUR
Subject: RE: FINALISE SLZ589P

Dear Yoong Wei,

Noted with thanks.

Kindly send Final invoice and all supporting documents to SOMPO INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Yoong Wei <tanyw@moval.com.sg>
Sent: Monday, 22 October 2018 3:28 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: FINALISE SLZ589P

Hi
We accept the offer for part by pat \$4374.54 with 4 working days
Thank you.

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Monday, 22 October 2018 9:51 AM
To: Tan Yoong Wei; Rasul (LKKAUTO)
Cc: SUR
Subject: RE: FINALISE SLZ589P

Dear Yoong Wei,

WITHOUT PREJUDICE

Finalise cost of repair part by part should be \$4347.54 with 4 working days

Nett Items (less 10%) discount.

Please check and confirm.

Thank you.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Yoong Wei <tanyw@moval.com.sg>

Sent: Friday, 19 October 2018 12:24 PM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: FW: FINALISE SLZ589P

Hi rasul,

Please advice whether we can finalise cost of repair part by part \$4665.60 part by part with 4 working days?

Thank you.

Best Regards,

Tan Yoong Wei

Estimator

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18018405/R1VD3N2

Date: 26/10/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D17MTMC01002135
Claimant Vehicle No :	SLZ589P	Insured Vehicle No :	FBH8312G
Date of Loss:	05/10/2018	Nature of Claim:	TP
		Claim No:	CMTD1804345

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ589P	Engine No:	HR12284700B
Make & Model:	NISSAN NOTE, 1.2 CVT (A)	Chassis No:	JN1TAAE12Z0980410
Reg. Date:	21/04/2018 (Man. Year: 2018)	Odometer:	413 km
Colour:	Grey		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,993.04	2,907.54	85.50	2.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,440.00	820.00	36.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,253.04	4,347.54	905.50	17.24
+ GST 7.00/7.00% (\$\$)	367.71	304.33	63.38	17.24
Nett Amount (\$\$)	5,620.75	4,651.87	968.88	17.24

INSPECTION

Date of Assignment:	10/10/2018	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	12/10/2018	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2018)
Parts: 144	NISSAN NOTE 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLZ589P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,345.40 FN	*1,345.40 FN
2	1		*REAR BOOT EMBLEM	Necessary	89.70 FN	*89.70 FN
3	1		*REAR BOOT LOGO NOTE	Necessary	93.60 FN	*93.60 FN
4	1		*REAR TAIL LAMP RH	Broken	566.70 FN	*566.70 FN
5	1		*REAR BUMPER RETAINER RH	Necessary	74.00 FN	*74.00 FN
6	1		*REAR BUMPER	Scratched	814.00 FN	*814.00 FN
7	1		*REAR REFLECTOR LIGHT GARNISH RH	Not Necessary	95.00 FN	*- FN
8	1		*REAR REFLECTOR LIGHT RH - CHECK (NPA)	Not Necessary	-	-
9	1		*REAR MUDFLAP RH	Deformed	101.20 FN	*101.20 FN
10	10		*REAR MUDFLAP CLIPS	Necessary	48.00 FN	*48.00 FN
11	10		*REAR BUMPER CLIPS	Necessary	48.00 FN	*48.00 FN
12	1		*REAR FENDER RH - REPAIR (NPA)	Repair	-	-
13	1		*REAR WINDSCREEN SEALANT	Necessary	45.00 FS	*45.00 FS
F=Franchise part. S=SpcNett. N=NettItemDisc.						
Sub Total (\$\$)					3,320.60	3,225.60
- Nett Item Discount on N Items 10.00/10.00% (\$\$)					327.56	318.06
Total Parts (\$\$)					2,993.04	2,907.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR REAR TAIL LAMP INNER PANEL RH, REAR FENDER RH, REAR WHEEL HOUSE RH. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS	New	800.00	500.00
2	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS	New	1,000.00	600.00
3	TO REMOVE REAR WINDSCREEN & REPLACE REAR WINDSCREEN	New	100.00	100.00
4	TO REMOVE & REPLACE REAR PARKING SENSORS & CHECK WIRING	New	60.00	40.00
5	TO REMOVE REAR BOOT MECHANISM, REAR BOOT LOCK & OTHER ATTACHMENT PARTS	New	100.00	60.00
6	TO REMOVE REAR SIDE TRIM BOARD L + R, SPARE TYRE & OTHER ATTACHMENT PARTS	New	120.00	100.00
7	TO RUST PROOF ACCIDENT AFFECTED AREAS	New	80.00	40.00
Gross Labour Cost (S\$)			2,260.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >