COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHD 6548G

MAKE :

MODEL

: HYUNDAI i40

DATE 10/10/2018 14:26

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 553.00	
	Rear Bumper Clip 10 pcs			\$ 22.00	
	Rear Bumper Under Cover			\$ 228.00	
	SUB TOTAL			\$ 803.00	-
	LESS 20%			\$ 160.60	
	DISCOUNTED TOTAL			\$ 642.40	_
	*				
	Rear Bumper Rubber Mat			\$ 50.00	I
	Rear Bumper Advertisement Logo			\$ 50.00	I
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	
				\$ 300.00	
	Labour Charge			200	l
	Panel Beating			\$ 220.00	
	Spray Painting Charge			\$ 229.00	4
	Wiring Charge			\$ 30.00	7
	Remove/Refix Reverse Sensor			\$ 80,00	1
	TOTAL LABOUR			\$ 550.00	
	ESTIMATE TOTAL			\$ 1,492.40	
	10 1:1110h		heave notify		
	(a/wi/(l/y) // 10/10/18 1550h.	LKK Auto	Consultants hence notify fer of the following:		1
	1/ 1/2/50/	• To resurve	V Certification of tesur	vey	
	// 10/10/18 /33 h.	To display	damagovina	rae" basis	
		 Third par 	V SUIVEY IS ONE	1	
	2 1/72	Maillena	MARCHINE SERVICE AND ADDRESS OF THE PERSON ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON	- ind 200	1
	, ,	Suppler is subjet	entary (tem(s) must be resurved to final approval from Insura	nce Company	
	Us		dged by Repairer		
-400	Aller Reports	Acknowle Signatur	e:		
	When proper	Date:			
=1/					
91 11					
			or .		
				8	
	This is an initial estimate based on a visual inspection of th	1			