



# 簡福星摩多工廠

## KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147  
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428  
 E-mail: ryan@kanfs.net/ patricia@kanfs.net  
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883  
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

FWD SINGAPORE PTE LTD  
 6 TEMASEK BOULEVARD  
 #18-01 SUNTEC TOWER 4  
 SINGAPORE 038986  
 VEHICLE NO. : SGV188T  
 ACCIDENT DATE : 08-10-2018 08:30  
 THIRD PARTY REF. : SLF8488A

DATE : 10-10-2018

*not approved  
 here  
 n/s  
 10/10/18  
 when the other way*

ATTN: FWD SINGAPORE PTE LTD

ESTIMATE COST OF REPAIR TO VEICLE SGV188T HONDA AIRWAVE

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR BOOT COVER <i>Body</i>	1382.50 /
2	1	REAR BOOT CHROME	288.90 ?
3	1	REAR BOOT GARNISH <i>3rd/1st</i>	451.50 /
4	2	REAR BOOT REFLECTOR@\$245.30 <i>one</i>	490.60 /
5	1	REAR BOOT WINDSCREEN MOULDING <i>new</i>	80.00 /
6	1	REAR BOOT LOCK <i>D/S</i>	109.40 /
7	1	REAR BOOT RUBBER <i>twi</i>	191.20 /
8	2	REAR LAMP@\$258.00 <i>ms one absuc</i>	516.00 <i>one</i>
9	1	REAR BUMPER <i>ms/ae</i>	1078.50 /
10	2	REAR BUMPER SIDE RETAINE@\$25.00 <i>new</i>	50.00 /
11	1	REAR BUMPER BEAM <i>new</i>	90.00 /
12	10	REAR BUMPER CLIP@\$3.90 <i>new</i>	39.00 /
13	1	REAR END PANEL TOP GARNISH <i>D.S</i>	138.60 /
14	2	REAR NUMBER PLATE LAMP@\$32.50 <i>11</i>	65.00 x
15	1	FRONT BUMPER <i>ms/ae</i>	1045.50 /
16	1	FRONT BUMPER REINFORCEMENT <i>DD</i>	338.30 /
17	10	FRONT BUMPER CLIP@\$3.90 <i>new</i>	39.00 /
18	1	REAR BOOT TRIMBOARD <i>ms/one</i>	550.50 /
			<hr/>
			6,944.50
LESS 20 %			<hr/>
			1,388.90
TOTAL (A)			<hr/>
			5,555.60

SPECIAL NETT ITEMS

1	1	REAR WINDSCREEN GUM	<i>new</i> 40.00 /
---	---	---------------------	--------------------



# 簡福星噴漆工廠

## KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147  
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428  
 E-mail: ryan@kanfs.net/ patricia@kanfs.net  
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883  
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SGV188T  
 ACCIDENT DATE : 08-10-2018 08:30  
 THIRD PARTY REF. : SLF8488A

#	QTY	PARTS DESCRIPTION
2	1	REAR REVERSE SENSOR
3	1	REAR CAMERA
4	1	FRONT NUMBER PLATE

	AMOUNT (SG\$)
slub	300.00 200
slub	500.00 300
ref	30.00 ✓
<b>TOTAL ( C )</b>	<b>870.00</b>

### LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00	—
2	1	TO REMOVE/REFIT REAR WINDSCREEN GLASS	100.00	—
3	1	TO REMOVE/REFIT REAR FENDER INNER GARNISH & ETC	120.00	80
4	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	620.00	600
5	1	SPRAYPAINTING CHARGES	680.00	650
6	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (FRONT)	300.00	200
7	1	SPRAYPAINTING CHARGES (FRONT)	300.00	200

TOTAL ( D ) 2,150.00

ESTIMATE TOTAL 8,575.60

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: