

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0020415
Sodexo Kim Yew Pte Ltd

Page 1 of 1
Your ref. TP-SLA 3378T EQ
Job No. 69895
Our ref. 18.10.08
Payment
Date 9/10/2018

Attn

Vehicle No : SLK 7780K
Vehicle Model : Honda Odyssey
Accident on : 3/10/2018

Not Wash
Resurvey B & paint
2 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear bumper	440.00		440.00 ✓
1.00	Pc	Rear bumper reflector LH	32.00		32.00 ✓
Total amount of parts supplied - S\$472.00					
1.00		15% of parts supplied.	70.80		70.80
Special nett item:					
1.00	Set	Rear reversing sensor with installation	200.00		200.00 ✓
Labour & Misc:					
1.00		To remove and renew above parts	200.00		200.00 ✓
1.00		To spray paint (Pearl paint)	280.00		280.00 250

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Sub-Total 1,222.80
GST 7.00% 85.60
Total S\$ 1,308.40

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."