

BOTAK DEE AUTO

Repair for all kinds of Motor Vehicle
 Workshop : No. 10 Industrial Park 2A #04-01
 Ang Mo Kio Autopoint Singapore 568047
 Company Registration No. 53203907J
 HP : 91004390 / 91254449 Fax : 6484 1482
 Email : botakdeeauto@gmail.com

M/s AXA Insurance Singapore *Not Authorised*
 DATE 09.10.2018 *5 days*
 8 Shenton Way #27-01 CAR NO SJB 3696 T
 AXA Tower S068811 MAKE Honda Stream

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : SLS 9988 Z

Qty	Pcs	MRHGD86906P030195	UNIT PRICE	AMOUNT		
1	pc	Rear bumper	<i>bu</i>	\$1,280.00	✓	
1	pc	Rear bumper lower lip	<i>nsp</i>	\$605.00	X	
1	pc	Rear bumper beam	<i>nsp</i>	\$232.00	X	
1	pc	Rear bumper towing cover	<i>su</i>	\$35.00	X	
10	pcs	Rear bumper clips	<i>nu</i>	\$5.00	\$50.00	✓
2	pcs	Rear bumper side retainer	<i>old dir</i>	\$35.00	\$70.00	✓
2	pcs	Rear bumper side bracket	<i>n</i>	\$22.00	\$44.00	X
2	pcs	Rear bumper lamp	<i>nsp</i>	\$92.10	\$184.20	X
1	set	Rear bumper reverse sensor	<i>S/Nett</i>	<i>scr</i>	\$300.00	✓
1	pc	Rear boot lid cover	<i>bu</i>	\$1,050.00	✓	
1	pc	Rear boot lid top lock	<i>n</i>	\$205.00	X	
1	pc	Rear boot lid cover outer handle garnish	<i>su</i>	\$128.00	X	
1	pc	Rear boot lid cover Honda "H" logo	<i>nu</i>	\$39.00	X	
1	pc	Rear boot lid cover Honda "Stream" emblem	<i>nu</i>	\$45.00	✓	
1	pc	Rear wind screen moulding	<i>nu</i>	\$56.00	✓	
1	pc	Rear exhaust silencer	<i>n</i>	\$506.50	X	
1	pc	Centre muffler	<i>n</i>	\$483.50	X	
1	pc	Rear end panel		\$486.00	?	
1	pc	Rear end panel top garnish		\$231.10	?	
1	pc	Rear number plate with casing	<i>bu</i>	\$60.00	X	
1	pc	Rear spare tyre bracket holder		\$285.00	?	
1	pc	Rear spare tyre retainer bracket hook	<i>bu</i>	\$70.00	X	
1	pc	Rear right side tail lamp	<i>CM</i>	\$460.00	✓	
				<i>2 of</i>		
				<i>flr</i>		
				Total		

BOTAK DEE AUTO

Repair for all kinds of Motor Vehicle
 Workshop : No. 10 Industrial Park 2A #04-01
 Ang Mo Kio Autopoint Singapore 568047
 Company Registration No. 53203907J
 HP : 91004390 / 91254449 Fax : 6484 1482
 Email : botakdeeauto@gmail.com

M/s AXA Insurance Singapore DATE 09.10.2018
8 Shenton Way #27-01 CAR NO SJB 3696 T
AXA Tower S068811 MAKE Honda Stream

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : SLS 9988 Z

Qty	Pcs	MRHGD86906P030195	UNIT PRICE	AMOUNT
		Continue from page one		\$6,905.30
		Spraying anti-rust coating onto new and affected panels.		\$150.00 ?
		Labour for jacking, knocking, straightening and realigning of affected area and replacing the above mentioned parts.		\$1,500.00 ?
		To apply silicon onto rear wind screen.		na \$60.00 ⁴⁰⁰⁰
		Dismantle and refix rear wind screen.		\$150.00 ¹²⁰⁰
		Labour for respray rear bumper, rear boot lid cover (inner & outer), rear end panel and rear two side mudguard.		800 \$1,500.00
		To checking, dismantle and replace rear exhaust box.		na \$150.00 X
			Total	\$10,415.30


 BOTAK DEE AUTO.

Page 2 of 2

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: