

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1160/2018/GW
Date : 11-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no: SLQ 6709 T

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Alatas Singapore Pte Ltd
Address : 1 International Business Park
#03-01E, Synergy
Singapore 609917
Telephone : HP +65 997360225
Type of Claim : Third Party Claims
Policy No. : 5077402437-02
Vehicle No : **SJY 4646 K**
Model Code : Audi A4 1.8 TFSI
Model / Year : Nov-08
Engine No : CDH026741
Chassis No : WAUZZZ8K99A128135
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Oct-18
Place of Accident : Along Road 1 Pan Island Expressway

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJY 4646 K

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer Assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper. Re-organise front crash management components. Reinstall all parts removed.	\$ 900.00 500
3	To respray front bumper.	\$ 800.00 450
TOTAL LABOUR CHARGES - FRONT		: \$ 2,060.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJY 4646 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	
1	FRONT BUMPER <i>reformed</i>	\$	2,394.00 ✓
2	FRONT BUMPER FIXING PARTS	\$	222.00 ✗
3	FRONT BUMPER GUIDE SECTION-LH/RH <i>} new</i>	2 \$	74.00 ✗
4	FRONT BUMPER SECURING STRIP	2 \$	60.00 ✗
5	FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE <i>} new</i>	\$	167.00 ✗
6	FRONT BUMPER PULL STRAP-LOWER	\$	44.00 ✗
7	FRONT BUMPER SPOILER-LOWER <i>cut</i>	\$	292.00 ✓
8	FOAM FILLER PIECE <i>new</i>	\$	107.00 ✗
9	FRONT BUMPER SIDE REINFORCEMENT <i>new</i>	\$	770.00 ✗
10	FRONT BUMPER SUPPORT-LH/RH <i>} new</i>	2 \$	48.00 ✗
11	FRONT BUMPER VENT GRILLE-LH/RH <i>} new</i>	2 \$	236.00 ✗
12	FRONT BUMPER COVER	\$	84.00 ✗
13	RADIAOTOR GRILLE <i>cut</i>	\$	595.00 ✓
14	RADIAOTOR GRILLE COVER <i>new</i>	\$	50.00 ✗
TOTAL PARTS CHARGES - FRONT		:	\$ 5,143.00
TOTAL LABOUR CHARGES - FRONT		:	\$ 2,060.00
GRAND TOTAL PARTS AND LABOUR - FRONT		:	\$ 7,203.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJY 4646 k.

S/N	Nature of Jobs		Estimated Charges	
1	To remove and transfer rear parking aid. Check function.	S/N \$	280.00	✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00	X.
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$	480.00	X
4	To dismantle and renew rear bumper and rear lid. To cut out and reweld end panelling.re-organize rear crash management components. Reinstall all parts removed.	\$	3,600.00	1250
5	To respray rear bumper, rear lid and end panelling . To carry out joint sealant work and stone chip treatment.	\$	2,500.00	1650
6	To carry out diagnostic check.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES - REAR			: \$	<u><u>7,332.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJY 4646 K

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/Nett</u>	
1	REAR BUMPER <i>Distorted</i>	\$ 1,621.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 195.00	X
3	REAR BUMPER CARRIER <i>?</i>	\$ 563.00	?
4	REAR BUMPER HOLDER BRACKET-LH/RH <i>new</i>	2 \$ 382.00	+
5	REAR BUMPER SPOILER <i>Dehnd</i>	\$ 333.00	✓
6	REAR BUMPER GUIDE SECTION-LH/RH <i>new</i>	2 \$ 75.00	+
7	REAR BUMPER UPPER GUIDE SECTION-LH/RH <i>new</i>	2 \$ 39.00	+
8	REAR BUMPER TRIM <i>Dehnd</i>	\$ 222.00	✓
9	REAR BUMPER SECURING STRIP <i>new</i>	\$ 11.00	X
10	REAR LID <i>Repair</i>	\$ 1,923.00	+
11	REAR LID ATTACHMENT PARTS <i>new</i>	\$ 133.00	X
12	REAR LID HINGE-LH/RH <i>new</i>	2 \$ 496.00	X
13	REAR LID GASKET FLAP <i>new</i>	\$ 176.00	+
14	REAR LID TOP BUFFER	5 \$ 57.00	X
15	REAR LID LOCK	\$ 190.00	X
16	REAR LID LOCK COVER	\$ 17.00	✓
17	REAR LID LOCK STRIKER	\$ 44.00	X
18	REAR LID PUSH BUTTON FOR ELECTRIC <i>HP</i>	\$ 159.00	X
19	REAR LID STOP BUFFER, ADJUSTABLE <i>HP</i>	2 \$ 48.00	X
20	REAR LID STOP BUFFER CAP	2 \$ 13.00	X
SUB-TOTAL PARTS CHARGES - REAR		\$ 6,697.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJY 4646 K.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/Nett</u>	
21	PACKING ADHESIVE <i>neu</i>	\$	29.00 ✓
22	AUDI EMBLEM <i>neu</i>	\$	108.00 ✓
23	REAR LID TRIM PANEL <i>neu</i>	\$	344.00 ✗
24	REAR CROSS PANEL TRIM <i>neu</i>	\$	160.00 ✗
25	LUGGAGE COMPARTMENT, FLOOR COVERING <i>neu</i>	\$	618.00 ✗
26	TAILLIGHT-LH <i>cracked</i>	\$	321.00 ✓
27	TAILLIGHT BULB-LH <i>neu</i>	2 \$	9.00 ✗
28	REAR CROSS PANEL-OUTER <i>3 repair</i>	\$	275.00 ✗
29	REAR CROSS PANEL-LOWER <i>3 repair</i>	\$	765.00 ✗
30	REAR BUMPER REINFORCEMENT ?	\$	468.00 ?
31	ACYLIC SEALANT <i>3</i>	S/N \$	180.00 ✗
32	CAVITY WAX <i>3</i>	S/N \$	140.00 ✗
33	STONE CHIP <i>3</i>	S/N \$	180.00 ✗
34	FRONT NO. PLATE <i>neu</i>	S/N \$	25.00 ✓
35	REAR NO. PLATE <i>neu</i>	S/N \$	25.00 ✗
36	SUNDRIES ?	\$	500.00 ?
Materials frt/rr		:	\$ 15,987.00
Labour charges frt/rr		:	\$ 9,392.00
Total frt/rr		:	\$ 25,379.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling -
Surveyed Date : 16/10/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : not authorized, 08 Days.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant