

Surveyor:

Mappins

DOI:

ASSIGNMENT

25/10/18

Date / Time:

9-10-18

Registered in Mexico:

Fre-assign / CCU / FTE

GBD 86638



Insured Vehicle No.:

Claim No.:

58MWD YH9

Name of Insured:

FORWATERS & DELIVERY Agency
SG PLU

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

22/09/2018

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

GBB 24942



INSRS:

WSP:

Tel:

Liability:

RMKS:

Thank One



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(3

x

days)

Loss of Income (LOI):

S\$

(3

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

WP REPORT
4250.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT
23/12/19

REF: **ASMUNXA)**

REF: **ASMUNXA)**

ASSIGNMENT

From: **25/10/2018**

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / IIV / MV

To inspect Vehicle No. **GBB 2494K**

at Workshop no:

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

4pm - 430pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

50k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

0347C

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBB 2494K

Yr Regn:

1008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

Toyota

cc - 2982

Colour:

silver

A/C

Insured / Std / NI / NA

Sp. Reading

236488

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02P900032344

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

5

mm

D.O.A.

27/9/18

D.O.I.

25/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

see ent. 28-10-2018 LIA 29373

L/S \$ 2,000.00

CRMP. \$ 15,491.25 (88%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

not attached
LKL
L/S
The photo is up
3 dy.
25/10/18

GBB2494K Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy	\$ 1,618.00 X
2	1	Front bumper tow cover	\$ 85.00 X
3	1	Front bumper left bracket	\$ 122.00 X
4	1	Front bumper reinforcement	\$ 630.00 X
5	2	Front bumper reinforcement support	\$ 184.00 X
6	1	Front bumper reinforcement centre crossmember	\$ 279.00 X
7	1	Front bumper lower grille	\$ 310.00 X
8	1	Front left headlamp	\$ 2,680.00
9	1	Front headlamp left bracket	\$ 63.00 X
10	1	Front left fog lamp	\$ 255.00 X
11	1	Front left fog lamp cover	\$ 78.00 X
12	1	Front grille assy	\$ 493.00 X
13	1	Front bonnet assy	\$ 2,389.00 X
14	1	Front bonnet emblem	\$ 120.00 X
15	2	Front bonnet stopper	\$ 68.00 X
16	1	Front bonnet lock	\$ 171.00 X
17	1	Front bonnet lock brace panel	\$ 116.00 X
18	2	Front bonnet hinges	\$ 188.00 X
19	1	Front top support panel assy	\$ 1,654.00 X
20	1	Front support panel top garnish seal	\$ 86.00 X
21	1	Front secondary radiator assy	\$ 1,129.00 X
22	1	Front secondary radiator cooling fan assy with motor	\$ 923.00 X
23	1	Front washer tank	\$ 192.00 X
24	1	Front left corner panel	\$ 283.00
25	1	Front left wing mirror assy	\$ 320.00 X
26	1	Front left door panel	\$ 1,858.00 X
27	1	Front left door lower step garnish	\$ 296.00 X
28	1	Front left door regulator linkage with motor	\$ 480.00 X
29	1	Front left door weatherstrip	\$ 288.00 X
30	1	Front left door outer handle	\$ 176.00 X
31	1	Front left door lock mechanism	\$ 245.00 X
32	1	Front left door outer moulding	\$ 196.00 X
			\$ 17,975.00
Less 25% 8070			\$ 4,493.75
			\$ 13,481.25

Think One Autocare Pte Ltd
 No.18 Defu Avenue 2
 Singapore 539522
 Tel: 6844 3300 Fax: 6842 4988

GBB2494K Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	12	Front bumper clips	11 \$ 50.00 X
2	6	Front grille clips	11 \$ 30.00 X
3	1	Front radiator coolant	11 \$ 80.00 X
4	1	Front left door company sticker	11 \$ 50.00 30
5	1	Front no plate	11 \$ 80.00 X
			<u>\$ 290.00</u>
Total parts			\$ 13,771.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Think One Autocare Pte Ltd
 No.18 Defu Avenue 2
 Singapore 539522
 Tel: 6844 3300 Fax: 6842 4988

GBB2494K Toyota Hiace

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten front and front left affected area and replace front damaged parts.	\$ 1,400.00	400
2	To putty and spray painting front and front left portion.	\$ 1,400.00	600
3	To check wiring and focus front headlamp.	\$ 50.00	20
4	To remove and install front bonnet lock mechanism.	\$ 1780.00	X
5	To apply anti rust proofing to front and front left affected area.	\$ 17150.00	X
6	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 17250.00	X
7	To remove and install front left door lock mechanism.	\$ 1780.00	X
8	To check door central locking for function.	\$ 1780.00	X
9	To transfer door glass to new door.	\$ 1780.00	X
10	Towing service.	\$ 17150.00	X
		<u>\$ 3,720.00</u>	

Total parts : \$ 13,771.25
 Total labour : \$ 3,720.00
 Total repair cost : \$ 17,491.25

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0347C
Vehicle Details	
Vehicle No.:	GBB2494K
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1KD1867480
Chassis No.:	JTFHT02P900032344
Maximum Power Output:	-
Open Market Value:	\$24,647.00
Original Registration Date:	29 Oct 2008
First Registration Date:	29 Oct 2008
Transfer Count:	1
Actual ARF Paid:	\$1,233.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Oct 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$29,397.00
COE Rebate Amount:	\$29,373.00
Total Rebate Amount:	\$29,373.00

The information contained herein is correct as at 30 Oct 2018

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Hiace

Price Range

Depreciation

> 10 year(s)

Vehicle Type



Advanced Search

Home » Used Cars » Quality Auto Hub » Toyota Hiace (COE till 07/2027)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Commercial Vehicle

BRAND NEW FLEET AVAILABLE FOR RENT / LEASE

CALL: 8482 3003

EMAIL: sales@sgcarrenting.com.sg

Locus Habitat SINGAPORE



UP TO 40% OFF



NOW AV In Size

Compare

Toyota Hiace (COE till 07/2027)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$49,800**Depreciation** \$5,740 /yr**Reg Date** 03-Jul-2007
(Byrs 8mths 2days COE left)**Lifespan** 02-Jul-2027**Manufactured** 2007**Mileage** 200,232 km (17.7k /yr)**Transmission** Auto**Engine Cap** 2,982 cc**Curb Weight** 1,760 kg**Fuel type** Diesel**Features** The Most Reliable Commercial Vehicle In The Market. Now! Provide You With Quality Performance, Definite Asset To Your Business.**Accessories** New Paint, Regularly Maintained By Careful Owner. Payload Up To 1 Ton, Reliable Japanese Engine/Highly In Demand Van Model. Welcome For Test Drive!**Description** Auto Transmission, Easy Loan Cheapest In The Market! Well Maintained By Previous Owner, No Repairs Needed! Wear And Tear Replaced And Very Low Maintenance! Definitely A Workhorse For Your Company Needs. High Trade And Flexible Loan Available. No Hidden Fees.**COE** \$34,070**OMV** \$26,106**Dereg Value** \$29,562 as of today (change)**No. of Owners** 2**Type of Veh** Van**Category** COE Car**Availability** Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 29-Oct-2018 | Last Updated on: 29-Oct-2018

Tags: Toyota Hiace, toyota hiace, 2007 Toyota Hiace, 2007 toyota hiace, Toyota, Hiace, hiace, Used Toyota

Upfront Payment:

= more Financial info

Transfer Fee \$25**Down Payment** \$4,980 (change)

Maximum 90% Loan

1st Instalment \$1,102**Total Upfront Payment** \$6,107 (excluding insurance)

Seller Information

Company

Quality Auto Hub

• dealer's pricelist
• 13 vehs sold | 4 vehs available**Address**

317 Outram Road #B1-37

Search cars nearby this location

Location

Concorde Shopping Centre

Contact Person(s) Yap

90662292

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Vic (LKKAUTO)

From: michaelng@thinkone.com.sg
Sent: Friday, 20 December, 2019 12:49 PM
To: Vic (LKKAUTO)
Subject: RE: GBB2494K & GBD8663P ACCIDENT DATED ON 27.09.2018 *LKK REF: CC4/ASM18018428/Uha3

Importance: High

Dear Vic,

We withdraw this case and close the file

Thank you

From: Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Sent: Thursday, 19 December, 2019 11:33 AM
To: karentan@thinkone.com.sg
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; michaelng@thinkone.com.sg
Subject: RE: GBB2494K & GBD8663P ACCIDENT DATED ON 27.09.2018 *LKK REF: CC4/ASM18018428/Uha3

Without Prejudice

Dear Karen,

We refer further to our below email.

Please furnish us any evidence to support your client's claim for our further action.

Thank you.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Hsiao Tong (LKKAUTO)
Sent: Monday, 24 December, 2018 3:47 PM
To: karentan@thinkone.com.sg

Cc: Joy Irene (LKKAUTO); Admin A

Subject: RE: GBB2494K & GBD8663P ACCIDENT DATED ON 27.09.2018 *LKK REF: CC4/ASM18018428/Uja3

Importance: High


Without Prejudice

Hi Karen,

We refer to your below email.

Please be informed that liability is unclear. Our insured driver reported that "**No Collision**". Kindly refer to the attached insured's statement for your easy reference.

Kindly let us have evidences (ie: video footage/ scene photos / PIR) in order for us to look into the matter.

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT
ON The 12 October 2018, I receive a letter from my company that stated I was involved in a Hit and run accident on 27 th September 2018, 2.15pm at Rivervale. I was the driver on the 27 th September 2018. But I did not recall hitting any vehicles or anyone. COS on that day I have about 10-15 locations to deliver within a short period of time. To my understanding, if there are such incidents happened there will be damages of a bump but there isn't

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Karen Tan <karentan@thinkone.com.sg>
Sent: Friday, 21 December 2018 4:21 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: FW: RE: GBB2494K & GBD8663P ACCIDENT DATED ON 27.09.2018
Importance: High

Hi Hsiao Tong,

Please assist.

Thank you.

Karen Tan
Claim Advisor
Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
HP : 9128 8488
DID : 6844 3300 FAX : 6842 4988

From: Karen Tan <karentan@thinkone.com.sg>
Sent: Friday, 21 December, 2018 4:02 PM
To: 'Joy Irene (LKK Auto)' <JoyIrene@lkkauto.com>
Subject: RE: GBB2494K & GBD8663P ACCIDENT DATED ON 27.09.2018
Importance: High

Hi Joy,

I would like to check on the above mentioned liability.

Thank you.

Karen Tan
Claim Advisor
Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
HP : 9128 8488
DID : 6844 3300 FAX : 6842 4988

Catherine Chong (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 9 October, 2018 6:22 PM
To: assignments
Subject: FW: AXA Ref: S8M00YH9MC/RA. PRI survey of GBB2494K at Think One
Attachments: TP SAS Report.pdf; PRI.pdf

From: ANG Richard <richard.angbs@axa.com.sg>
Sent: Tuesday, 9 October, 2018 6:18 PM
To: Admin A <admin-a@lkkauto.com>
Subject: AXA Ref: S8M00YH9MC/RA. PRI survey of GBB2494K at Think One

Hi LKK,

Please appoint Marcus to attend to the PRI survey.

Ins'd has not reported the accident to us yet.

Thank you.

Regards,

Richard Ang | Specialist, Motor (Property) Claims
AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: richard.angbs@axa.com.sg
Customer Care No. 1800 8804888

*10.10.2018 @ 9:58am
Karen reh not in.*



**GLOBAL INSURANCE
BRAND
FOR THE 8TH
CONSECUTIVE YEAR**

Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

DHAKAL Raghav

From: Karen Tan <karentan@thinkone.com.sg>
Sent: Monday, October 08, 2018 1:49 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: RE: GBB2494K & GBD8663P ACCIDENT DATED ON 27.09.2018
Attachments: SAS2483105.PDF

Importance: High

Categories: Raghav

Dear Sir/Mdm,

I would like to arrange a surveyor for GBB2494K as my client is claiming against your insured GBD8669P for the above mentioned accident.

Thank you.

Karen Tan
Claim Advisor
Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
HP : 9128 8488
DID : 6844 3300 FAX : 6842 4988



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

11 October, 2018

FORWARDERS & DELIVERY AGENCY SINGAPORE (PTE) LTD

1 BUROH LANE

#02-5A

SINGAPORE 618292

Dear Sir,

OUR REF : CC4/ASM18018428/ja3 // S8M00YH9

YOUR REF : GBD 8663P

**ACCIDENT INVOLVING GBD 8663P & GBB 2494K ON 27/09/2018 ALONG/AT
INSIDE RIVERVALE CRESENT LOADING / UNLOADING BAY**

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18018428/Uha3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:RICHARD ANG

Date : 16-01-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 8663P	Veh. Inspected	GBB 2494K
Policy No.	VFX/P2129073	Coverage (\$)	0.00
Claim No.	S8M00YH9	Excess (\$)	0.00
Assign From		Assign Date	09/10/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JTFHT02P900032344	Colour	SILVER
Odometer	236498	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	FIRESTONE	5 mm
L/H Front Tyre	195 R15	FIRESTONE	5 mm
R/H Rear Tyre	195 R15	FIRESTONE	5 mm
L/H Rear Tyre	195 R15	FIRESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/09/2019	Inspection Date	25/10/2018
Survey held at	THINK ONE AUTOCARE PTE LTD NO.18 DEFU AVENUE 2 SINGAPORE 539522		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 2494K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER ASSY (CONSISTENT)	TO REPAIR SEE LABOUR	1,618.00	-
1	FRONT BUMPER TOW COVER (CONSISTENT)	NOT NECESSARY	85.00	-
1	FRONT BUMPER LEFT BRACKET (CONSISTENT)	NOT NECESSARY	122.00	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	630.00	-
2	FRONT BUMPER REINFORCEMENT SUPPORT (CONSISTENT)	NOT NECESSARY	184.00	-
1	FRONT BUMPER REINFORCEMENT CENTRE CROSSMEMBER (CONSISTENT)	NOT NECESSARY	279.00	-
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	NOT NECESSARY	310.00	-
1	FRONT LEFT HEADLAMP (CONSISTENT)	SCRATCHED	2,680.00	2,680.00
1	FRONT HEADLAMP LEFT BRACKET (CONSISTENT)	NOT NECESSARY	63.00	-
1	FRONT LEFT FOG LAMP (CONSISTENT)	NOT NECESSARY	255.00	-
1	FRONT LEFT FOG LAMP COVER (CONSISTENT)	NOT NECESSARY	78.00	-
1	FRONT GRILLE ASSY (CONSISTENT)	NOT NECESSARY	493.00	-
1	FRONT BONNET ASSY (CONSISTENT)	NOT NECESSARY	2,389.00	-
1	FRONT BONNET EMBLEM (CONSISTENT)	NOT NECESSARY	120.00	-
2	FRONT BONNET STOPPER (CONSISTENT)	NOT NECESSARY	68.00	-
1	FRONT BONNET LOCK (CONSISTENT)	NOT NECESSARY	171.00	-
1	FRONT BONNET LOCK BRACE PANEL (CONSISTENT)	NOT NECESSARY	116.00	-
2	FRONT BONNET HINGES (CONSISTENT)	NOT NECESSARY	188.00	-
1	FRONT TOP SUPPORT PANEL ASSY (CONSISTENT)	NOT NECESSARY	1,654.00	-
1	FRONT SUPPORT PANEL TOP GARNISH SEAL (CONSISTENT)	NOT NECESSARY	86.00	-
1	FRONT SECONDARY RADIATOR ASSY (CONSISTENT)	NOT NECESSARY	1,129.00	-
1	FRONT SECONDARY RADIATOR COOLING FAN ASSY WITH MOTOR (CONSISTENT)	NOT NECESSARY	923.00	-
1	FRONT WASHER TANK (CONSISTENT)	NOT NECESSARY	192.00	-
1	FRONT LEFT CONRRER PANEL (CONSISTENT)	DENTED	283.00	283.00
1	FRONT LEFT WING MIRROR ASSY (CONSISTENT)	NOT NECESSARY	320.00	-
1	FRONT LEFT DOOR PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,858.00	-

Report Ref No. CC4/ASM18018428/Uha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LEFT DOOR LOWER STEP GARNISH (CONSISTENT)	NOT NECESSARY	296.00	-
1	FRONT LEFT DOOR REGULATOR LINKAGE WITH MOTOR (CONSISTENT)	NOT NECESSARY	480.00	-
1	FRONT LEFT DOOR WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	288.00	-
1	FRONT LEFT DOOR OUTER HANDLE (CONSISTENT)	NOT NECESSARY	176.00	-
1	FRONT LEFT DOOR LOCK MECHANISM (CONSISTENT)	NOT NECESSARY	245.00	-
1	FRONT LEFT DOOR OUTER MOULDING (CONSISTENT)	NOT NECESSARY	196.00	-
	LESS 25% DISCOUNT		-4,493.75	-
	LESS 50% DISCOUNT		-	-1,481.50
			13,481.25	1,481.50
	<u>SPECIAL NETT ITEMS</u>			
12	FRONT BUMPER CLIPS (SN)(CONSISTENT)	NOT NECESSARY	50.00	-
6	FRONT GRILLE CLIPS (SN)(CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT RADIATOR COOLANT (SN)(CONSISTENT)	NOT NECESSARY	80.00	-
1	FRONT LEFT DOOR COMPANY STICKER (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	FRONT NO PLATE (SN)(CONSISTENT)	NOT NECESSARY	80.00	-
			290.00	30.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN FRONT AND FRONT LEFT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER ASSY.		1,400.00	400.00
	TO PUTTY AND SPRAY PAINTING FRONT AND FRONT LEFT PORTION .		1,400.00	600.00
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP .		50.00	20.00
	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM .	NOT NECESSARY	80.00	-
	TO APPLY ANTI RUST PROOFING TO FRONT AND FRONT LEFT AFFECTED AREA.	NOT NECESSARY	150.00	-
	TO REMOVE AND INSTALL COOLING SYSTEM TO FACILITATE THE REPAIR AND CHECK FOR LEAKAGE.	NOT NECESSARY	250.00	-
	TO REMOVE AND INSTALL FRONT LEFT DOOR LOCK MECHANISM .	NOT NECESSARY	80.00	-

Report Ref No. CC4/ASM18018428/Uha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK DOOR CENTRAL LOCKING FOR FUNCTION .	NOT NECESSARY	80.00	-
	TO TRANSFER DOOR GLASS TO NEW DOOR .	NOT NECESSARY	80.00	-
	TOWING SERVICE.	NOT NECESSARY	150.00	-
			3,720.00	1,020.00
GRAND TOTAL			17,491.25	2,531.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CC4/ASM18018428/Uha3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

⏪ Service Request Details

Claim	SBN00YHY	Actions	
Reference	CC4/AS418018420/0ha2q2	Next Step	Wait for: Approve Invoice
Loss Date	27 September 2018	<button>Add Invoice</button>	
Report Date	8 Oct 2018 3:58:22 PM	Vehicle Information	
Request Date	9 October 2018	Incident Vehicle Registration #	GBB2494K
Due Date		Make	TPVD TOYOTA
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)	Model	HINCE
Type of Loss	Third Party Vehicle Damage	Service Address	
Services	Pending verification - Direct Settlement	...	
		Primary Contact	
		Think One Autocare Pte Ltd	
		No.18 Detu Avenue 2, 539522, Singapore	
		Claim Handler	
		ANG Richard	
		richard.lan@bsi@axa.com.sg	

Additional Instructions

Hi, pls assign Marcus to attend to the survey. Thank you.

1

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

➕ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
📄 Accident Statement	Reports & Statement		Martineen	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (6).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
 LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
 LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
 Immediate Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 Email from TP dtd 201219.pdf	Letters and Correspondence	Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 LKK INSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	31 October 2018
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	31 October 2018
 Ltr to Insured -non reporting.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	11 October 2018
 GBB2494K TP CIA REPORT.PDF	Reports & Statement	CIA Report	DHAKAL Rayhaw	8 October 2018
 TP PRI FROM WORKSHOP.pdf	Letters and Correspondence	Workshop	DHAKAL Rayhaw	8 October 2018