

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

GBB2494K Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy	\$ 1,618.00
2	1	Front bumper tow cover	\$ 85.00
3	1	Front bumper left bracket	\$ 122.00
4	1	Front bumper reinforcement	\$ 630.00
5	2	Front bumper reinforcement support	\$ 184.00
6	1	Front bumper reinforcement centre crossmember	\$ 279.00
7	1	Front bumper lower grille	\$ 310.00
8	1	Front left headlamp	\$ 2,680.00
9	1	Front headlamp left bracket	\$ 63.00
10	1	Front left fog lamp	\$ 255.00
11	1	Front left fog lamp cover	\$ 78.00
12	1	Front grille assy	\$ 493.00
13	1	Front bonnet assy	\$ 2,389.00
14	1	Front bonnet emblem	\$ 120.00
15	2	Front bonnet stopper	\$ 68.00
16	1	Front bonnet lock	\$ 171.00
17	1	Front bonnet lock brace panel	\$ 116.00
18	2	Front bonnet hinges	\$ 188.00
19	1	Front top support panel assy	\$ 1,654.00
20	1	Front support panel top garnish seal	\$ 86.00
21	1	Front secondary radiator assy	\$ 1,129.00
22	1	Front secondary radiator cooling fan assy with motor	\$ 923.00
23	1	Front washer tank	\$ 192.00
24	1	Front left corner panel	\$ 283.00
25	1	Front left wing mirror assy	\$ 320.00
26	1	Front left door panel	\$ 1,858.00
27	1	Front left door lower step garnish	\$ 296.00
28	1	Front left door regulator linkage with motor	\$ 480.00
29	1	Front left door weatherstrip	\$ 288.00
30	1	Front left door outer handle	\$ 176.00
31	1	Front left door lock mechanism	\$ 245.00
32	1	Front left door outer moulding	\$ 196.00
			<hr/>
			\$ 17,975.00
Less 25%			\$ 4,493.75
			<hr/>
			\$ 13,481.25

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

GBB2494K Toyota Hiace

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front and front left affected area and replace front damaged parts.	\$ 1,400.00
2	To putty and spray painting front and front left portion.	\$ 1,400.00
3	To check wiring and focus front headlamp.	\$ 50.00
4	To remove and install front bonnet lock mechanism.	\$ 80.00
5	To apply anti rust proofing to front and front left affected area.	\$ 150.00
6	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 250.00
7	To remove and install front left door lock mechanism.	\$ 80.00
8	To check door central locking for function.	\$ 80.00
9	To transfer door glass to new door.	\$ 80.00
10	Towing service.	\$ 150.00
		<u>\$ 3,720.00</u>

Total parts : \$ 13,771.25
Total labour : \$ 3,720.00
Total repair cost : \$ 17,491.25

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

GBB2494K Toyota Hiace

			Estimated Parts Price
No	Qty	Parts Description	
<u>Special Nett Items</u>			
1	12	Front bumper clips	\$ 50.00
2	6	Front grille clips	\$ 30.00
3	1	Front radiator coolant	\$ 80.00
4	1	Front left door company sticker	\$ 50.00
5	1	Front no plate	\$ 80.00
			<hr/>
			\$ 290.00
			<hr/>
Total parts			\$ 13,771.25