

DATE/TIME

ASS. REC. BY:

REF: C/TPD18018442/Z

Special Instructions:

Surveyor

ASSIGNMENT (Office)

From (Person): Kamdiah Kante

of

SFF

Date/Time: 27/9/2018

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SHC 8268G

Insured:

at Workshop m/s

Tel:

of

Policy No:

MHASPF06000005579

Claim No:

TP/1P/5969/2018

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

15/9/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SHC 8268G - X

S30/1

⑪ SHC 8268 G

Rohaizal (LKKAUTO)

From: Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>
Sent: Thursday, 27 September 2018 7:53 PM
To: Rohaizal (LKKAUTO)
Cc: Bryan Ang (LKKAUTO); SPF-TP FAIT; Mohd Jamal MARZUKI (SPF); Chin Yong TAN (SPF); Tiak Yee PHUA (SPF)
Subject: Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 12 vehicles below:

a) Case IAFP-IB-20180925 - Mechanical Inspection of Motorcycle FBA2867Z (TP/IP/52725/2018)

On 13 September 2018, sometime before 9.20 p.m., the Involved party was riding motorcycle FBA2867Z along Circuit Road on the left most lane of 3 lanes road, when suddenly the Deceased (pedestrian) started crossing the road from the left to right of the rider's view. Rider was unable to brake in time and collided onto the deceased.

Vehicle to be inspected: FBA2867Z - Rider (Involved Party)

IO In-Charge: SIO Farhan

b) Case IAFP-IB-20180925 - Mechanical Inspection of Motor Lorry, GT4254U (TP/IP/50357/2018)

On 4 September 2018, sometime before 1.42 p.m., the driver of motor lorry, GT4254U claimed that the brakes were ineffective as he was trying to stop resulting in his motor lorry to veer to the right and collided onto the centre divider along Adam Road.

Vehicle to be inspected: GT4254U - Driver (Potential Defendant)

IO In-Charge: IO Esmond Phua

c) Case IAFP-IB-20180925 - Mechanical Inspection of Motorcycle, JQE1418 (TP/IP/52477/2018)

d) Case IAFP-IB-20180925 - Mechanical Inspection of Motor Car, SBY6618Z (TP/IP/52477/2018)

On 12.9.2018 at about 5.22 pm, motor car was driving along AYE towards Tuas on the 1st lane of 3 lanes road when he swerved to his left and resulted his left rear portion collided onto the Deceased riding motorcycle on 2nd lane before his front right portion collided onto the vehicle rear left portion on 1st lane. The impact caused the Deceased to fall onto 3rd lane and resulted another lorry front right tyre to run over him. Deceased was pronounced dead at the scene.

Vehicle to be inspected: JQE1418 - Rider (Deceased)

Vehicle to be inspected: SBY6618Z - Driver (Accused)

IO In-Charge: SIO Vilton

e) Case IAFP-IB-20180925 Mechanical Inspection of Motorcycle, FBM8439Z (TP/IP/51657/2018)

On 8 September 2018 at 9.24 am, Motorcycle FBM 8439 Z was travelling along Yishun Avenue 9 towards Avenue 8 when the pedestrian crossed from the right to left of motorcycle thus both collided. As a result of the accident, the pedestrian succumbed to her injuries and was pronounced dead at KTPH on the same day.

Vehicle to be inspected: FBM8439Z - Rider (Deceased)

IO In-Charge: SIO Yazid

- f) **Case IAFP-IB-20180925 Mechanical Inspection of Motorcycle, JSH9356 (TP/IP/53769/2018)**
- g) **Case IAFP-IB-20180925 Mechanical Inspection of Motor Taxi, SHC7938M (TP/IP/53769/2018)**
- h) **Case IAFP-IB-20180925 Mechanical Inspection of Motor Lorry, GBD2447L (TP/IP/53769/2018)**

On 19 September 2018 at 3.54 pm, motorcycle JSH 9356 was travelling along Sungei Kadut Avenue towards Woodlands Road when a motor taxi SHC 7938 M from the opposite direction lost control, mounted the kerb and collided onto a motor lorry GBD 2447 L and the said motorcycle which was travelling on the opposite direction. As a result of the accident, the motorcyclist was pronounced dead at the scene.

Vehicle to be inspected: JSH 9356 - Rider (Deceased)

Vehicle to be inspected: SHC 7938 M - Driver (Accused)

Vehicle to be inspected: GBD 2447 L - Driver (Involved Party)

IO In-Charge: SIO Yazid

- i) **Case IAFP-IB-20180925 - Mechanical Inspection of Motor Car, SKD3331D (TP/IP/46761/2018)**

On 17 August 2018 (Friday) at about 3.32 a.m., it was revealed that the Deceased was negotiating a left bend at the opposite direction; exiting from Lentor Ave Slip Road into Yishun Ave 1 when he mounted onto right kerb, collided onto a 'Give Way' sign and skidded across the three lanes of Yishun Ave 1 towards the direction of Mandai Road. Subsequently, mounted onto the centre divider and collided onto the centre guard railings; resulting his vehicle to flung onto the opposite direction and landed onto its left side of vehicle; covering lane 3 and 4 along Yishun Ave 1 towards the direction of Yishun Ave 8.

Vehicle to be inspected: Motor Car, SKC3331D - Driver (Involved Party)

IO In-Charge: DOC Shahril

- j) **Case IAFP-IB-20180925 - Mechanical Inspection of Motorcycle, AKD1832 (TP/IP/52969/2018)**
- k) **Case IAFP-IB-20180925 - Mechanical Inspection of Motor Taxi, SHC8268G (TP/IP/52969/2018)**

On 15 September 2018 (Saturday) at about 12.40 a.m., footage from the Involved Party's in-built camera revealed that the Involved Party was travelling straight along Pan Island Expressway (Tuas) on lane 1 of the 3 lanes road. As the Involved Party was driving forward, an unknown motor car ahead of him was seen applying the brakes. The Involved Party swerved to the left to avoid a collision with the unknown motor car ahead of him. At this juncture, the Deceased and his motorcycle were seen lying on lane 2. The left front portion of Involved Party's motor taxi collided onto the Deceased's motorcycle as he switched lanes. As a result of the accident, the Deceased sustained head injuries and was conveyed in critical condition to Changi General Hospital by an ambulance. However, the Deceased succumbed to his injuries and was pronounced dead by Dr Mathavan Valentina in hospital on the same day at 2.16 a.m.

Vehicle to be inspected: Motorcycle, AKD1832 - Rider (Deceased)

Vehicle to be inspected: Motor Taxi, SHC8268G - Driver (Involved Party)

IO In-Charge: IO Kamaliah

1) Case IAFP-IB-20180925 - Mechanical inspection of Motorcycle, FBL1211P (TP/IP/42521/2018)

On 28 July 2018 (Saturday) at about 1.32 a.m., the Deceased was travelling along Fort Canning Link into Penang Road towards Somerset when the Deceased self-skidded. The Deceased was conveyed by ambulance to Singapore General Hospital and was pronounced dead on 120 August 2018 at 7.37pm by Dr Tan Shi Hui at SGH.

Vehicle to be inspected: FBL1211P - Rider (Deceased)

IO In-Charge: IO Clarence Lim

2. These request has been approved by my management.
3. Thank you Sirs.

Cc: Bryan Ang (LKK), FAIT Team, OC Jamal, DOC Chin Yong & GIT IO Esmond Phua, fyip

Best regards,

Kamaliyah Kamis (Miss)
Investigation Officer | Fatal Accident Investigation Team
Traffic Police | Singapore Police Force
DID: (65) 6547 6435 | FAX: (65) 6547 6352



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Proleged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."