

FASTECH AUTO PTE LTD
 1 KAKI BUKIT AVENUE 6
 #01-46/48/50
 SINGAPORE 417883

Not Authorized
 LKK
 11/10/18
 1/5 @ 4000/-
 3 day.

VEHICLE NO: SLK 456A

QTY	PARTICULAR		
1 PCS	BOOTLID		R \$2,445.00 X
1 PCS	BOOTLID 'VOLVO' EMBLEM		su \$122.00 //
1 PCS	BOOTLID 'S60' EMBLEM	95.00	su \$108.00 //
1 PCS	BOOTLID 'T2' EMBLEM	82.00	su \$105.00 //
1 PCS	REAR BUMPER	1672.00	su/pe \$2,125.00 //
1 PCS	REAR BUMPER CENTRE GARNISH	695.00	wop/100 \$866.00 //
1 PCS	REAR BUMPER LOWER GARNISH	653.00	su/pe \$850.00 //
2 PCS	REAR BUMPER SIDE RETAINERS @\$150.00		su \$300.00 X
2 PCS	REAR BUMPER PDC SENSORS @\$265.00		su \$530.00 X
1 SET	REAR BUMPER CLIPS		su \$60.00 //
1 PCS	REAR bumper reinforcement	754.00	su \$1,100.00 //
			\$8,611.00

LABOUR CHARGES:

TO CHECK WIRING	\$80.00	20
TO DISMANTLE & REPLACING PDC SENSOR	\$80.00	50
TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY	\$150.00	60
TO SPRAY RUSF PROOFING	\$80.00	X
TO DISMANTLE REFIX REAR EXHAUST	\$150.00	X
LABOUR FOR PANEL BEATING, CUT & REPLACING PARTS	\$800.00	400
TO PUTTY & SPRAY PAINTING	\$800.00	600
TOTAL	\$10,751.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

4133
 5%
 3926.35

FASTECH AUTO PTE LTD