

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 4 OCTOBER 2018

Third Party Insurer:

AXA

Vehicle No: SKA4314H

Third Party Veh No:

SLE1113H

Model: MAZDA 3 1.6L SDN

Date of Accident:

3 OCTOBER 2018

Chassis: JM6BL10Z1A0159418 - 2010

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$	
1	REAR BOOTLID <i>5ne</i>		\$1,161.60	✓
1	RAER BOOTLID EMBLEM LOGO <i>Nec</i>		\$70.90	✓
1	REAR BOOTLID EMBLEM 'MAZDA 3' <i>Nec</i>		\$61.40	✓
1	REAR BOOTLID REFLECTOR LAMP LH <i>2 mounting crack</i>		\$350.30	✓
1	REAR BOOTLID INNER TRIM BOARD <i>Svc</i>		\$352.40	X
1	REAR BOOTLID WEATHER STRIP <i>deformed</i>		\$159.30	✓
2	REAR BOOTLID HINGE RH/LH <i>regr</i>	\$135.70	\$271.40	X
2	REAR BOOTLID DAMPLE RH/LH <i>Svc</i>	\$177.30	\$354.60	X
1	REAR BOOTLID MECHANISM LOCK <i>Dent</i>		\$177.30	✓
1	REAR TAILLAMP LH <i>2 mounting crack</i>		\$618.70	✓
1	REAR TAILLAMP INNER PANEL LH <i>regr</i>		\$235.00	X
1	REAR BUMPER <i>Dented</i>		\$1,049.80	✓
2	REAR BUMPER REFLECTOR RH/LH <i>broken</i>	\$159.20	\$318.40	✓
1	REAR BUMPER NUMBER PLATE LAMP <i>2 broken</i>		\$68.10	✓
2	REAR BUMPER SIDE RETAINER RH/LH <i>Svc</i>	\$57.10	\$114.20	X
2	RAER BUMPER BRACKET RH/LH <i>Svc</i>	\$57.30	\$114.60	X
1	REAR BUMPER REINFORCEMENT <i>2 Dented</i>		\$529.60	✓
10	REAR BUMPER CLIPS <i>Nec</i>	\$5.00	\$50.00	✓
4	REAR BUMPER STAY CLIPS <i>Svc</i>	\$12.00	\$48.00	X
1	REAR END PANEL <i>2 Dented</i>		\$609.30	✓
1	REAR END PANEL INNER TOP GARNISH <i>st</i>		\$286.40	✓
1	REAR FENDER AIR VENT LH <i>NH</i>		\$82.30	X
1	FRONT BUMPER <i>regr</i>		\$1,126.30	X
1	FRONT BUMPER TOW HOOK COVER <i>Svc</i>		\$27.50	X
8	FRONT BUMPER CLIPS <i>Svc</i>	\$5.80	\$46.40	X
1	FRONT GRILLE BASE <i>crack</i>		\$327.80	✓
6	FRONT GRILLE CLIPS <i>Nec</i>	\$5.80	\$34.80	✓
SUB TOTAL			\$8,646.40	
Less 20%			-\$1,729.28	
PARTS TOTAL			\$6,917.12	

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$	
2	REAR BUMPER REVERSE SENSOR <i>Dent</i>		\$280.00	220/-
1	REAR NUMBER PLATE WITH CASING <i>st</i>		\$70.00	45/-
S/N TOTAL			\$350.00	

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 4 OCTOBER 2018

Third Party Insurer:

AXA

Vehicle No: SKA4314H

Third Party Veh No:

SLE1113H

Model: MAZDA 3 1.6L SDN

Date of Accident:

3 OCTOBER 2018

Chassis: JM6BL10Z1A0159418 - 2010

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

800/- \$1,200.00

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

800/- \$1,100.00

TO TUFF KOTE / ANTI-RUST

\$60.00 40/-

TO CHECK WIRING, LIGHTING & WATER LEAKAGE

\$60.00 30/-

TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR

\$80.00 40/-

TO DISMANTLE & REINSTALL REAR INTERIOR CARPET COMPONENT MECHANISM
TO FACILITATE REPAIR WITH CHECK FOR FUNCTION

\$180.00 80/-

TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD

\$150.00 NW

LABOUR TOTAL

\$2,830.00

TOTAL

\$10,097.12

08/10/2018 @ 1745hr

Not Andrew

1 year

2/Sum 8 days.

2 Kk Auto

Photo after repair

97237799

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: