

ASS. REC. BY:

REF: CS/FCI/2018450/Ktd3⁷²

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

(WS)

From (Person):

Lurene juw

of

FCI

Date/Time: 10/10/18 @ 6:08pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 9530C

Insured:

SHC 7966G

at Workshop m/s

Hwa Seng Spray

Tel:

6453 3100 / 9863 0678

of

Blk 15 Sin Ming Ind. Est # 01-117

Policy No:

Claim No:

D18007371 MFST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 08/10/2018

Insp: 160 Sin Ming Drive #05-11

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time:

11/10/18 @ 9:28am

Person Contacted:

Ah boon

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SMD 9530C - X

SHC 7966G - X.

11/10 @ 11:45am Revised preli advise via email

30/10 - Finalised \$6022.32, 8 days. (Red: 3151.60 : 34%)

REF: FCI

ASSIGNMENT

From:

Date:

11/10/2018

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMD 9530C

at Workshop m/s

Hwa Beng Spray

of

160 Sin Ming Drive # 05-11

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

898k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

Jays

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{DS}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMD 9530C

Yr Regn:

09, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

A)

Free.c

Wagon 1496

Colour

M. D. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

5723

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GB7

1072132

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

8/10/18

D.O.I.

11/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/10 File pass to Catherine, got injury

RECEIVED 30 OCT 2018

Date/Time, File Pass to?



: Preli. Report

1) 30/10 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

170

50

50+50

26

346

Report Format:

Lump Sum / I.B.I. (\$) 6022.72



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007354MFSH

Date: 16/10/2018

Our Ref: CS/FCI18018418/Utd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMD 9530C

Please be informed that we had conducted the inspection of the abovementioned vehicle
11/10/2018 at the premises of M/s Hwa Seng Spray and have the following to report: -

Workshop Estimate Amount	: S\$ <u>8,329.12</u>
Revised Estimate Amount	: S\$ <u>4,977.52</u>
"Check" Items Amount	: S\$ <u>174.80</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the
rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	10-10-2018	Our Ref No.	D18007371MFSH
Accident Date	08-10-2018	Claim Type.	Third Party
Insured Vehicle	SHC7966G	Third Party Vehicle.	SMD9530C
Survey Location	BLK 15 SIN MING IND EST #01-117 Sector A		
Contact Person.	HWEE BOON		
Contact No.	64533100/ 98630678	Fax No.	64591932
Survey Type	DIRECT SETTLEMENT:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HWA SENG SPRAY PAINTING CO	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	LURENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 16 October 2018 11:45 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Lurene Jaw'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007371MFSH/1
Attachments: PRELI ADVISED SMD 9530C.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SMD 9530C**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 11 October 2018 9:34 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007371MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 10 October 2018 6:08 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007371MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

HWA SENG SPRAY PAINTING CO
160 Sin Ming Drive
#05-11, Sin Ming Autocity
SINGAPORE 575722.
(COMPANY REGISTRATION NO. 095744008)
TEL: 64533100
FAX: 62669932

KT

Not Authorised
Resurvey B&P
B.I

1 of 1

8 days

6022-32

Estimate repair cost to HONDA FREED reg no : SMD 9530 C

1pc tailgate	S\$
1pc logo emblem	
1pc emblem 'FREED'	
1pc emblem 'HYBRID'	
1pc tailgate rubber	
2pcs tailgate absorber	(S\$165.30/pc)
2pcs tailgate hinges	(S\$60.70/pc)
1pc tailgate upper lock	
1pc tailgate lower lock	
1pc tailgate outer chrome	
1pc tailgate inner trim	
2pcs tailgate reflector	(S\$360.50/pc)
2pcs taillamp	(S\$580.00/pc)
1pc rear bumper	
2pcs rear bumper retainer	(S\$ 26.50/pc)
2pcs rear bumper bracket	(S\$30.50/pc)
1pc end panel	
1pc end panel garnish	

Pr	1100.90	✓
Pr	32.50	✓
Pr	55.00	✓
Pr	75.50	✓
Pr	168.10	✓
Pr	330.60	X
Pr	121.40	X
Pr	157.50	X
Pr	27.10	X
Pr	320.40	X
Pr	288.00	✓
Pr	721.00	X
Pr	1160.00	X
Pr	925.60	✓
Pr	53.00	X
Pr	61.00	X
Pr	623.20	✓
Pr	115.60	✓

Less 20%

6336.40
1267.28
5069.12


Labour & misc charges

Labour to remove and install rear windscreen
Sealant and clip
Inner seal
Labour to remove and install upholstery
Panel knocking
Spray painting
Tuff kote
Wire checking
1 set reverse sensor

160.00	120l
80.00	60sm
60.00	30sm
200.00	80l
1300.00	700l 1000l
1000.00	900l
180.00	60l
50.00	20l
Short 230.00	200sm
8329.12	

9173-92

HWA SENG SPRAY PAINTING COMPANY



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HWA SENG SPRAY PAINTING CO
160 Sin Ming Drive
#05-11 Sin Ming Autocity
SINGAPORE 575722
(COMPANY REGISTRATION NO. 095744008)
TEL : 64533100
FAX : 62669932

ESTIMATE REPAIR COST TO HONDA FREED REG. NO : SMD 9530 C

		SS
	Supplementary Parts	
1pc	Floor Panel	B ₁ 1056.00 ✓
	Less 20%	<u>211.20</u>
		<u>844.80</u>

HWA SENG SPRAY PAINTING COMPANY

A handwritten signature in black ink, consisting of several overlapping, sweeping strokes, positioned below the company name.

FAX: 62669932

Not Notarize
Presny B4 paint

6 days

Less 20%

1 set reverse sensor

HWA SENG SPRAY PAINTING COMPANY

B_1	1100.90	✓
M_1	32.50	—
M_2	55.00	✓
M_3	75.50	✓
D_1/M_1	168.10	✓
S_1	330.60	X
R	121.40	X
	157.50	?
R	27.10	X
S_2	320.40	X
B_2	288.00	✓
S_1	721.00	X
S_2	1160.00	X
B_1	925.60	✓
S_2	53.00	X
	61.00	?
B_1	623.20	✓
D_1	115.60	✓

5069.12

	160.00	120l
na	80.00	60sm
na	60.00	30sm
	200.00	80l
	1300.00	900l
	1000.00	800l
	180.00	60l
	50.00	20l
Shot	230.00	200sm
	<u>8329.12</u>	

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18018450/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7966G	Veh. Inspected	SMD 9530C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007371MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	10/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GB71072132	Colour	METALLIC DARK BLUE	
Odometer	5723	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	YOKOHAMA	9 mm	
L/H Front Tyre	185/65 R15	YOKOHAMA	9 mm	
R/H Rear Tyre	185/65 R15	YOKOHAMA	9 mm	
L/H Rear Tyre	185/65 R15	YOKOHAMA	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/10/2018	Inspection Date	11/10/2018	
Survey held at	HWA SENG SPRAY PAINTING COMPANY 160 SIN MING DRIVE #05-11 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 9530C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	BENT	1,100.90	1,100.90
1	LOGO EMBLEM	NECESSARY	32.50	32.50
1	EMBLEM "FREED"	NECESSARY	55.00	55.00
1	EMBLEM "HYBRID"	NECESSARY	75.50	75.50
1	TAILGATE RUBBER	DISTORTED / DENTED	168.10	168.10
2	TAILGATE ABSORBER @\$165.30	SERVICEABLE	330.60	-
2	TAILGATE HINGES @\$60.70	TO REPAIR SEE LABOUR	121.40	-
1	TAILGATE UPPER LOCK	TO REPAIR SEE LABOUR	157.50	-
1	TAILGATE LOWER LOCK	TO REPAIR SEE LABOUR	27.10	-
1	TAILGATE OUTER CHROME	SERVICEABLE	320.40	-
1	TAILGATE INNER TRIM	BUCKLED	288.00	288.00
2	TAILGATE REFLECTOR @\$360.50	SERVICEABLE	721.00	-
2	TAILLAMP @\$580.00	SERVICEABLE	1,160.00	-
1	REAR BUMPER	BENT	925.60	925.60
2	REAR BUMPER RETAINER @\$26.50	SERVICEABLE	53.00	-
2	REAR BUMPER BRACKET @\$30.50	TO REPAIR SEE LABOUR	61.00	-
1	END PANEL	BENT	623.20	623.20
1	END PANEL GARNISH	DENTED	115.60	115.60
1	FLOOR PANEL (ADDITIONAL)	BENT	1,056.00	1,056.00
	LESS 20% DISCOUNT		-1,478.48	-888.08
			5,913.92	3,552.32
SPECIAL NETT ITEMS				
1	SEALANT AND CLIP (SN)	NECESSARY	80.00	60.00
1	INNER SEAL (SN)	NECESSARY	60.00	30.00
1	SET REVERSE SENSOR (SN)	SHORTED	230.00	200.00
			370.00	290.00

Report Ref No. CS/FCI18018450/Ktd3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR TO REMOVE AND INSTALL REAR WINDSCREEN.		160.00	120.00
	LABOUR TO REMOVE AND INSTALL UPHOLSTRY.		200.00	80.00
	PANEL KNOCKING, INCLUSIVE OF THE REPAIR OF TAILGATE HINGES, TAILGATE UPPER LOCK, TAILGATE LOWER LOCK AND REAR BUMPER BRACKET.		1,300.00	1,000.00
	SPRAY PAINTING.		1,000.00	900.00
	TUFF KOTE.		180.00	60.00
	WIRE CHECKING.		50.00	20.00
			2,890.00	2,180.00
	GRAND TOTAL		9,173.92	6,022.32
RECOMMENDED COST OF REPAIRS				6,022.32

Report Ref No. CS/FCI18018450/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.