

## SINGAPORE CIVIL DEFENCE FORCE

## FIRE REPORT

1. GENERAL INFORMATION			
NCIDENT NO. : /20180927/0264		LOCATION OF FIRE:	
FIRE REPORTED ON: 27 September 2018		Yishun Heavy Vehicle Park (Y0017) Yishun Avenue 7 Singapore	
TIME OF CALL: 09:34:23 hrs			
STATION COVERAGE : Yishun	Fire Station		
2. INCIDENT INFORMATION			
FIRE INVOLVED: The rear engine compartment of a bus (PZ8118R).			
METHOD OF EXTINGUISHMENT: By members of public using dry powder fire extinguisher before the arrival of SCDF crew.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine of the bus was damaged. The rear right lights assembly and the paintwork of the bus sustained heat and smoke damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			

RASHID B MD NOOR for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE

This is a computer generated Fire Report. No signature is required.