



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2007 ISUZU LT134P ISUXXX (PZ8118R)

Date of Loss 27 September 2018

Time of Loss 9.25

Loss Description PZ8118R (INSD) - FIRE

Comment

Workshop Details

Total Rebate Amount 34169

Nett Loss Amount \$55,831.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 118



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	PZ8118R	Purchase Date	dd/mm/yyyy
Registration State	SINGAPORE	Registration Date *	06/05/2008
Mileage	380293	Age of Vehicle	10

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2007	2007
Make	ISUZU LT134P	ISUZU
Model	ISUXXX	LT134P

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	RATONEL BRYAN COLIN @ ARYAN	
Date of Birth	25 October 1985	dd/mm/y
Age	33	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	JALLT134P77000316	JALLT134P7700031
Engine No	6HK1460692	6HK1460692
Engine Capacity		7790
Sum Insured	0	0
Market Value	0	90000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	3	
Driver License #		
License Type		
License Issue Date	1 January 2016	dd/mm/y
License Expiration Date		dd/mm/y
Address	BLK 342B YISHUN RING ROAD #09-1924, 762342, Singapore	
Address type	Personal Correspondence	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Unknown	
Identification #	S8531636B	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

11/10/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

295/80R22.5

Rear Tyre Size

295/80R22.5

Front left side

BRIDGESTONE5mm

Rear left side

BRIDGESTONE5mm

Front right side

BRIDGESTONE5mm

Rear right side

BRIDGESTONE5mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details																
Vehicle & Driver Details																
Vehicle Condition																
Taxes & Ratio																
Parts & Labour																
Miscellaneous																
Summary																
Parts																
AddApproveDenySubmit All																
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			REAR RIGHT BUMPER ASSY			Damaged	1200		10		1080	Reviewing	
		2	1			REAR RIGHT BUMPER STRUCTURAL FRAME ASSY			Damaged	380		10		342	Reviewing	
		3	1			REAR RIGHT TAILLAMP ASSY			Damaged	980		10		882	Reviewing	
		4	1			REAR RIGHT TAILLAMP WIRE HARNESS			Damaged	290		10		261	Reviewing	
		5	1			REAR LID COVER ASSY			Damaged	4300		10		3870	Reviewing	
		6	1			REAR LID COVER WEATHERSTRIP			Damaged	480		10		432	Reviewing	
		7	1			REAR TOP LID COVER ASSY			Damaged	2600		10		2340	Reviewing	
		8	1			REAR TOP LID COVER LOCK			Damaged	80		10		72	Reviewing	
		9	5			REAR TOP AIR COND FAN ASSY			Damaged	420		10		1890	Reviewing	
		10	1			REAR RIGHT CORNER PANEL			Damaged	2400		10		2160	Reviewing	
		11	1			REAR RIGHT TOP INSPECTION LID COVER ASSY			Damaged	2200		10		1980	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		12	1			REAR RIGHT TOP INSPECTION LID COVER WEATHERSTRIP			Damaged	310		10		279	Reviewing	
		13	1			REAR RIGHT TOP INSPECTION LID COVER LOCK			Damaged	80		10		72	Reviewing	
		14	1			REAR RIGHT LOWER INSPECTION LID COVER ASSY			Damaged	3100		10		2790	Reviewing	
		15	1			REAR RIGHT LOWER INSPECTION LID COVER WEATHERSTRIP			Damaged	390		10		351	Reviewing	
		16	1			REAR RIGHT LOWER INSPECTION LID COVER LOCK			Damaged	80		10		72	Reviewing	
		17	1			REAR RIGHT CENTRE HORIZONTAL PANEL			Damaged	250		10		225	Reviewing	
		18	1			SET REAR RIGHT STRUCTURAL FRAME ASSY			Serviceable	0	0	0	0	0	Deny	
		19	1			REAR RIGHT ROCKER PANEL			Serviceable	0	0	0	0	0	Deny	
		20	1			REAR RIGHT WINDOW PROTECTOR MOULDING			Damaged	550		10		495	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO TOW VEHICLE (TWO TRIPS)	400	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
 	2		TO SUPPLY AND SPRAY INSULATION FOAM ON ALL AFFECTED PARTS	800	0	0	Reviewing		
 	3		TO LIFT ENGINE SO AS TO ENABLE REPAIR TO BE CARRIED OUT AND REFIT SAME	500	0	0	Reviewing		
 	4		TO REMOVE ALL DAMAGED ALTERNATOR, WIRE HARNESS INCLUDING REWIRING AND CHECKING OF WIRING SYSTEM	0	0	0	Deny		
 	5		TO REMOVE REAR WINDSCREEN GLASS SO AS TO ENABLE REPAIR TO BE CARRIED OUT AND REFIT SAME	600	0	0	Reviewing		
 	6		TO REMOVE DAMAGED EXHAUST ASSY, DIESEL PARTICULATE DIFFUSER ETC. AND REFIT NEW	0	0	0	Deny		
 	7		TO REMOVE DAMAGED AIR COND COMPRESSOR, PIPES, FANS ETC AND REFIT NEW INCLUDING VACUUM AND RECHARGE GAS	0	0	0	Deny		
 	8		TO PUTTY AND SPRAY PAINTING ON ALL AFFECTED PARTS AFFECTED BY THE FIRE	1600	0	0	Reviewing		
 	9		TO CUT OFF DAMAGED STRUCTURAL FRAMES AND WELD NEW. TO REMOVE ALL DAMAGED BODY PARTS AND REFIT NEW INCLUDING ALIGN SAME	2500	0	0	Reviewing		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 30 DAYS	Reviewing			
		2	ALTERNATOR	Reviewing	2200	BURNT	
		3	AIR COND COMPRESSOR	Reviewing	1800	BURNT	
		4	AIR COND DISCHARGE PIPE	Reviewing	850	BURNT	
		5	AIR COND. FAN ASSY.-5PCS	Reviewing	2100	BURNT	
		6	AIR CON DISCHARGE PIPE	Reviewing	720	BURNT	
		7	RADIATOR ASSY	Reviewing	3600	BURNT	
		8	RADIATOR EXPANSION TANK ASSY	Reviewing	340	BURNT	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		9	RADIATOR HOSE - 2PCS	Reviewing	560	BURNT	
		10	RADIATOR FAN ASSY	Reviewing	680	BURNT	
		11	RADIATOR FAN COWLING	Reviewing	430	BURNT	
		12	HYDRAULIC RESERVOIR TANK	Reviewing	280	BURNT	
		13	HYDRAULIC RESERVOIR TANK PIPE- 2PCS	Reviewing	380	BURNT	
		14	ENGINE MOUNTING- 2PCS	Reviewing	1240	BURNT	
		15	REAR WINDSCREEN GUM	Reviewing	500	BURNT	
		16	REAR RIGHT WINDOW GLASS GUM	Reviewing	280	BURNT	
		17	SET REVERSE SENSOR	Reviewing	480	BURNT	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		18	REAR STICKER, '60KM/H'	Reviewing	10	NECESSARY	
		19	REAR EXHAUST PIPE 'A' (PART NO. 150001A)	Deny	0	SERVICEABLE	
		20	REAR EXHAUST PIPE 'B' (PART NO. 150001B)	Deny	0	SERVICEABLE	
		21	REAR EXHAUST PIPE 'C' (PART NO. 150001C)	Deny	0	SERVICEABLE	
		22	REAR EXHAUST PIPE (PART NO. 150126)	Deny	0	SERVICEABLE	
		23	REAR EXHAUST SILENER (PART NO. 150012)	Deny	0	SERVICEABLE	
		24	REAR EXHAUST SILENCER (PART NO. 150554)	Deny	0	SERVICEABLE	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		25	REAR EXHAUST PIPE GASKET (PART NO. 150571) - 4PCS	Deny	0	SERVICEABLE	
		26	DPD-DIESEL PARTICULATE DIFFUSER (PART NO. 150556)	Reviewing	8925	BURNT	
		27	AIR CLEANER (PART NO. 130001)	Reviewing	877	BURNT	
		28	RESONATOR, AIR INTAKE (PART NO. 131102)-2PCS	Reviewing	552	BURNT	
		29	HOSE TO RESONATOR (PART NO. 131337)-2PCS	Reviewing	64	BURNT	
		30	HOSE, AIR INTAKE (PART NO. 131179)	Reviewing	403	BURNT	
		31	HOOD ASM (130133A)	Reviewing	78	BURNT	
		32	HOSE RUBBER, AIR BREATHING (028063A)	Reviewing	16	BURNT	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		33	HOSE RUBBER, AIR BREATHING (028063B)	Reviewing	13	BURNT	
		34	HOSE RUBBER, OIL DRAIN	Reviewing	10	BURNT	
		35	HOSE RUBBER, HEAD COVER TO SEPARATOR (028307)	Reviewing	79	BURNT	
		36	HOSE RUBBER (PART NO. 028315)	Reviewing	66	BURNT	
		37	HOSE, BREATHING (PART NO. 028316A)-2PCS	Reviewing	88	BURNT	
		38	HOSE, BREATHING (PART NO. 028316B)	Reviewing	62	BURNT	
		39	WIRE HARNESS, FRAME (PART NO. 810006)	Deny	0	SERVICEABLE	

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		40	WIRE HARNESS, ENGINE (PART NO. 810013)	Deny	0	SERVICEABLE	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount\$53,676.00

Claim Amount\$53,676.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$19,593.00	\$19,593.00
Labour	\$6,400.00	\$6,400.00
Miscellaneous	\$27,683.00	\$27,683.00

Submit for Review

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
 	1	FINAL LUMP SUM	Reviewing	43000		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount

\$43,000.00

Claim Amount

\$43,000.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$43,000.00	\$43,000.00

Submit for Review