



SINGAPORE CIVIL DEFENCE FORCE

## FIRE REPORT

|  |         |  |                         |
|--|---------|--|-------------------------|
| <b>1. GENERAL INFORMATION</b>  |         |  |                         |
| INCIDENT NO. : /20180927/0264  |         | LOCATION OF FIRE:<br><br>Yishun Heavy Vehicle Park (Y0017)<br>Yishun Avenue 7<br>Singapore |                         |
| FIRE REPORTED ON : 27 September 2018   |         |  |                         |
| TIME OF CALL : 09:34:23 hrs  |         |  |                         |
| STATION<br>COVERAGE : Yishun Fire Station  |         |  |                         |
| <b>2. INCIDENT INFORMATION</b>   |         |  |                         |
| FIRE INVOLVED: The rear engine compartment of a bus (PZ8118R).   |         |  |                         |
| METHOD OF EXTINGUISHMENT: By members of public using dry powder fire extinguisher before the arrival of SCDF crew.   |         |  |                         |
| PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)   |         |  |                         |
| DAMAGE SUSTAINED: As a result of the fire, the engine of the bus was damaged. The rear right lights assembly and the paintwork of the bus sustained heat and smoke damage. |         |  |                         |
| <b>3. FATALITY/INJURY INFORMATION</b>  |         |  |                         |
| NAME   | PIN/FIN | ADDRESS  | DEAD/INJURIES SUSTAINED |
| NIL  | NIL     | NIL  | NIL                     |
| <b>REPORT CERTIFIED TRUE AND CORRECT BY:</b><br><br><br><br><br><br><br><br>RASHID B MD NOOR<br>for COMMISSIONER<br>SINGAPORE CIVIL DEFENCE FORCE                          |         |  |                         |

*This is a computer generated Fire Report. No signature is required.*