



ACCIDENT TIME REPORTED	1045HRS
ACCIDENT DATE	8-Oct-18
BUS CAPTAIN NAME	BAHTHIAR BIN MD HASSAN
EMPLOYEE NUMBER	

BUS REGISTRATION NUMBER	SG5025J
BUS TYPE (SD/DD)	DD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

	Part No.	Part or Item Description	Quantity	Total Cost
			7% GST	\$0.00
			FINAL TOTAL COST	\$0.00

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)			TOTAL COST
TO REPLACE/REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING)			1200 \$1,600.00
			7% GST
			FINAL TOTAL COST

ESTIMATED ACCIDENT REPAIR COST



SECTION 5: REPAIRS TO BUS ADVERTISEMENT VINYL/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST	-
---------------------------------	---

SECTION 6: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 7: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date In For Repairs	13/10/2018	
		Date Out From Repairs	15/10/2018	
		Number of Days Under Repair	2	
BUS TYPE (SD / DD)	DD	LOSS OF USE COST		\$800.00

SUMMARY	
SECTION NO.	COST
1	\$0.00
2	\$1,712.00
3	-
4	-
5	\$800.00
ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5)	\$2,512.00

Same
Hp 90010068
2 days
12/10/18 @ 1645
Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: