



Case Details

Case Reference Number : TAX/10/18/2021
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHD6122B

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-4024-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd
 Accident Date and Time : 05/10/2018 02:45 PM
 Vehicle Age(In Months) : 29

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval		
					List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In			COVER, OUTER MIRROR, RH	1	107.40	107.40	25.00	80.55	Replace	1	80.55	Replace ✓/ce
One Time Key In			MIRROR ASSY, RH	1	1,307.10	1,307.10	10.00	1,176.39	Replace	0	0	Not Given ✓/XSL
One Time Key In			MIRROR LAMP RH	1	65.30	65.30	10.00	58.77	Replace	1	58.77	Replace ✓/MJS
One Time Key In			MIRROR GLASS RH	1	212.80	212.80	25.00	159.60	Replace	0	0	Not Given ✓/XSL
Total Spare Part Cost								1,475.31		Surveyor Total	139.32	
Lump Sum Discount (%)								0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost								1,475.31		Final Sur Total	139.32	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		0.00	0.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO RESPRAY VIEW MIRROR	180.00	30	
Total:		180.00	30.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REMOVE AND REFIX WING MIRROR	120.00	0	NN
2	TOWING CHARGE	84.00	0	NN
Total:		204.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,475.31	139.32
Total Labour Cost	0.00	0.00
Total Spray Painting	180.00	30.00
Other	204.00	0.00
Overall Total	1,859.31	169.32
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	169.32
Surveyor Approved Amount		169.32
No of Repair Days*	2	1
Remarks	-	PART BY PART REPAIR. 1 DAY. BEFORE PAINT PHOTOS.
Surveyor Name		Naz
Signature		
Survey Date	11/10/2018	Save Clear

NAZ LKK
 9/10/18 1145
 P/P
 1 DAY
 BEFORE PAINT PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: