



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP AYA
Xiao Tong

Accident date: 04/10/2018

Estimated repair cost for vehicle no: SLU5346S MAZDA 3 1.5 A '17

CHASSIS: JM6BN22A8J0192678

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Buckled</i>		\$1,067.30 ✓
2	2	Front Bonnet Hinge <i>new</i>	\$41.00	\$82.00 +
3	1	Front Bonnet Insulator <i>new</i>		\$182.00 +
4	8	Front Bonnet Insulator Clip <i>new</i>	\$6.50	\$52.00 +
5	1	Front Bonnet Inner Rubber <i>new</i>		\$65.90 +
6	1	Front Bonnet Inner Outer Rubber <i>new</i>		\$83.60 +
7	12	Front Bonnet Inner Outer Rubber Clip	\$6.50	\$78.00 +
8	2	Front Head Lamp <i>cracked</i>	\$1,019.50	\$2,039.00 ✓
9	2	Front Head Lamp Lower Bracket <i>new</i>	\$26.00	\$52.00 ✓
10	1	Front Bumper <i>distorted</i>		\$825.00 ✓
11	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30
12	2	Front Bumper Side Retainer <i>new</i>	\$28.70	\$57.40 ✓
13	1	Front Bumper Number Plate <i>cracked</i>		\$50.00 ✓
14	1	Front Bumper Number Plate Garnish <i>del</i>		\$71.00 ✓
15	1	Front Bumper Reinforcement <i>Best</i>		\$478.80 ✓
16	2	Front Bumper Fog Lamp <i>new</i>	\$140.00	\$280.00 +
17	2	Front Bumper Fog Lamp Cover <i>new</i>	\$25.00	\$50.00 +
18	1	Front Grille <i>cracked</i>		\$129.00 ✓
19	8	Front Grille Clip <i>new</i>	\$6.50	\$52.00 30
20	1	Front Grille Emblem Logo <i>cracked</i>		\$58.50 ✓
21	1	Front Grille Top Cover <i>del</i>		\$338.50 ✓
22	2	Front Grille Side Chrome Moulding <i>cracked</i>	\$182.50	\$365.00 ✓
23	2	Front Fender <i>Buckled</i>	\$333.90	\$667.80 ✓
24	2	Front Fender Cowling <i>new</i>	\$197.00	\$394.00 +
25	16	Front Fender Cowling Clip <i>new</i>	\$6.50	\$104.00 +
26	1	Front Support Panel <i>cracked</i>		\$469.70 ✓
27	1	Front Support Panel Top Cover <i>new</i>		\$124.00 +
28	10	Front Support Panel Top Cover Clip <i>new</i>	\$6.50	\$65.00 +
29	2	Front Horn <i>new</i>	\$119.00	\$238.00 ✓
30	1	Front Air-Con Condenser <i>new Best</i>		\$1,063.00 ✓

31	1	Front Air-Con Section Pipe	3 new		\$345.70	x
32	1	Front Air-Con Discharge Pipe	3 new		\$248.80	x
33	1	Front Radiator	new		\$1,064.90	p
34	1	Front Radiator Fan Motor Assy	crushed		\$1,356.80	x ✓
35	1	Front Radiator Top Hose	3 new		\$37.70	t
36	1	Front Radiator Lower Hose	1 new		\$73.30	x
37	1	Front Air Cleaner Air Duct	not new		\$92.70	x
38	1	Front Air Cleaner Assy	new		\$155.10	x
39	1	Rear Boot Lid	Buckled		\$957.40	✓
40	2	Rear Boot Lid Hinge	new	\$145.30	\$290.60	x
41	1	Rear Boot Lid Emblem Logo	2		\$74.40	✓
42	1	Rear Boot Lid Mazda 3 Logo	1 new		\$53.40	✓
43	1	Rear Boot Lid Skyactiv Logo	1		\$63.60	✓
44	2	Rear Boot Lid Side Reflector	lot	\$265.00	\$530.00	✓
45	1	Rear Boot Lid Number Plate	not new		\$50.00	t
46	2	Rear Boot Lid Number Plate Lamp	new	\$71.10	\$142.20	x
47	1	Rear Boot Lid Inner Lock	Damaged		\$153.00	✓
48	1	Rear Boot Lid Inner Rubber	lot		\$129.30	✓
49	1	Rear Boot Lid Inner Trim Board	new		\$220.20	t
50	8	Rear Boot Lid Inner Trim Board Clip	not new	\$6.50	\$52.00	x
51	1	Rear Boot Lid Camera	Damaged		\$680.00 380 (SW)	
52	2	Rear Tail Lamp	lot	\$509.40	\$1,018.80	✓
53	2	Rear Tail Lamp Lower Bracket	new	\$29.20	\$58.40	p
54	1	Rear Bumper	Distorted		\$1,074.80	✓
55	8	Rear Bumper Clip	new	\$6.50	\$52.00 30	
56	2	Rear Bumper Side Retainer	new	\$36.10	\$72.20	✓
57	2	Rear Bumper Side Reflector	not new	\$50.40	\$100.80	t
58	1	Rear Bumper Reverse Sensor	Damaged		\$380.00 200 (SW)	
59	2	Rear Bumper Towing Cover	Missing	\$16.20	\$32.40	✓
60	1	Rear Bumper Reinforcement	Bent		\$537.20	✓
61	1	Rear End Panel	Bent		\$505.10	✓
62	1	Rear End Panel Top Garnish	crushed		\$185.10	✓
63	2	Rear Fender	Repair	\$1,174.20	\$2,348.40	x
64	2	Rear Fender Inner Trim Board	3 new	\$235.60	\$471.20	x
65	16	Rear Fender Inner Trim Board Clip	3 new	\$6.50	\$104.00	t
66	1	Rear Spare Tyre Panel	Repair		\$524.70	x
67	1	Rear Spare Tyre Panel Top Cover	new		\$355.00	x
68	1	Rear Spare Tyre Panel Top Sponge	crushed		\$195.10	✓
69	1	Rear Spare Tyre Panel & End Panel Sealant	not new		\$450.00	x
70	1	Rear Exhaust	not new Bent		\$1,075.80	x ✓
71	2	Rear Exhaust Mounting	2	\$27.10	\$54.20	x
72	1	Rear Exhaust Aluminium Cover	not new		\$129.30	x
73	1	Rear Centre Exhaust	new		\$1,433.00	t

15784 40 S.N. 580
1262752

Subtotal :- \$27,576.10

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas	\$380.00 7 120.
To remove & refit rear & centre exhaust	\$380.00 80.
To remove & refit boot lid camera & windscreen video camera	\$380.00 50
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear windscreen	\$120.00 X
Gum	\$50.00 X
To remove & refit petrol tank	\$280.00 X
To remove & refit roof lining	\$380.00 X
To remove & refit seat cushion & trim board	\$380.00 80.
To check wiring	\$100.00 60.
Tuff kote	\$150.00 80
Towing fee	\$100.00 60.
Panel beating	\$3,500.00 1700
Spray painting	\$3,000.00 1800

4080

Supplementary : 83096

total 181848

14.5K

12 days

14.5K

Subtotal :- \$9,300.00

Total:- \$36,876.10

Adrian King
1/5 08/10/18.
No of days ??

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

09/10/2018

Accident date: 04/10/2018

Supplementary

Supplementary repair cost for vehicle no: SLU5346S MAZDA 3 1.5 A '17

CHASSIS: JM6BN22A8J0192678

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Auto Lock Switch <i>new</i>		\$165.00 <i>x</i>
2	1	Front Support Panel Bonnet Lock Bracket <i>Bent</i>		\$48.40 ✓
3	1	Front Head Lamp Panel <i>Bent</i>		\$249.00 ✓
4	1	Front Reinforcement Cover <i>broken covered</i>		\$145.00 ✓
5	1	Front Bumper Top Cover Inner Bracket <i>del.</i>		\$185.00 ✓
6	2	Front Bumper Inner Side Bracket <i>new</i>	\$28.00	\$56.00 <i>x</i>
7	1	Front Bumper Reinforcement Lower Cover <i>crushed</i>		\$125.70 ✓
8	1	Front Bumper Centre Lower Cover <i>crushed</i>		\$285.60 ✓

Subtotal :- \$1,259.70

1038.70
830.96.