



Co. Reg: 200922097K GST Reg.No: 200922097K
 Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883
 • Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
 Date:

Date : 11/10/2018

Total Pages : 1

TO: AXA INSURANCE SINGAPORE PTE LTD
 8 Shenton Way
 #27-01 AXA Tower
 Singapore 068811

Our Customer : KOK SIEW CHERN
 Vehicle No : SKZ758E
 Model : HONDA VEZEL

Manufacture Year : 2015
 Date of Accident : 3/10/2018

Total Estimate Repair Days : 6

Attn : Motor Claim Department
 Email : motor.survey@axa.com.sg

Re: Repair Estimate For Third Party Claim against SGA655Y

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Tailgate <i>953</i>	1	\$1,320.70	\$1,320.70	<i>Subsid ✓</i>
2	Tailgate 'VEZEL' emblem	1	\$58.20	\$58.20	<i>✓</i>
3	Tailgate logo	1	\$58.70	\$58.70	<i>17 X</i>
4	Rear bumper <i>762</i>	1	\$985.50	\$985.50	<i>17/18 ✓</i>
5	Rear bumper clips	10	\$3.50	\$35.00	<i>✓</i>
6	Rear bumper retainer	2	\$58.20	\$116.40	<i>17 X</i>
7	Rear bumper chrome plate	1	\$280.50	\$280.50	<i>17 200 S.W</i>
8	Rear parking sensor	1	\$280.00	\$280.00	<i>Sub 200 S.W</i>
9	Rear end panel	1	\$680.20	\$680.20	<i>?</i>
10	Rear end panel sealant	1	\$25.00	\$25.00	<i>?</i>
11	Rear windscreen weatherstrip <i>mouthy</i>	4	\$42.10	\$168.40	<i>max X</i>
12	Rear windscreen inner seal	1	\$60.00	\$60.00	<i>✓</i>
13	Rear windscreen sealant	2	\$25.00	\$50.00	<i>✓</i>
	Sub Total			\$4,118.60	
	<i>50%</i> Less 20%			\$823.72	
	Sub Total 1			\$3,294.88	
	Total Spare Parts			\$3,294.88	
B.	Labour				
1	To knock and straighten the necessary portion. Cut and weld damaged panel. Adjust and realign the same			\$1,000.00	<i>400</i>
2	To putty and spray tailgate complete, end panel and rear bumper			\$800.00	<i>400</i>
3	To transfer tailgate fitting, attachments and perform water seepage test			\$180.00	<i>60</i>
4	To remove and install rear windscreen glass			\$120.00	<i>✓</i>
5	To rust proof the affected areas			\$80.00	<i>30</i>
6	To check all wiring and all lighting			\$60.00	<i>20</i>
7	To install rear parking sensor and rear camera			\$120.00	<i>50</i>
	Total Labour			\$2,360.00	
					<i>1080</i>
	Total Repair Cost			\$5,654.88	
	* The above quoted are exclusive of GST.				

*Not Adjust
 New
 The photo after
 4 days
 12/10/18*