

# LKK Auto Consultants h

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Co. Reg: 200922097K GST Reg.No: 200922097K

Auto Bay @ Kaki Bukit Bldg 1 Area "A" Kaki Bukit Ave 6 #06-04 (S) 417883

• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Acknowledged by Repairer

Signature:

Date:

Date: 11/10/2018

Total Pages: 1

TO: AXA INSURANCE SINGAPORE PTE LTD  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

Our Customer: KOK SIEW CHERN

Vehicle No: SKZ758E

Model: HONDA VEZEL

Manufacture Year: 2015

Date of Accident: 3/10/2018

Total Estimate Repair Days: 6

Attn: Motor Claim Department  
Email: motor.survey@axa.com.sg

P/P \$ 3014.56

Not Affected  
Klan  
The photo after  
4 days  
12/10/18  
P-1918-20  
202  
P-1534.56  
S.N + 400  
1000 + 1080

Re: Repair Estimate For Third Party Claim against SGA655Y

| No.                                      | Item Descriptions                                                                                      | Qty | Unit Price | Amount     | Remarks From Surveyor |
|------------------------------------------|--------------------------------------------------------------------------------------------------------|-----|------------|------------|-----------------------|
| <b>A. Spare Parts</b>                    |                                                                                                        |     |            |            |                       |
| 1                                        | Tailgate 953                                                                                           | 1   | \$1,320.70 | \$1,320.70 | 400                   |
| 2                                        | Tailgate 'VEZEL' emblem                                                                                | 1   | \$58.20    | \$58.20    | 100                   |
| 3                                        | Tailgate logo                                                                                          | 1   | \$58.70    | \$58.70    | 17 X                  |
| 4                                        | Rear bumper 762                                                                                        | 1   | \$985.50   | \$985.50   | 100/100               |
| 5                                        | Rear bumper clips                                                                                      | 10  | \$3.50     | \$35.00    | 100                   |
| 6                                        | Rear bumper retainer                                                                                   | 2   | \$58.20    | \$116.40   | 17 X                  |
| 7                                        | Rear bumper chrome plate                                                                               | 1   | \$280.50   | \$280.50   | 100 200 S.N           |
| 8                                        | Rear parking sensor                                                                                    | 1   | \$280.00   | \$280.00   | 100 200 S.N           |
| 9                                        | Rear end panel                                                                                         | 1   | \$680.20   | \$680.20   | 100 X                 |
| 10                                       | Rear end panel sealant                                                                                 | 1   | \$25.00    | \$25.00    | 100 X                 |
| 11                                       | Rear windscreen weatherstrip monthly                                                                   | 4   | \$42.10    | \$168.40   | 100 X                 |
| 12                                       | Rear windscreen inner seal                                                                             | 1   | \$60.00    | \$60.00    | 100 X                 |
| 13                                       | Rear windscreen sealant                                                                                | 2   | \$25.00    | \$50.00    | 100                   |
|                                          | <b>Sub Total</b>                                                                                       |     |            | \$4,118.60 |                       |
|                                          | <b>Less 20%</b>                                                                                        |     |            | \$823.72   |                       |
|                                          | <b>Sub-Total 1</b>                                                                                     |     |            | \$3,294.88 |                       |
|                                          | <b>Total Spare Parts</b>                                                                               |     |            | \$3,294.88 |                       |
| <b>B. Labour</b>                         |                                                                                                        |     |            |            |                       |
| 1                                        | To knock and straighten the necessary portion. Cut and weld damaged panel. Adjust and realign the same |     |            | \$1,000.00 | 400                   |
| 2                                        | To putty and spray tailgate complete, end panel and rear bumper                                        |     |            | \$800.00   | 400                   |
| 3                                        | To transfer tailgate fitting, attachments and perform water seepage test                               |     |            | \$180.00   | 60                    |
| 4                                        | To remove and install rear windscreen glass                                                            |     |            | \$120.00   | 100                   |
| 5                                        | To rust proof the affected areas                                                                       |     |            | \$80.00    | 30                    |
| 6                                        | To check all wiring and all lighting                                                                   |     |            | \$60.00    | 20                    |
| 7                                        | To install rear parking sensor and rear camera                                                         |     |            | \$120.00   | 100                   |
|                                          | <b>Total Labour</b>                                                                                    |     |            | \$2,360.00 |                       |
|                                          | <b>Total Repair Cost</b>                                                                               |     |            | \$5,654.88 | 1080                  |
| * The above quoted are exclusive of GST. |                                                                                                        |     |            |            |                       |